LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Mackinac Corner Code ## Located in: 41173 43N H 7N 1. Public Land Survey 43N H 7N 2. Property Controlling in Section 3. Miscellaneous Register of Deeds Stamp & File Number Property in Sec. 4. Lot No. . 5. Private Claims j Stephan J. Szyszkoski , in a field survey on ... September 17 1992 , 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

Court of Law, established, re-established, monumented, re-monumented, recovered, found as

(LIS) Quarter corner common to Sections 36 743N-R7M, and 1 742N-R7M. Corner previously recorded by Frank J. Bray as monumented by a 1' pipe with a 4° aluminum cap in 1966, with the following accessories: 8° Y. Pine (1/4S)(MBT) 547E 64 links, 11° J. Pine (1/4S)(MBT) \$69M 26 links.

(813) Section corner common to Sections 35-36 T43M-R7W, and 1-2 T42M-R7W. Corner previously recorded by Billy D. Buckler as monumented in 1962 by a 1/2"x36" iron bar with the following MBTs: 14" Soft Maple (\$35 MBT) M28M 53 links, 4" M. Pine (MBT) \$52M 25 links, 5" R. Pine (St MBT) \$41E 70.5 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(LL3) Found a 1° from pipe with 4° aluminum cap at record bearing and distance from the MBFs noted above. Removed the monument and placed, at it's position, a 1° pipe with a plastic cap stamped 'Mich DNR LS 33986' set below the surface to preclude disturbance by proposed road improvements. Marked 2 additional bearing trees as described below.

(KI3) Found and accepted a 1/2" iron bar at record bearing and distance from the R. Pine M8T and the stump of the M. Pine M8T noted above. The Maple MBT was not recovered. Marked 3 new bearing trees as noted below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(L13) Set a 1"x32" iron pipe with a plastic RLS cap. Blazed, scribed, and set measuring nails with tags in the following MBTs: 12" J. Pine SB6N 52.0" 14" R. Pine East 58.15" Set measuring mails in the record MBTs: 10" R. Pine \$47E 42.7" 14" J. Pine 5690 17.1"

expressed below:

on this certificate.

(K13) 1/2" iron bar buried in the center of an E-N road. Blazed, scribed, and set measuring nails in the following new bearing trees: 5" Maple \$368 21.25' 10° Balsam M48E 22.05' 10" W. Pine S32W 33.3" Set a measuring mail and tag in the

existing record MST: 8" R. Pine S4LE



Date /-27-95

46.7'.

Surveyor's Michigan License No. _