LAND CORNER RECORDATION CERTIFICATE Filling Requirement of Act 74, Mich. P.A. 1970

#166 For corners in 10038 Mackinac Located In: Corner Code ## 10036 1. Public Land Survey T 43N R 7N F12 40037 _ R S 33 T 43N R 7W 2. Property Controlling WC 8-4 S _33_ T _43N_ R _7N__ in Section WC F12-5 Miscellaneous Register of Deeds Stamp & File Number Property in Sec. 4. Lot No. Recorded Plat 5. Private Claims I. <u>Stephan J. Szyszkoski</u> __ , in a field survey on _ March 02, 1992 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

(F12) Cormer previously recorded by Billy D. Buckler in 1963 as being established and monumented at the intersection of 1/4 lines. (NC 8-4) Southwest corner of the North 8 Chains of the Southeast quarter of the Northwest guarter of Section 33. Corner not established in original survey. Found no record of prior monumentation.

(WC F11-F12) Southeast corner of the North 8 chains of the Southeast quarter of the Northwest quarter of Section 33. Not established in original survey. Found no record of prior monumentation.

8. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(Ff2) Found and accepted 1" pipe with 4" tablet set by Buckler with both of his 1963 BT's agreeing.

(MC 8-4) Established corner on west N-S 1/16 line 528.02' south (8 chaims perpendicular to the morth E-N 1/16 line) of the unmonumented NW 1/16 corner of Section 33.

(MC F11-F12) Established corner on N-S 1/4 line of section 33 528.02' (being 8 chains as measured perpendicular to north E-N 1/16 line) southerly of north I/Iô corner. Found no monumentation at this position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
(FI2) Found I* gipe with 4* cast (NC 8-4) Set a 1*x32* painted iron pipe (NC FI1-FI2) Set 1*x32* painted iron aluminum tablet. \$75E 8.9' set mail and tag in 20" W. Pine (obt); \$30E 4.25" mail and tag in 5" spruce; \$30M 2t.17" set mail and tag in 18' W. Pine inbtl; M30W 17.7' neil and tag in 9" maple. scribed obt's at BH. Blazed and scribed others at BH and bass.

on this certificate.

with 4" cast aluminum HDWR tablet. N36E 9.9' nail and tag in 11" maple: \$885 32.1' mail and tag in 10° maple; \$350 7.8' nail and tag in 9' maple: N55W 13.7' mail and tag in 7" maple. Blazed and scribed all trees at BH ("PC") and base ("BT").

pipe with 4° cast aluminum MDNR tablet. M16E 12.2' mail and tag in 13" W. Pine; S60E 22.7' mail and tag in 12" W. Pine; \$48W 5.7' nail and tag in 6" W. Pine: N44W 34.25' mail and tag in 11" W. Pine. All trees blazed and scribed at BH ("PC") and base ("BT"). 6 F M/C

Surveyor's Michigan License No.

SZYSZKOSKI LAND SURVEYOR

STEEHAN J.