Cons. 4047 REV. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

**OW** 

	T. 43 R.K.		Mackinac	COUNTY
ESCRIPTION OF CORNER	Section Corner common	to Sections 13-14	-23-24	
ORNER MONUMENT	l <sup>n</sup> pipe with 4 <sup>n</sup> alumin	num cap.		
ATE MONUMENT PLACED AND WITH		N60°W 19.9'		
	10" Cedar (S23 NBT)			
	10" Tamarack (S24 N	BT) \$80°E 5.31		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from one Cedar bearing tree, N70°E, 19 links. Tree down with both faces rotting. No evidence of the hemlock witness.

Corner lies in a thick cedar swamp.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler, R.L.S. DATE 9/25/68

RÉGISTERED LAND SURVEYOR