LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970 3 Corners. Mackinac Co.

	FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	,	
	I. PUBLIC LAND SURVEY	T. 43 %; R. 8 %	G-10, F-11, F-11A		
	2. PROPERTY CONTROLL- ING IN SECTION—	,T N E. S., R W.		·	
		,T			
	4. LOT NO, RECORDED PLAT				
	5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND	
	Billy D. Buckler do hereby certify that under requirements of P.A. 74. Michigan P.A. of 1970,				
	the corner points mentioned in lines 1 and 2 above were, in a field survey on 6-5, 5-20 , 19 80, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on, 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:				
G-10	A. Description of original monument and accessories and/or subsequent restoration: Quarter Cor. bet. Sec's. 27-28, set by H. Brevoort Jr. D.S. in 1845. Bearings were: Tamarack 3", N33°W, 26 lks. & Tamarack 4", S47°E, 06 lks.				
P-11	Quarter Cor. bet. Sec's. 28-33, set by H. Brevoort Jr. D.S. in 1845. Bearings were: Tamarack 16", S28°E, 33 lks. & Cedar 10", N78°E, 19 lks.				
P-11A	Meander Corner bet. Sec's. 28-33, on Lake Michigan, 15.00 chains, record distance, West of quarter corner. Bearings were: Pine 6, N86°E, 2.55 chs. & Pine 4, N5°W, 1.68 chs.				
G-10	B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Placed corner on old line of N-S blazes, 12.55! North of a blazed stut. This places the corner 7.85! East of a strait line bet. two corners and midway. Found several lines of blazes, one of which bears West from this corner. Swamp edges check well.				
F-11	Replaced corner from one probable B.T.; a Tam. 16", 528°E, 33 lks. Found no identifying				
P-11A	Restored corner by extending line thru the quarter corner, from Sec. Cor. 27-28-33-34. Corner lies 30' North of centerline, U.S.#2.				
Placed	C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: The pipe with 4 aluminum cap at all three corners.				
G-10	New Bearings: 18" W. Pine, S82°E, 60.5' & 18" W. Pine, S11°W, 77.6'. Corner lies in wet spruce, tamarack swamp aprox. 100' from the east edge and 200' South of the Natural gas				
P-11 P-11A	pipe line clearing. New Bearings: 10" Cedar, N36 E, 26.4' & 9" Cedar, S54 E, 15.2' & 12" Cedar, S58 W, 23.9'. New Bearings: 6" S. Maple, N15 W, 9.6' & 8" S. Maple, N82 E, 9.8' & 8" W. Pine, S54 E, 31. HWY DEPT R.O.W. MARKER, N56 W, 65.7'.				
	SIGNED BY Sill	1. Q. Suckles) DATE9-29-8	BUCKLER E	
	SURVEYOR'S MICHIGAN R	ckler		GURVEYOR S	
	FOR STATE AND UNITED			0867 AND 9	
			DATE		
·	APPROVED AND SIGNED I	CHIEF OF SURVEY PARTY BY	LAND SURVEYOR	(SEAL)	
	SURVEYOR'S MICHIGAN REGISTRATION NO				
	FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28. 1971 REVISED MAY 14. 1975				
1		MAY PLACE SKETCH ON BACK OR ATTACHED SHEET			