MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 11812 W

				Macl	rinsc	
DESCRIPTION OF CORNER	Section	Cerner c	emmen to	Sections	30-31-25-36.	
CORNER HONUMENT	l" pipe with	4º Almi	num Cap.			<u> </u>
DATE MONUMENT PLACED	AND WITHESSED	10-22	69			
WITHESSES TO CORNER	<u>18# C</u>	der (Wit) s81°W	26 .9 t		
30 - 43-11	8*_R):	(NBT) H	25 % 30.	91		
CIRCLE CORNER REGISTES	AND					

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at an eldlow iron pipe, which is situated in Antersection of roads to Worth and Easte Found this pipe in place.

SURVEYOR'S SEAL

Silly & Buckles

I GIVED _____

12-30-69

REGISTERED LAND SURVEYOR