## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

_	riling Requirem	ent of Act 74, Mich. P.A. 1	970 as Amende	d	
For corners in					
Mackinac	Located In:	Corner Code #	•		
(County)		5511.6. 5556 //			
1. Public Land Survey	T 43N R 12N T 43N R 12H T R	D1			
	S				
2. Property Controlling	S T R	<del></del>			
in Section  3. Miscellaneous	S T R				<b>.</b>
Property in Sec.	S T R S T R			Register of Deed Number	s Stamp & File
4. Lot No , Rec	corded Plat		1 A B (	D E F G	HIJKL
5. Private Claims		5 2003	2	<del>├</del> ─┊ <del>┈</del> ┤	╌┋╾╂╼┇╼┼╼╏╌
	D1 Oct 0	8 2003	3	<del>┣</del>	<del>                                     </del>
Stephan J. Szyszkoski	in a field surrouse	20 4	4   7	<del>├─</del> ┆ <del>─</del> ┼─	10-11-12-
that under requirements of P.A	, in a neto survey on _ A. 74. Michigan P.A. of 1970, the	, 20 do hereb	y state 5	┝╌┞╌┼╌┼╌	<del>                                     </del>
above were in conformance w	ith regulations and rules therefo	ore as required in the current ma	nual of 6 -18	17	15-14-13-
survey instructions of the Unite	ed States Department of the Inter	rior, Bureau of Land Management tioned in lines 3, 4 and 5 above v	orbya 7		
conformance with the rules of	the Michigan Board of Land Sun	tioned in tines 3, 4 and 5 above v veyors or by a Decree of a Court o	vere in	_2021	23 23 24
established, re-established, mo	onumented, recovered, found as	expressed below:	9		
NOTE: Not were at a 2			10 30	29 28	272525
NOTE: Not more than 2 on this certificate		n and range, may be recorde	11 11		
on this certificate	<b>∤•</b>		12-31	32 33	34 35 36
A. Description of original r	monument and accessories ar	nd/or subsequent restoration:			
D1) The original post and ac round. Reestablished the co D3) The original post, acces 973 survey has been destroye ean true bearing between Sec	ccessories were not recovered orner midway and on a line of ssories, 1973 monument and a ed by logging operations. I ction corners 2633.42' East	od applied in restoring or reest d. Found no acceptable evide f mean true bearing between S ccessories were not recovered reestablished the corner acc and West (sketches provided t be). Found a wood post for a	nce of the positi Section corners of d. It appears tha cording to the 197 by Wilcox Assoc.,	record 2639.73 t the physical ( 3 method, midway Inc. show a 1973	'East and West.  By and on a line of a measure of
DNR cap. Blazed, scribed, a easuring nails in:	and set MDNR cap.  measuring 1/4S MBT" 6" Balsam do 8" Balsam do 10" Cedar do 5" twin C	established to perpetuate loc i IDx36" I.pipe with 4" alum. 8lazed, scribed, and set nails in: N32W 10.7" "1/4S NBT" N35E 19.65" do in clump S23E 78.8' do edar S57W 64.65' do are magnetic. Distances are tag.	to	OF MICH	
Signed by Stephen	I Smarkel.		Date	2/17/04	,
Surveyor's Michigan License	No. — 3398	36		•	-