LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

#88

For corners in Hackinac	Located In:	Corner Code #	1/-	1	lu	13,	6-	7					
(County)			- 1/-		, ,								
1. Public Land Survey	TR TR TR												
Property Controlling in Section Miscellaneous Property in Sec.	S36 T_44NR_81 S6 T_44NR_81 S T R S T R	11 12		Reg	iste	r of D	eedi	s Str	a mp	& F	ie N	umb	eer_
4. Lot No, Reco	rded Plat		1	А В	c T	D _	<u>E 1</u>	F G	i H	-	J T	<u>к</u>	<u>.</u> .
			2	- 6	\dashv	- \$-	-	·	<u>.</u> غ	+	- 2-	+	· i
	•	un 26 1996	3	\vdash	┰		 -			╌	+	+	十
requirements of P.A. 74, Michig conformence with regulations and United States Department of the that the corner points mentioned	en P.A. of 1970, the comer poi d rules therefore as required in t interior, Bureau of Land Mener d in lines 3, 4 and 5 above were y a Decree of a Court of Lan	, 19 do hereby state that unde into mentioned in lines 1 and 2 above were in the current manual of survey instructions of the jernent or by a decree of a Court of Law and & in conformance with the rules of the Michigal w; established, re-established, monumented	n 5 f 6	— [†]		-17	-1	6— 1—	—10 —15 —15 —22	 	-14-	 	13-
NOTE: Not more than 2 cor on this certificate.	ners, all in the same town an	d range, may be recorded	9 10 11 12	H		_29_ 	2	8-		+	-26- -35-		25-
			12	تـــا	┙	Ĩ	oxdot			\perp	Ĺ	•	•
(11-Sec. 36) Southwest 1/16	s corner, Sec. 36. Corner	nd/or subsequent restoration; not established in the original surv not established in the original surve											

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(11-Sec. 36) Found no monumentation at the corner position. Established the corner at the intersection of straight lines connecting opposite 1/16 corners. The controlling 1/16 corners Mest and South of here were not monumented. For the purposes of establishing this corner, their positions were determined by computation, being midway and on a straight line between adjacent section or 1/4 corners, as appropriate. At the position for the corner, I placed a 1" x 36" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped. Distances north and east to monumented 1/16 corners were found to be 1328.34' and 1329.35', respectively. (12-Sec. 36) Found no monumentation at the corner position. Established the corner midway and on a straight line between Center of Section 1323.12' north (recorded in 1991 by T.L. Fabis) and 1/4 corner 1323.12' south (recorded in 1991 by T.L. Fabis). At the position for the corner I buried a 1" x36" iron pipe capped with a yellow plastic cap stamped MICH DNR LS 33986. The monument falls 4' west of the centerline of a N-S trail.

C. Description of monument for corner and act (11) Set 1 pipe with 4" MDNR cap.	cessories established to perpetuate locating the (12) Buried a 1" pipe with plastic cap.	position of the corner:
Blazed, scribed, and set measuring nails	Blazed, scribed, and set measuring nails	OF MIC
in the following:	in the following:	
5" Beach S87N 43.2' "SN1/16 BY"	30" Maple S55W 63.15' "51/16 BT"	* STEPHAN J.
5" Reech H87W 34.1' "SW1/16 BT"	24" Maple S41M B1.4" "S1/16 BT"	* SZYSZKOSKI
4" Maple S86E 31.0' "SW1/16 8T"	Other accessories:	* LAND
3" Maple S54E 67.65' "SW1/16 BT"	Power Pole "£6" M26E 69.0"	SURVEYOR
Centerline railroad North approx. 69'.	Fd. 5/B° iron \$26W 5.15'	
Placed a 5" squared and scribed post	Bearings are magnetic.	33986
adjacent to the monument. Bearings are	Centerline of railroad approx 132.5'	CAND SOLVE
magnetic.	North.	The same of the sa
Signed by Stephen J. I mig	Sisti Date	12/10/96
Surveyor's Michigan License No.	33986	•

For the Michigan Department of Natural Resources - Forest Management Division