(2

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Mackinac	Located in:	Corner Code #									
1. Public Land Survey	TR TR TR TR										
Property Controlling In Section Miscellaneous Property in Sec.	S 6 T 44N R 8 S 6 T R R S T R	6 5		Regis	ster o	l Dee	ds St	emp &	File	Numi	ber
4. Lot No, Recon	ded Plat		1	λ B	c p	E	<u>, </u>	H	- 1	<u>к</u>	<u>L</u>
		ug 30 1995 ug 29 1995	3	- 6-	士	· _	1	3 	†²	士	-1-
Stephan J. Szyszkoski requirements of P.A. 74, Michiga	in a field survey on	, 19 do hereby state the	it under 4 were in _	 _		<u>-</u>	<u>} </u>	—1 <mark>0</mark> —	<u></u> }		-12- -
United States Department of the I	nterior, Bureau of Land Man in lines 3, 4 and 5 above wi	in the current manual of survey instruction regement or by a decree of a Court of Law ere in conformance with the rules of the M Law; established, re-established, monur	encilor 6 Echigen _	18	+1	-	16-	—1 ['] 5—	+-1	+	-13-
recovered, found as expressed be	low:		8	19- 	十 ² i	┱	-21	<u>—2</u> 2— 	+-2: 	`-	-24-
NOTE: Not more than 2 com on this certificate.	ers, all in the same town :	and range, may be recorded	10	l Î	-2	,	-28 	—27— 	20	6	_25_
			11	31-	_3	2	33_	_34_	3:	-	-36-

A Description of original monument and accessories and/or subsequent restoration:

(6-Sec. 6) Northeast 1/16 corner, Section 6. Corner not established in the original survey. Found no subsequent record.

(5-Sec. 6) North 1/16 corner Section 6. Corner not established in the original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(6-Sec. 6) Found no evidence of prior monumentation at the corner position. Established the corner at the intersection of straight lines connecting opposite 1/16 corners. The 1/16 corner to the north is not monumented. At the position for the corner I placed a 1"IDx36" iron pipe capped with a 4" dia. cast aluminum MDMR tablet, appropriately stamped. From the corner monumented, I found an axle shaft placed by unknown persons 42" north and 61" mast.

(5-Sec. 6) Found no evidence of prior monumentation at the corner position. Established the corner 20 chains, proportionate to the original record, north of the Center of Section 6 and on a straight line between the center and the North 1/4 corner of Section 6, both found monumented. The Center is 1326.60' south and the 1/4 corner 1296.59' north. At the position for the corner I placed a 1"IDx36" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped. From the corner monumented, I found a 1" iron pipe placed by unknown persons, projecting about 2 ft., 61.6' north and 13.3' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. (6) Set 1 pipe with 4 MDMR cap. (5) Set 1 pipe with 4 MDMR cap.									
(6) Set I pipe with 4 MDNR cap.	(5) Set 1" pipe with 4" MDWR cap.								
Blazed, scribed, and set measuring nails	Blazed, scribed, and set measuring na	ils of Michigan							
in the following trees:	in the following trees:								
5" M. Brich S10E 44.2" "HE1/16 BT"	10" R. Pine MOZE 11.4" "M1/16 BT"	# ★ STEPHAN J.							
14" R. Pine W34W 65.9"	14" R. Pine M32E 42.65' "	A * SZYSZKOSKI **							
12" R. Pine M30M B5.3"	12" R. Pine H27W 7.15' "	3 LAND ≯							
Found Axle shaft N60E 74.02'	12" R. Pine S78W 27.6'	SURVEYOR							
Placed a 4° Cedar post, squared and	Fnd 1" pipe N09W 63.01"	No. 33986							
scribed, adjacent. Bearings are	Edge of plantation 54' West. Bearing								
magnetic.	are magnetic.	CAND SU							
The state of a	lali n	1/-29-95							
Signed by Naghtan J. Xayan									
Surveyor's Michigan License No	<u> 33986</u>								

For the Michigan Department of Natural Resources - Forest Management Division