Mackinache O

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

3 Corners

CORNER CODE NUMBER

Mackinac Co.

FOR CORNERS OF -:

LOCATED IN -:

1. PUBLIC LAND SURVEY T S., R W 13-Sec.1	
2. PROPERTY CONTROLL. 1	
3. MISCELLANEOUS PROPERTY IN SECTION, T S., R	
4. LOT NO, RECORDED PLAT	
5. PRIVATE CLAIMS	REGISTER OF DEEDS STAMP AND FILING NUMBER
I,	, 1979, established in conformance with regulations states Department of the Interior repoints mentioned in lines 3, 4 tored, established or re-established
14-Sec.1 South 1/16 Corner on East side of Section 1.	•
16-Sec.l East 1/16 Corner on South side of Section 1.	
B. Description of corner evidence found and/or method applied in restoring or re-establishin	ng corner:
13-Sec.1 Placed Corner at center of SE + Section.	
14-Sec.1 Placed Corner midway bet. Sec. Cor. to South and # Cor	r. to North.
16-Sec.1 Placed corner midway bet. Sec. Cor. to East, and ‡ Con	r. to West.
C. Description of monument for corner and accessories established to perpetuate locating the	position of the corner:
Placed 1" Pipe with 4" Aluminium cap at all corners.	
13-Sec.l Bearings 8" Maple, S50°E, 3.7' and 10" Y. Birch, 10" Twin Maples, S79°W, 22.1' 14-Sec.l Bearings: 7" Aspen, S60°W, 27.2' and Twin 14" Chern	\$31°W, 25.5' and
Corner lies on East side of N-S road.	
16-Sec.l Bearings: 24" R. Maple, N74°W, 29.5' and 8" H. Maple	The second second
SIGNED BY BILLY D. Buckler Surveyor's MICHIGAN REGISTRATION NO. 8887	BILLY DE BUCKLER LAND SURVEYOR
FOR STATE AND UNITED STATES AGENCIES:	9887
SIGNED BYDATEDATE	
APPROVED AND SIGNED BY DATE DATE	(SEAL)
	·

SURVEYOR'S MICHIGAN REGISTRATION NO.