## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co.

1 Corner

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	•
I. PUBLIC LAND SURVEY	T. 44 S., R. 11 W	<u>D-5</u>	
2. PROPERTY CONTROLL- ING IN SECTION-	,T		
3. MISCELLANEOUS PROPERTY IN SECTION —	,T		
4. LOT NO, RE	CORDED PLAT		
5, PRIVATE CLAIMS			REGISTER OF DEEDS :

- A. Description of original monument and accessories and/or subsequent restoration:
- -5 North 1/4 cor of sec. 17. Wood Fost, Cedar 8", S40°E, 50 lks. & Tam. 5", N60°W, 87 lks.

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner;
- Found SE O.E.T, (Cedar 8", S40°E, 50 lks.) now 10" and down but still living with many branches now growing as trees. Both upper and lower faces plain with some axe marks but scriting weathered off. A tam. stp. with signs of scarring and overgrowth is at the proper bearing (N60°W) but the distance is somewhat short. It would be close if the numbers were inverted: I.E. 78 lks. instead of 87 lks. as recorded.
  - C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- -5 D.N.R. Mcnument. New Bearings:

6" Cedar, N54°W, 56.2' 4" Cedar, South, 15.55' 5" Cedar, S40°E, 14.5' 4" Tam., N71 E, 33.4'

SIGNED BY Lavid B. Ballitt DATE 8-3-82

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)