LAND CORNER RECORDATION CERTIFICATE Pitter Descriptions and Add 74 Little D & 4070

For corners in	r mag	requirement of sect 14, ha							
Mackinac	Located in:	Corner Code #							
(County)									
1. Public Land Survey	TR TR TR								
Property Controlling In Section Miscellaneous Property in Sec.	S_2 T_44H R_1 S_2 T_44H R_1 S_ T_R S_ T_R	<u> </u>		Registe	r of Dec	eds Stan	np & Fi	ile Nui	mber
4. Lot No, Reco 5. Private Claims	rded Plat		=	A B C	D E	F G	H I	₽ <mark>J K</mark>	L
•	f	Oct 12 1998		3		\bot		\dashv	
requirements of P.A. 74, Michig conformance with regulations an United States Department of the that the corner points mentions	, in a field survey on an P.A. of 1970, the corner p d rules therefore as required in interior, Burseu of Land Man d in lines 3, 4 and 5 above we y a Decree of a Court of L		above were in suctions of the of Law and for the Michigan monumented,	4 - 7 - 5 - 18 - 7 - 8 - 19 - 19 - 19 - 19 - 19 - 19 - 19	-17	-16	-10	-11	—12— —13— —24—
NOTE: Not more than 2 cor on this certificate.	ners, all in the same town a	ind range, may be recorded		9	_29 	-28 -33	27	-26 -35	-25 36-
				13'					

Description of original monument and accessories and/or subsequent restoration:

(1-Sec. 2) West 1/16 corner between Sec. 2 T44M-R11W and Sec. 35 T45M-R11W. Corner not established in the original survey. Corner established in 1967 by Billy D. Buckler RLS: * This corner established midway and on line bet. 1/4 cor. to east and Sec. Cor. to west. Corner monument 1" pipe with 4" aluminum cap. 6" H. Maple M20M 17.0', 9" H. Maple S25M 13.6'"

(3-Sec. 2) North 1/16 corner between Sections 2-3 T44N-R11W. Corner not established in the original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(1-Sec. 2) Recovered the 1967 monument as described, a 1" ID from pipe capped with a 4" dia. cast aluminum MDNR tablet, in good condition, and at record bearing and distance from the 1967 witness trees, both in good condition. My measurements show the monument to be 2.04' Mest and 3.96' South of the record position. I accept the monument as a careful and faithful determination of the position of the corner. I made new markings on the 1967 witness trees and marked two new accessories as described below. Corner recovered and rewitnessed by T.Stark and M.Feldpausch, Newberry District Office.

(3-Sec. 2) Found no evidence of prior monumentation at the corner position. Established the corner on a line of mean true bearing between Quarter corner 1313.26' south and Section corner 1210.83' north, being 20 chains proportionate to the original record north of the quarter corner. At the position for the corner, I placed a 1° 10 x 36° iron pipe capped with a 4° dia. cast aluminum MDMR tablet, appropriately stamped. Corner placed and witnessed by T.Stark and M.Feldpausch, Newberry District Office.

(1) Fnd 1" pipe with 4" MDHR cap. Blazed, scribed, and set measuring nails in the following: 12" Maple S25M 13.0' "M1/16" (1967 wit) 10" Maple M17M 17.4' "M1/16" (1967 wit) B" Maple S67E 29.95' "M1/16 BT" 12" Maple M64M 25.1' "M1/16 BT"	cessories established to perpetuate locating the (3) Set 1" pipe with 4" MDNR cap. Blazed, scribed, and set measuring nails in the following: B" Cedar S07E 16.85" N1/16 87" 10" Spruce S44W 7.1" N1/16 BT" B" Cedar W78W 52.05" N1/16 BT" 12" Spruce M50E 25.3" N1/16 BT"	STEPHAN J. SZYSZKOSKI LAND STIRVEYOR
N-S rd. is 16' West. Placed a 4' squared and scribed post adjacent. Bearings are magnetic.	Placed a squared cedar post adjacent. Bearings are magnetic.	33986 12/26/28

Surveyor's Michigan License No.

For the Michigan Department of Watural Resources - Forest Management Division