## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Mackinac	Located In:	Corner Code #								
(County)										
1. Public Land Survey	T44H R	11W								
	TR_									
	ŢŖ_									
2. Property Controlling	TR_ S TR									
in Section	S TR_		ļ							
3. Miscellaneous	S TR_									
Property in Sec.	S TR_			Re	gister :	of Dee	ds St	amp &	File Nu	ımber
			_							
4. Lot No, Recor	ded Plat									
5. Private Claims				ı <b>^</b> _	B C	D E	F G	H	<del>Ĭ ∳</del> -	KLM
		<b>\</b>		2 ├─	<u> </u>	\$ <del></del>		_ ş_	<u> </u>	<del> -</del> !-
•	1	Oct 12 1998		_ <b>3</b>	—⊢	+	4-1		₩-	+
I, Steohan J. Szyszkoski			by state that under	- 4⊢	<del>}_</del>	b	- 9	10	<u> </u>	<u> </u>
requirements of P.A. 74, Michiga	in P.A. of 1970, the corner	points mentioned in lines 1 an		5 ├	<u> </u>	<del> </del>	-		++	$\perp \perp \perp$
conformance with regulations and United States Department of the I				6 L	! !	1-	-16	 -—15	114	13
that the corner points mentioned				7			4	<del>-</del>	$\perp \perp$	$\perp \perp \perp$
Board of Land Surveyors or by recovered, found as expressed be		Law, detablished, re-detablish	eu, monumentes,	e  ;	 	20	-21_	! 22	23-	1-24
			•	9 _	1					<u> </u>
NOTE: Not more than 2 corr on this certificate.	hers, all in the same hown	and range, may be recorded		10—			_		1_1_	25_
OI 9 IIS COMMUNIC.					Ľ	Ĭ	<u>֚֚֚֚֚֡֞</u>			
				11				34	15-	1 1
				12	ïΤ	ïΤ	ĭΠ	]	آ آ	
A. Description of original mo	nument and ecoessorie	e andler aubecouest rester	etion:	13-		• • • • • • • • • • • • • • • • • • • •				
conclude that it is not docume to corners. It is likely the established K1 by proportion B. Description of corner evidance, in good condition, aromer blazes overgrown. I not "H. Maple (now 12") was four f II and 10.3" north of a streinstalled it in the position aithful reestablishment of the be 2666.12" and from K1 to be 2666.12" and from K1 to be bearing trees as described.	hat II was used on the hate methods using JI dence found and/or method at as described, a 1 had at record bearing fite that the 1967 record at 21.2', and the II raight line between II hat which I found it, he position of the orig Buckler's monument at	west but highly unlikely for control. Buckler's lithod applied in restoring or I.D. iron pipe capped wiron the two 1967 witness: d is in error in that the O'H. Maple (now 18') was and M1. During the courbeing the 1967 position ginal corner. I found the M1 to be 5323.22'. I mage	that K1 was use attitudinal contributional contributions of the a 4" dia. case apples, both recodistances to the found at 17.6", se of my survey, herein recorded, a distance from the markings	ed on the rol for I mer.  st alumin covered in MBTs a The mc I remon. I accept J1 to Bu on the 1	e east: Il was ; In was ; In good appear conument yed the apt the uckler' 1967 wi	R table condito have monuments monuments	kler s ly I1  et, as tion n e been ecover ent as ment s trees	ppropri with up n trans red 263 nd lates s a car to the and ma	ently  iately pper and sposed. 31.06' er reful a east a arked t	đ The east nđ t K1
C. Description of monument II) Set 1° 10 x36° iron pipe luminum MDHR cap. Blazed, set measuring nails in: 8° Haple S37E J7.65° 1/45° (2° Haple N76E 21.3° 1/45° (1° Haple N40M 5.3° 1/45 MI Naple S04M 8.55° 1/45 MI laced a 4° squared and scribust adjacent. Bearings are mistances are horizontal.	with 4" cribed, and (1967 wit) SI (1967 wit) SI	TEPHAN J. TYSZKOSKI LAND URVEYOR No. 33986	- .÷							
· · · — — — — — — — — — — — — — — — — —	No 339	86	. Data		-1-1	<u></u>				
Surreyor & Michigan Licelise										
" Maple M40N 5.3" "1/4S M " Maple S04N 8.55" "1/4S M laced a 4" squared and scrib ost adjacent. Bearings are m	ed cedar sagnetic.  No. 339	URVEYOR No. 33986 4 N D & W  66 arthent of Natural Resour	Date ces - Forest Mar	nagement		on	ESSION	AL SURV	TEYORS, J	AN. 28, 19