## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

For corners in		time tradation of stat 14, Mach, P.A. 1870							
Mackinac (County)	Located in:	Corner Code #							
1. Public Land Survey	ŤR_ ŤR_								
Property Controlling in Section     Miscellaneous Property in Sec.	TR_ S2 T_400R_ S2 T_400R_ S TR_ S TR_	110 8 11 11 11 11 11 11 11 11 11 11 11 11 1		Register	of Dee	ds Stan	no & F	-De Nin	mhei
4. Lot No, Reco 5. Private Claims	rded Plat			A B C	D E	F G	ні	JK	L
. Stanhan I Saverbooki		Oct 01 1998	3	111	-5	<b> -</b>  -	. } - +	• <u>2</u>	_ [
		, 19 do hereby state the points mentioned in lines 1 and 2 above in the comment mentioned and a state of the comment		<u> -</u>	-	9	10-	-11-	—1 <sup>1</sup> 2
conformence with regulations and rules therefore as required in the current menual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in time 3, 4 and 5 above were in conformence with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,				18	-17	16-	15-	-14	-13
ecovered, round as expressed below:		9		20	21	22	_23	—24- I	
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.			9 10	1 1 1	29	28	<del> -</del>	-26	
			11 12		32	33	34	-35	-36-
Nonadation of adultura			13	<u></u>	4	<u> </u>	ᄔ	┷┷	丄

A. Description of original monument and accessories and/or subsequent restoration:

(8-Sec. 2) Nest 1/16 corner, Section 2. Corner not established in the original survey. Found no subsequent record.

(11-Sec. 2) Southwest 1/16 corner of Section 2. Corner not established in the original survey. Found no subsequent record.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

(8-Sec. 2) Found no evidence of prior monumentation at the corner position. Established the corner midway and on a straight line between Quarter corner 1321.12' Mest and Center of Section 1321.12' East. At the position for the corner, I placed a 1° ID x 36° iron pipe capped with a 4° dia. cast aluminum NONR tablet, appropriately stamped and buried it below the surface in the SN side of an intersection of trails north, south, and east. Corner placed and witnessed by T.Stark and M.Feldpausch, Newberry District Office. (11-Sec. 2) Found no evidence of prior monumentation at the corner position. Established the corner at the intersection of straight lines connecting opposite 1/16 corners 1324.23' Mest, 1323.85' East, 1312.87' North, and 1313.32' South. At the position for the corner I placed a 1° ID x 36° iron pipe capped with a 4° dia. cast aluminum MDNR tablet, appropriately stamped. Corner placed and witnessed by T.Stark and M.Feldpausch, Newberry District Office.

C. Description of monument for comer and a (8) Set 1" pipe with 4" MONR cap.  Blazed, scribed, and set measuring nails in the following:  14" Maple M81E-28.1" "M1/16 BT"  12" Maple S15E 23.05" "M1/16 BT"  24" Twin Maple S40N 16.0" "M1/16 BT"  10" Maple N28E 23.2" "M1/16 BT"  Placed location poster on cedar post approx 9" Mest. Bearings are magnetic.	Coessories established to perpetuate locating the (11) Set 1" pipe with 4" MONR cap. Blazed, scribed, and set measuring nails in the following: B" Maple MOSE 8.75" "SNI/16 8T" 8" Maple NS2E 8.2" "SNI/16 8T" 6" Maple SS4E 5.15" "SNI/16 BT" 4" Maple N18W 10.45" "SNI/16 BT" Placed a 3" squared and scribed cedar post adjacent.	STEPHAN J. SZYSZKOSKI LAND SURVEYOR No. 33986
Signed by Stephen Say	3 holi: Date_	12/28/98

For the Michigan Department of Natural Resources - Forest Management Division