LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Mackinac (County)	Located in:	Corner Code #									
1. Public Land Survey	T <u>44H_R_11</u> TR TR TR										
Property Controlling N Section Miscellaneous Property in Sec.	S TR S TR S TR S TR		R	egist	er of l	Deed	s Str	ımp 8	l File	Nun	nber
4. Lot No, Reco	orded Plat		1 Å	B (D D	E	F G	H - 3-	•	J K	<u>-</u>
Aug 06 1998 I. <u>Stephan J. Szyszkoski</u> , in a field survey on, 19			3 — 4 — 5 —	18-	- 8-		9	10 15	 	1	-12- -13-
			8 -	- 19 	20-	+	21	22 -		23	24-
NOTE: Not more than 2 co on this certificate.	omers, all in the same flown a	ind range, may be recorded	10-	30	-29		28-	27-		26-	-25-

A. Description of original monument and accessories and/or subsequent restoration:

(11) Corner common to Sections 2-3 T44N-R11N and 34-35 T45N-R11N. Corner established in 1841 by John Burt: "Set post corner of sections 34&35. W. Pine 22 N79E 19, Cedar 12 M50N 5." Additional bearing trees by Mm. Ives in 1849: Cedar 7 S35N 23, Cedar 11 S45E 24. Corner perpetuated in the original position in 1967 by Billy D. Buckler, RLS: "This corner replaced at an old cedar post with all four original witnesses in evidence; a M. Pine bearing N79E 19 lks, tree broken off about 3' high; three cedar stumps, cut 16" high bearing N50N 5 lks, S35N 23 lks, and S45E 24 lks. Found original faces with scribe marks on all stumps. Corner lies in a thick cedar swamp. Corner monument 1" pipe with 4" aluminum cap. Witnesses to corner 6" cedar (S35 NBT) N59E 4.2', 5" Cedar (S2 MBT) S75N 120'." Record dated 3-27-69.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(II) Recovered the 1967 monument as described, a 1° ID iron pipe capped with a 4° aluminum Michigan Dept. of Natural Resources tablet, in good condition, and at record bearing and distance from the remains of the original bearing trees as noted in the 1969 certificate. The remains have deteriorated and the scribing is no longer visible. Recovered the 1967 Cedar 6° in good condition. This tree was removed to facilitate GPS observations and is now a cut stump. The Cedar 5°, noted in the record as being 120' distant, was recovered at 12.0' from the monument. The discrepancy is presumed to be a typographical error. This tree has fallen down. I accepted the monument as a careful and faithful perpetuation of the original corner and left it in place. I marked four new accessories as described below. Corner recovered and remitnessed by T.Stark and M.Feldpausch, Newberry District Office.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

(It) Found 1° iron pipe with aluminum MDNR cap. Blazed, scribed, and set measuring nails in the following:
5° Cedar N25E 13.7° "S35 NBT"
6° Cedar N04M 8.4° "S34 NBT"
6° Cedar S37E 16.9° "S2 NBT"
6° Cedar S55M 19.3° "S3 NBT"
Placed 4° squared and scribed cedar post adjacent. Bearings are magnetic.

Surveyor's Michigan License No

Date 11-18-98

For the Michigan Department of Natural Resources - Forest Management Division

SZYSZKOSKI

LAND

SURVEYOR