LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For comers in

Mackinac (County)	Located In:	Corner Code #								
1. Public Land Survey	T44#_R_11 T44#_R_11 TR_	<u> </u>								
Property Controlling in Section Miscellaneous Property in Sec.	TR_ S TR_ S TR_ S TR_ S TR_		Re	gister	of De	eeds Si	temp 8	. File	Numt	ber
4. Lot No, Reco	orded Plat		1 A 1	- c	D	E F (5 H	<u>1</u>	_ K	<u>L</u>
requirements of P.A. 74, Michiconformence with regulations at United States Department of the that the corner points mentions Board of Land Surveyors or I	_ , in a field survey on gan P.A. of 1970, the comer p nd rules therefore as required in a interior, Burseu of Land Mant ad in lines 3, 4 and 5 above we by a Decree of a Court of L	ig 19 1998 , 19 do hereby state that under points mentioned in lines 1 and 2 above were in the current manual of survey instructions of the agement or by a decree of a Court of Law and for in conformance with the rules of the Michigaruw, established, re-established, monumented	3	8	-17	9	10-	-	+	-12-
NOTE: Not more than 2 co on this certificate.		and range, may be recorded	8 —1 9 — 10 —3	9	-29	21 	27	21	5	-24- -25-

A. Description of original monument and accessories and/or subsequent restoration:

(X4) Quarter corner common to Sections 11-12. Corner reestablished in 1980 by Billy D. Buckler, RLS: "Restored corner midway and on line bet. two Sec. Cors. We evidence of original corner. Placed 1° pipe with 4° aluminum cap. He new witnesses available. Corner lies in an open clear cut area."

(K3) Corner common to Sections 1-2-11-12. Corner reestablished in 1969 by Billy D. Buckler, RLS: 'This corner placed in intersection of an old road east and west; an old RR grade north and south. This position is nearly equi-distant between Sec. Cors., one mile to east and to west. Corner monument 1 1/4 x 30 iron pipe, buried in road intersection. 12 Hard Maple(S11 M8T) S44M 22.7', 8 Hard Maple(\$12 NBT) \$598 25.7'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

(K4) Recovered the 1980 monument as described, a 1° ID iron pipe capped with a 4° dia, cast aluminum MONR tablet, 0.28' South and 0.52' West of the record position. I accepted the monument as a careful and faithful reestablishment of the position of the original corner. Left the monument in place and marked four bearing trees as described below. Corner recovered and remitnessed by T.Stark and M.Feldpausch, Newberry District Office.

(X3) Recovered the 1969 monument as described, in good condition, and at record bearing and distance from the two 1969 witness trees.

Left the monument in place and made two new accessories as described below. Corner recovered and rewitnessed by T.Stark and M.Feldpausch, Newberry District Office.

e position of the corner.

 C. Description of monun 	nent for corner and a	accessories established to perpetuate locating the						
(X4) Found 1" iron pipe wi	th 4" MONR	(K3) Found 1 1/4" iron pipe. Blazed,						
cap. Blazed, scribed, and	iset measuring	scribed, and set measuring mails in the						
nails in the following:		following:						
10" Maple \$20E 17.1"	"1/4S NBT"	16" Haple \$45N 23.0' "\$11" (1969 wit)						
8" Maple S80W 30.2'	"1/45 N8T"	12" Haple \$53E 26.0" "\$12" (1969 wit)						
6" Twin Cherry N43E 16.4"	"1/45 NBT"	14" Maple N38E 43.4' "S1 NBT"						
8" Maple S75E 23.4'	"1/45 NBT"	12" Maple 570E 37.4" "S12 MBT"						
Bearings are magnetic. Pl	aced a 4"	Bearings are magnetic.						
squared and scribed cedar								
1.		1						

STEPHAN J. SZYSZKOSKI LAND

For the Michigan Department of Natural Resources - Forest Management Division