SURVEY & REMONUMENTATION

0126148

APR 2 8 1995

Private Claims _

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

94 SEP 30 AM 9: 00 A 4/23 a 1 i i i

Fo 	r corners COMMISSION Macomb	Washingto Located In: Township		REGISTER OF AUGH MACOMA COLATY, MT
1.	Public Land Survey	T 4 N R 12 E	G-10	
		T R T R T R		11BER 06464PG461
2.	reparty during	S T R S T R		
3.	Miscellaneous S Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4.	Lot No, Reco	orded Plat		ARCDEEGHL!KI

June 15 Huston K. Kennedy, in a field survey on _ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Lawland/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 6 10 12
- A. Description of original monument and accessories and/or subsequent restoration:
- 1817-GLO Wampler, D.S.; Set Post 10" Lynn S46*E 17 Links; 20" White Oak N16*E 36 Links
- 1.) 1973-Avey, P.S. #15396; LCRC L.2426, Pg.327 Fnd 1/2" Bar in hand hole 2.) 1974-Avey, P.S. #15396; LCRC L.2522, Pg.273 Same wit as 1973 LCRC
- 3.) 1987-Kennedy, P.S. #17623; LCRC L.4134, Pg.721 Fnd 1/2" Iron Rod in Monument Box
- 4.) 1988-Avey, P.S. #30076; LCRC L.4353, Pg.430 Fnd 1/2" Iron Rod in Monument Box
- 5.) 1973-Avey, P.S. #15396; Survey L.2467, Pg.821 Same wit as 1973 LCRC
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 1994 Kennedy Surveying, Inc. Kennedy, P.S. #17623 Fnd 1/2" Iron Rod in a Monument Box 1.7' East of the centerline of Camp Ground Road, which has a bituminous surface, and Glacier Club Golf Course to the West.

Witnesses from LCRC 1, 3 & 4 were used to recover and verify the location of the found 1/2" Iron Rod in a Monument Box.

FIELD MEASUREMENT BETWEEN

G-10 to G-9 2685.02 Feet G-10 to G-11 2676.51 Feet

Surveyor's Michigan License No.

ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD 94 9

WILLIAM E. SODERBERG, P.S., CHAIRMAN

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- G-10 I replaced the found 1/2" Iron Rod in a Monument Box with 3/4" x 24" Iron Rod w/2" diameter aluminum cap stamped "Macomb County Monument MI Act 345 #17623" in a existing Monument Box.

S80'E 21.64' Set PK & Remon. Washer NE face Guide Pole

S25'W 53.91' Set PK & Remon. Washer NW face Power Pole

N85'W 80.95' Set PK & Remon. Washer South face 34" Maple

N80'E 60.22' Set PK & Remon. Washer SW corner of house #60000

OF MC Syldence of the The selected location is accepted by and is generally accepted by Professional Surveyorys position of the original corner. KENNED)

Signed by *0*7623

Date

AND SURVEYORS, JAN. 28, 1971 MICHIENS SHIPPERSON

ROFESSIONAL SURVEYOR

REVISED MAY 14, 1975 REVISED JAN., 1983