## SURVEY &

			RECORDATIO			-
For corners	in	riing Require	ment of Act 74,	Wilch. P.A. 197	APR 0 7 1998	
Macomb (County)		Located In: Ray Twp.	Corner Code	#	SECTION	
1. Public L	and Survey	T <u>-4-N</u> R <u>-13-E</u> T R T R T R	K-13			
in Secti 3. Miscella		T C062382			400 08:57A 12/22/1997 UNTY, MI REG/DEEDS Register of Deeds Stamp & File Numb	er
4. Lot No.	, Recorder	d Plat		<del></del>		ь м
5. Private	Claims				2 6 5 4 3 2	
J. Trivate	Ciairis				3	
	•				4 7 8 9 10 11 1	2
i loho N	Padach in a field	overse October 16 1	10 07 de besetes e		5	
i, <u>John N. Redash</u> , in a field survey on <u>October 16</u> , 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above						3—
were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a					7	
decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in					8 19 20 21 22 23 2	4
		chigan Board of Land Surve mented, recovered, found as	•	of a Court of	و	
			•		10 30 29 28 27 26 2	5
		n the same town and range,	may be recorded		11	$\square$
on	this certificate.				12 31 32 33 34 35 3	6—
					13	
A. Descrip	tion of original monum	ent and accessories and/o	r subsequent rest	oration:		
1817	set post	G.L.O. Notes	W. Preston	N/AN/A		-
1973	N/A	Survey	H. Kobs	#14097	L2466, P719	
1975 1989	Not found 1/2" Iron bar	Survey Survey	G. Avendt H. Kobs	#16034 #14097	L2585, P701 L4729, P172	
1994	PK and Tag #16052	•	R. Smith	#16052	L6300, P929	
1994	PK and Tag #16052	L.C.R.C.	R. Stecker	#30103	L6245, P35	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:						
and verify it		h current measurements f			following witness ties were used to recover and survey (L6300, P929). Field observa	
J-13 to K-1	3 K-13 to L-	13 K-1 to K-13	3			
2676.68 m				- m = .		
2640.00 Rec. G.L.O. 2692.92 rec. survey 15.85 Rec. survey, L2585, P701 L6300 P929 15.83 Rec. L.C.R.C. L6245, P35						
		Rec. G.L.O.	E.O.H.O. E0240,	100		
					the position of the corner:	
I replaced "Macomb	the found P.K. nail a County Monument M	nd tag in asphalt paver II Act 345 #37281" w	ment with a 3/4 ith a new monu	" X 24" iron ro ment box. Wit	od with a 2" aluminum east samped tnesses are as follows: OF M/C,	
Due We	est 16.01' Macor	nb County Remon. Cap	o in monument l	oox (K-1, T-3-N	4., 11-10-L., 22 42 6 4 4 4 4	4
N. 03°	W., 52.01' Between	en P.K. Nail and Maco			e U-pole * REDASH *	<b>1</b>
		cross W. end concrete			PROFESSIONAL SURVEYOR C	<b>3</b>
		cross N. rim storm ma P.K. nail W. face 42"			PROFESSIONAL SURVEYOR NO. 37281	#
J. 14	17., 42.00 FUUIIU	1 AN HOW YY, IdUE 42	Oak stump		SURVEYOR ROOM No. 37281	F
	d location is accepted being the design of the original corrections.	by me and generally acceptor.	oted by Profession	nal Surveyors as	70 A) 70 A	

DateDecember 16, 1997 FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14,1975
REVISED MAY 14,1976
REVISED JAN., 1983
REVISED JAN., 1983
REVISED OCT., 1996
WILLIAM E. SODERBERG, P.S., CHAIRMAN

Surveyor's Michigan License No. 37281