LAND CORNER RECORDATION CERTIFICATE

7-7-7-7-7-7-XXX

Surveyor's Michigan License No. P S # 16923

	Filing F	Requirement of Act 74, Mich. P.A. 1	1970
= or corners in MANISTEE (County)	_ Located In:	Corner Code #	REGISTER'S OFFICE MANISTEE COUNTY #98-334 AT 10:30 An.
2. Property Controlling in Section S. Miscellaneous S.	TR		AUG 1 7 1998 Penny A. Resus REGISTER OF DEEDS Register of Deeds Stamp & File Number
Property in Sec. S	TR		refigier of needs of such or Life inflithet
■4. Lot No, Reco ■5. Private Claims	orded Plat	<u>.</u>	1 A B C D E F G H I J K L M
nereby certify that under require lines 1 and 2 above were in courrent manual of survey instruction above were in conformance with Court of Law; established, expressed below:	in a field in the sale corners, all in the sale	d survey on <u>April 23rd</u> 19 98, do a P.A. of 1970, the corner points mentioned in ns and rules therefore as required in the Department of the Interior, Bureau of Land he corner points mentioned in lines 3, 4 and 5 Board of Land Surveyors or by a Decree of a ed, re-monumented, recovered, found as me town and range, may be	4 7 8 9 10 11 12 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
A. Description of original r	nonument and accessor	ies and/or subsequent restoration:	13
M - 4 Corner common to section 12 T21N, R14W 1837 GLO survey by John Brink P. Pine 10" for corner No witnesses given No date book "A" page 20, Mon. not given # 1 W. Pine stp 22" N61W 25 lks (16.5')		1963 survey by R.A. Griffin survey tech. Found 1" pipe with lime # 2 Cedar post East 33' # 3 W. Oak 6" S35E 129.3' dock spike in SE side # 4 W. Oak 8" S40W 117.00' dock spike in SE side # 5 SE cor. con. found. addition on S side cabin N64W 121.80'	
1909 survey by Fargo Eng. Co. 1992 survey by Rowe Eng. for 1" Gas pipe with lime, no witnesses given Witnesses same as R.A. Grif			
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M - 4 Corner common to section 12 T21N, R14W & section 7 T21N, R13W On April 23rd 1998 I found the 5" square con. mon. set by R.A. Griffin, the condition of the witnesses are as follows,			
Gone # 1, # 4 Found # 2, # 3, # 5 (Did			,
_			
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: M - 4 Corner common to section 12 T21N, R14W & section 7 T21N, R13W On April 23rd 1998, I accepted the found 5" square con. mon. as a careful and faithful reestablishment of the position of the original corner, and took the following witnesses.			
# 6 J. Pine 6" East 50.85 # 7 B. Oak 8" 8468 66.35' # 8 W. Oak 6" 884W 40.38' # 3 W. Oak 10" 836E 129.3 # 2 Cedar Post East 32.90	found 60d spike in found 8d spike set 2' found dock spike	S.W. side 60d spike in N. side in S.W. side	
Corner is in a monument b re-bar. (Tippy Dam Road) Corner (- according to t as amended, (ox in the centerline ### ratified by the county plan adopted	of a North-South blacktop road in by the Manistee County Peer Group bursuant to P.A. 345 of 1990, and Remonument Act. M21, 54 261	fill and has been raised with a 1/2". OF MICHIGAN SAMMY S. BARNETT
Signed by Sammy A	Barnets	Date_8/3/98	PROFESSIONAL SURVEYOR ON No.