DEC 2 9 1996

COMMISSION

PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1976 REVISED JAN., 1983 REVISED OCT 1995

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1	1970	
For corners in		REGISTER'S OFFICE
Manistee Located In:	Corner Code #	MANISTEE COUNTY
(County)		OCT 17 1997
1. Public Land Survey T 21N R 17W	M-07	
TR	Southeast Sec.	Xt Boriah QU
TR	Cor. Sec. 13	REGISTER OF DEEDS
TR	- A - A	
2. Property Controlling S TOIN RIGW in Section S T R	A 07	
3. Miscellaneous S T R		Boulator of Dondo Stown & Ello
Property in Sec. S T R		Register of Deeds Stamp & File Number
	<u></u>	
4. Lot No, Recorded Plat		ABCDEFGHI _{JK} LM
5. Private Claims		1
o. Trivato dialina		2 - 6 5 - 4 - 3 - 2 - 1
**************************************		3
		4 - 7 - 8 - 9 - 1 - 12 - 12 -
A Anthony NA Chardinald in a field assurance to the OO	40.07.4.1	5
I, Anthony M. Slawinski, in a field survey on July 28, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2		6 19 17 -16 15 14 13-
above were in conformance with regulations and rules therefore as re-	quired in the current manual of	7
survey instructions of the United States Department of the Interior, E		8 29 20 21 22 23 24
by a decree of a Court of Law and /or that the corner points mentic were in conformance with the rules of the Michigan Board of Land		9
Court of Law; established, re-established, monumented, recovered, fo		1 4 3 0 - 2 9 - 2 B - 2 7 - 2 6 - 2 5
NOTE: Not more than 2 corners, all in the same town and ra		
NOTE: Not more than 2 corners, all in the same town and ra on this certificate.	inge, may be recorded	12-31-32-33-34-35-36-
31, 1113 331 3113		13
A. Description of original monument and accessories and/or s	subsequent restoration:	
M-7 Southeast Section Corner of Section 13, T21N., R17W.		
Set by John Brink in 1837		
1. B. Oak 12" S 34° W 28 links (Gone)		
2. W. Pine 11" N 41° W 37 links (Gone)		· · ·
	•	
B. Description of corner evidence found and/or method appli	ied in restoring or reestablishir	ng corner:
M-7 Southeast Section Corner of Section 13, T21N., R17W.	·	₽ ~ F
Found Iron by Cole (1972)	Also referenced:	Group 1530, 4.261
3. S 45° W 37.72′ Power Pole (Gone)	Also referenced: GLO Original Field note:	s by Brink (1837). Book 1. Page 415 5
4. S 45° E 31.18' Telephone Pole (Gone)		MCI.
	Mears engineering - Sur	rvey (1990), Liber 2, Page 188 - 출하 🚡
Vailliencourt LCRC No. 72-2 (1972)	Observation of the second state of the second	Ö ₹ ₹
5. S 50° E 43.86′ Top of Fire Hydrant (Gone) 6. S 40° W 37.80′ Power Pole (Gone)	Siawinski- i raverse sne	eet, field notes & survey (1982) -2) 1972 -2) 1972
5. 5 % W 57.55 F 5 % C 10 % G	Vailliencourt LCRC (72-	-2) 1972
Found Iron by Slawinski	,	-2) 1972 Early mant to the man
7. S 65° W 37,72′ 6″ Ash (Gone)	Zwar- Survey (1996)	ع و ۵ او
On July 28, 1997 I (Anthony Slawinski) & Abonmarche		
found a 1" Iron Pipe.		1890), Vol. 2 of Plats, Page 114 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
	Cole - Survey Traverse	Sheat & Survey, (1972)
C. Description of monument for corner and accessories estab	lished to perpetuate locating t	the position of the corner:
M-7 Southeast Section Corner of Section 13, T21N., R17W.	g	20 A
On this 20 4007 I have the disk of the C		~ F 8 # 8
On July 28, 1997 I installed a Manistee County Monument, we mentioned 1" iron pipe as a careful and faithful re-establishment.		
mentioned is not hibe as a cateful after (diffin) te-establishing	are or the position of the origin	nai corner and witnessed by:
8. N 39° E 94.10' Southwest Corner of Building		Z1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
9. N 72° W 91.45' Power Pole (Spike in the Northeast side)		Comer // according as amende
10. S 52° W 48.15′ Power Pole (Spike in the Northwest sid	<i>71 U</i>	Comer according ame
11. S 69° E 58.60' Power Pole (Spike in the Southwest side Corner was set in the intersection of the center lines of 28th S	1	THONY C
Comer was set in the intersection of the center lines of 28" 8	ineer and iverson quact.	u _]
Signed by Anthony m. Stamohi	SLA	WINSKI 20-2-97
Surveyor's Michigan License No. 13597	「 I SUR	RVEYOR O