

WAY 1 6 1997

Surveyor's Michigan License No. 16423

COMMERCIAN!

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

The second of the second states of the second of the secon	=or co	rners in	Filing Re	equirement of Act 74, Mich. P.	REGISTER'S OFFICE
1. Public Land Survey 1. T 2 N R 16 N H-4 1. T 2 D R 16 N H-4 1. T 2	MANIS	IEE (County)	_ Located In:	Corner Code ##	MANISTEE COUNTY
Property Controlling S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register Register of Deeds Stamp & File Number Property in Sec. S T R R Register Register of Deeds Stamp & File Number Register	1. Pu	-			#96-311 AT 10:40 A-m.
in Section S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Recorded Pist A Description of Section 12, 122N, R16N, On the Township Line On Nay 21, 1976. Hencine points mentioned in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management of the decree of a land mentioned in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management of the decree of a land survey in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management of the decree of a land Surveyors of by Decree of a Court of Lave, added the concer points mentioned in the act of above were in conformance with the rules of the Michigan Board of Land Surveyors of by Decree of a Court of Lave, added the concer points mentioned in the act of the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management of bund as activesed before. NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this cartificate. A Description of original monument and accessories and/or subsequent restoration: M-4 East 1/4 Corner for Section 12, 122N, R16N, 0n the Township Line By Healbock 15° N55°N 211ke. (13.86¹) 35 Ecorner Fonce Fost Weet 35.13¹ #4 Cherry 12° M12°N 163.05¹ #5 Henlack 15° N55°N 211ke. (27.01¹) 44 Cherry 12° M12°N 163.05¹ #5 Henlack 15° N55°N 211ke. (12.12N, R16N, 0n the Township Line On 14y 21, 1996, I found a 12° spike over 3/4° Land Pipe, over a 1/2° Re-rod, at the Center-Line of Milarch Road and old fence line to the West, I Found no evidence to dispute this location for the 1/4 corner. Corner 1			TR_ TR_		
5. Private Claims Samy S. Barnett	in 3. Mi	Section scellaneous	S T R S T R		Register of Deeds Stamp & File Number
5. Private Claims Samy S. Barnett	A 10	it No	ecorded Plat		
A Description of original monument and accessories and/or subsequent restoration. **Not peak with instruction of the Michigan Pa, 1976, the convertion of t					
do hareby certify that under requirements of P.A. 74. Michigan P.A. of 1870, the corner points menioned in lines 1 and 2 above were in conformance with the United States Department of the Interior, Bureau of Land Management or by a decree of a Count of Law and of that the corner points menioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors on by a Decree of a show were in conformance with the rules of the Michigan Board of Land Surveyors on by a Decree of a show were in conformance with the rules of the Michigan Board of Land Surveyors on by a Decree of a show were in conformance with the rules of the Michigan Board of Land Surveyors on by a Decree of a show were in conformance with the rules of the Michigan Board of Land Surveyors on by a Decree of a show were in conformance with the rules of the Michigan Board of Land Surveyors on by a Decree of a show were in conformance with the rules of the Michigan Board of Land Surveyors on by a Decree of a show were in conformance with the rules of the Michigan Board of Land Surveyors on by a Decree of a show were in conformance with the michigan Board of Land Surveyors on by a Decree of the Surveyors of the Surveyo	•	· .			3 5 5 7 3 7 2 7 1
do hareby certify that under requirements of P.A. 74. Michigan P.A. of 1870, the corner points menioned in lines 1 and 2 above were in conformance with the United States Department of the Interior, Bureau of Land Management or by a decree of a Count of Law and of that the corner points menioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors on by a Decree of a show were in conformance with the rules of the Michigan Board of Land Surveyors on by a Decree of a show were in conformance with the rules of the Michigan Board of Land Surveyors on by a Decree of a show were in conformance with the rules of the Michigan Board of Land Surveyors on by a Decree of a show were in conformance with the rules of the Michigan Board of Land Surveyors on by a Decree of a show were in conformance with the rules of the Michigan Board of Land Surveyors on by a Decree of a show were in conformance with the rules of the Michigan Board of Land Surveyors on by a Decree of a show were in conformance with the rules of the Michigan Board of Land Surveyors on by a Decree of a show were in conformance with the michigan Board of Land Surveyors on by a Decree of the Surveyors of the Surveyo	_			V 04 07	3-1-10-11-1-12
on this cartificate. A. Description of original monument and accessories and/or subsequent restoration: M-4	do here in lines curren Manag above Court expres	eby certify that under request 1 and 2 above were in the manual of survey instruction of by a decree of a were in conformance with of Law; established, rested below:	uirements of P.A. 74, Michig conformance with regulatications of the United States Court of Law and/or that the the rules of the Michigan Elestablished, monumented	an P.A. of 1970, the corner points mentions and rules therefore as required in Department of the Interior, Bureau of a corner points mentioned in lines 3, 4 a loard of Land Surveyors or by a Decreid, re-monumented, recovered, foun	oned n the Land 7
A. Description of original monument and accessories and/or subsequent restoration: M-4	NOTE		rners, all in the same to	wn and range, may be recorded	
M-4 East 1/4 Carner for Section 12, 122N, R16M, On the Township Line 1837, John Brink, D.S., G.L.O. Set Nood post #1 Heelock 9" S10"W 211ks.(13.86') #2 Hemlock 16" N359W 451ks.(29.70') #4 Cherry 12" N12°W 163.95' #4 Found 3/4" Iron Pipe, from Field notes B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-4 East 1/4 Corner for Section 12, 122N, R16M, On the Township Line On May 21, 1996, I found a 12" spike over 3/4" Iron Pipe, over a 1/2" Re-rod, at the Center-line of Milarch Road and old fence line to the West, I found no evidence to dispute this location for the 1/4 corner. Condition of recorded witnesses are; #1 Lione #2 Gone #3 Found replacement post #4 Found in good condition Comer		· '			
1837, John Brink, D.S., G.L.D. Set Wood post #! Hemlock 9" \$10°W 21lks.(13.86') #2 Hemlock 16" N35°W 45lks.(29.70') #3 Corner Fence Post West 35.13' #4 Cherry 12" N12°W 163.95' 1897, J.H. Willard, MCS Stone & Large Cedar Post, found B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-4 East 1/4 Corner for Section 12, 122N, R16W, On the Township Line On May 21, 1996, I found a 12" spike over 3/4" Iron Pipe, over a 1/2" Re-rod, at the Center-line of Milarch Road and old fence line to the West, I found no evidence to dispute this location for the 1/4 corner. Condition of recorded witnesses are; #1 Cone #2 Gone #3 Found replacement post #4 Found in good condition Comer M -		•		·	
Found 1/2" Iron Pipe #1 Hemlock 9" \$10°W 21lks.(13.86°) #2 Hemlock 16" N35°W 45lks.(29.70°) #3 Corner fence Post West 35.13′ #4 Cherry 12" N12°W 163.95′ #3 Corner fence Post West 35.13′ #4 Cherry 12" N12°W 163.95′ #3 Corner fence Post West 35.13′ #4 Cherry 12" N12°W 163.95′ #3 Corner fence Post West 35.13′ #4 Cherry 12" N12°W 163.95′ #3 Corner fence Post West 35.13′ #4 Cherry 12" N12°W 163.95′ #4 Found 3/4" Iron Pipe, from field notes #5 Found 3/4" Iron Pipe, from field notes #6 Found 3/4" Iron Pipe, over a 1/2" Re-rod, at the Center-line of Milarch Road and old fence line to the West, I found no evidence to dispute this location for the 1/4 corner. #6 Corner for Section 12, I22N, R16W, On the Township Line #7 Corner for Section 12, I22N, R16W, On the Jownship Line #8 Found in good condition #8 Found in good conditio		East 1/4 Corner to	r Section 12, 122N, R	16w, un the lownship line	
1977. J.H. Millerd, MCS Stone & Large Cedar Poet, found 1985. Manistee Road Comm. Found 3/4" Iron Pipe, from Field notes 8. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-4 East 1/4 Corner for Section 12, 122N, R16M, On the Township Line On May 21, 1996, I found a 12" spike over 3/4" Iron Pipe, over a 1/2" Re-rod, at the Center-line of Milarch Road and old fence line to the West, I found no evidence to dispute this location for the 1/4 corner. Condition of recorded witnesses are; #1 Gone #2 Gone #3 Found replacement post #4 Found in good condition COMER		Set Wood post #1 Hemlock 9" S	10°W 211ks.(13.86')	Found 1/2" Iron Pipe #3 Corner Fence Pos	st West 35.13'
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-4 East 1/4 Corner for Section 12, T22N, R16M, On the Township Line On May 21, 1996, I found a 12" spike over 3/4" Iron Pipe, over a 1/2" Re-rod, at the Center-line of Milarch Road and old fence line to the West, I found no evidence to dispute this location for the 1/4 corner. Condition of recorded witnesses are; #1 Gone #2 Gone #3 Found replacement post #4 Found in good condition Comer — — — — — ratified by the Maristee County Peer Group as amended, (being the State Survey and Remonument Act, MCL 54.261 at .seq.). Date of Reser Review: — IIII — 2 1996 Comer — — — — — — — — — — — — — — — — — — —			•	·	
On May 21, 1996, I found a 12" spike over 3/4" Iron Pipe, over a 1/2" Re-rod, at the Center-line of Milarch Road and old fence line to the West, I found no evidence to dispute this location for the 1/4 corner. Condition of recorded witnesses are; #1 Gone #2 Gone #3 Found replacement post #4 Found in good condition C. Description of monument for comer and accessories established to perpetuate locating the position of the corner. C. Description of monument for comer and accessories established to perpetuate locating the position of the corner. M-4 East 1/4 Corner for Section 12, I22N, R16W, On the Township Line I replaced 3/4" Iron Pipe and 1/2" Re-rod, in the exact location, with a Standard Manistee County Monument, 0.5 feet below the road surface inside a new road monument box, and is accepted as a careful and faithful reestablishment of the position of the original corner. New Fence Corner Post West 42.40'(16p spike in south side of post) (OBT #4) Cherry 16" N 12° W 163.95'(60d spike in SW side of tree) SAMMY S. EARNETT PROFESSIONAL SURVEYOR PROFESSIONAL SURVEYOR		Stone & Large Ceda	r Post, found		
On May 21, 1996, I found a 12" spike over 3/4" Iron Pipe, over a 1/2" Re-rod, at the Center-line of Milarch Road and old fence line to the West, I found no evidence to dispute this location for the 1/4 corner. Condition of recorded witnesses are; #1 Gone #2 Gone #3 Found replacement post #4 Found in good condition C. Description of monument for comer and accessories established to perpetuate locating the position of the corner. C. Description of monument for comer and accessories established to perpetuate locating the position of the corner. M-4 East 1/4 Corner for Section 12, I22N, R16W, On the Township Line I replaced 3/4" Iron Pipe and 1/2" Re-rod, in the exact location, with a Standard Manistee County Monument, 0.5 feet below the road surface inside a new road monument box, and is accepted as a careful and faithful reestablishment of the position of the original corner. New Fence Corner Post West 42.40'(16p spike in south side of post) (OBT #4) Cherry 16" N 12° W 163.95'(60d spike in SW side of tree) SAMMY S. EARNETT PROFESSIONAL SURVEYOR PROFESSIONAL SURVEYOR	B. De	escription of corner ev	idence found and/or me	thod applied in restoring or reesta	ablishing corner:
Milarch Road and old fence line to the West, I found no evidence to dispute this location for the 1/4 corner. Condition of recorded witnesses are; #1 Gone #2 Gone #3 Found replacement post #4 Found in good condition C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. M-4 East 1/4 Corner for Section 12, T22N, R16W, On the Township Line I replaced 3/4" Iron Pipe and 1/2" Re-rod, in the exact location, with a Standard Manistee Gounty Monument, 0.5 feet below the road surface inside a new road monument box, and is accepted as a careful and faithful reestablishment of the position of the original corner. New Fence Corner Post West 42.40'(16p spike in south side of post) (08T #4) Cherry 16" N 12° W 163.95'(60d spike in SW side of tree) SAMMY S. CAPP (MBP) Power Pole S 26° E 57.74' (0.H. nail NE side of pole) Witness Iron 2" re-rod w/ RLS cap N 52° E 25.93'(8 feet East of road edge) The Representation of the corner. SURREYOR Corner M - 4 ratified by the Menistee County Peer Group according to the county plan adopted pursuant to P.A. 345 of 1990, as amended, (being the State Survey and Remonument Act, MCL 54.261 Latting M: Page Review: 111					
#1 Gone #2 Gone #3 Found replacement post #4 Found in good condition Comer M - D + ratified by the Menistee County Peer Group according to the county plan adopted pursuant to P.A. 345 of 1990, as amended, (being the State Survey and Remonument Act, MCL 54.261 cl. seq.). Date of Poor Review:					
as amended, (being the State Survey and Remonument Act, MCL 54.261 #4 Found in good condition as amended, (being the State Survey and Remonument Act, MCL 54.261 #4 Found in good condition C. Description of monument for comer and accessories established to perpetuate locating the position of the corner: M-4 East 1/4 Corner for Section 12, T22N, R16W, On the Township Line I replaced 3/4" Iron Pipe and 1/2" Re-rod, in the exact location, with a Standard Manistee County Monument, 0.5 feet below the road surface inside a new road monument box, and is accepted as a careful and faithful reestablishment of the position of the original corner. New Fence Corner Post West 42.40'(16p spike in south side of post) (08T #4) Cherry 16" N 12° W 163.95'(60d spike in SW side of tree) SAMMY S. SAMMY S. BARNETT PROFESSIONAL SURVEYOR PROFESSIONAL SURVEYOR			ded witnesses are;	Corner M - 04	fool by the same of
#3 Found replacement post #4 Found in good condition Et. sec.). Date of post Review:				according to the county plan ad	opted pursuant to P.A. 345 of 1990
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-4 East 1/4 Corner for Section 12, T22N, R16W, On the Township Line I replaced 3/4" Iron Pipe and 1/2" Re-rod, in the exact location, with a Standard Manistee County Monument, 0.5 feet below the road surface inside a new road monument box, and is accepted as a careful and faithful reestablishment of the position of the original corner. New Fence Corner Post West 42.40"(16p spike in south side of post) (0BT #4) Cherry 16" N 12° W 163.95"(60d spike in SW side of tree) SAMMY S. SAMMY S. BARNETT Witness Iron ½" re-rod w/ RLS cap N 52° E 25.93"(8 feet East of road edge) PROFESSIONAL SURVEYOR		•	•	et. seq.). Date of Poor Boulour	vey and Remonument Act, MCL 54.261
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-4 East 1/4 Corner for Section 12, T22N, R16W, On the Township Line I replaced 3/4" Iron Pipe and 1/2" Re-rod, in the exact location, with a Standard Manistee County Monument, 0.5 feet below the road surface inside a new road monument box, and is accepted as a careful and faithful reestablishment of the position of the original corner. New Fence Corner Post West 42.40"(16p spike in south side of post) (0BT #4) Cherry 16" N 12° W 163.95"(60d spike in SW side of tree) SAMMY S. SAMMY S. BARNETT Witness Iron ½" re-rod w/ RLS cap N 52° E 25.93"(8 feet East of road edge) PROFESSIONAL SURVEYOR		#4 round in good	condition	A. Salar Hench.	Arather in Starie
I replaced 3/4" Iron Pipe and 1/2" Re-rod, in the exact location, with a Standard Manistee County Monument, 0.5 feet below the road surface inside a new road monument box, and is accepted as a careful and faithful reestablishment of the position of the original corner. New Fence Corner Post West 42.40'(16p spike in south side of post) (OBT #4) Cherry 16" N 12° W 163.95'(60d spike in SW side of tree) SAMMY S. SAMMY S. SAMMY S. BARNETT Witness Iron ½" re-rod w/ RLS cap N 52° E 25.93'(8 feet East of road edge) PROFESSIONAL SURVEYOR	C D4	sociation of manumen	t for corpor and conseq.		
I replaced 3/4" Iron Pipe and 1/2" Re-rod, in the exact location, with a Standard Manistee County Monument, 0.5 feet below the road surface inside a new road monument box, and is accepted as a careful and faithful reestablishment of the position of the original corner. New Fence Corner Post West 42.40'(16p spike in south side of post) (OBT #4) Cherry 16" N 12° W 163.95'(60d spike in SW side of tree) **SAMMY S.** **SAMMY S.** **BARNETT** **Witness Iron 2" re-rod w/ RLS cap N 52° E 25.93'(8 feet East of road edge) **PROFESSIONAL SURVEYOR**	O. De			,	cating the position of the conter.
O.5 feet below the road surface inside a new road monument box, and is accepted as a careful and faithful reestablishment of the position of the original corner. New Fence Corner Post Weet 42.40'(16p spike in south side of post) (OBT #4) Cherry 16" N 12° W 163.95'(60d spike in SW side of tree) SAMMY S. SAMMY S. BARNETT Witness Iron ½" re-rod w/ RLS cap N 52° E 25.93'(8 feet East of road edge) SURVEYOR	M4	East 1/4 Corner fo	r Section 12, T22N, R	16W, On the Township Line	
(OBT #4) Cherry 16" N 12° W 163.95'(60d spike in SW side of tree) SAMMY S. SAMMY S. SAMMY S. BARNETT Witness Iron ½" re-rod w/ RLS cap N 52° E 25.93'(8 feet East of road edge) SURVEYOR	,	0.5 feet below the	road surface inside	a new road monument box, and i	s accepted as a careful and faithful
O SUNVEYOR OF	€ f3t	(OBT #4) Cherry 1 P(PP) Power Pole	6" N 12° W 163.95'(5 26° E 57.74' (D.H	60d spike in SW side of tree) . nail NE side of pole)	SAMMY S. BARNETT
					SURVETUR OF

EYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983