LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Manistee (County)		Located	d In	Corner Code #	
1. Public Land Survey		T 23N	R <u>14W</u> R	<u> 1-1</u>	
Property Controlling in Section	s	T	R		
Miscellaneous Property in Section	s	T			Register of Deeds Stamp & File Number
4. Lot No:	Recorded	d Plat:			— A B C D E F G H I J K L M
5. Private Claims: _					
I, <u>Craig W. McVean</u> , in a requirements of PA 74, Mi and 2 above were in conforthe current manual of su Interior, Bureau of Land Miccorner points mentioned in of the Michigan Board of established, re-established NOTE: Not more than be recorded on this ce	ichigan PA of ormance with rvey instructi anagement on in lines 3, 4 and f Land Survit, monumente 2 corners,	if 1970, the or regulations ions of the or by a decreed to 5 above we weyors or by ed, recovered	corner poin and rules t United Sta e of a Cour were in con y a Decre d, found as	ts mentioned in lines therefore as required in tes Department of the tof Law and/or that the formance with the rule e of a Court of Law expressed below:	1
A. Description of origina	al monumen	it and acces	ssories ar	id/or subsequent res	storation:
corner is correctly	set post — 1 884°W 9 L. (Co. Surveyo Government 10°W 7½ L. 175°W 10 L. Co. Land Color r and 2 NBT related to significant	I) Black Ash (5.84') or's Record t Bearing Tr . (4.95'); (6.60') mer Record T's – B. Ash otandard cor Corner to Se	10" S7°E (Book "A" ees – J. H d by Kenn governm mer and a ections 34	p. 194.) H. Millard – eth Ostling – Fd. ents BT's gone but appears acceptable & 35, T24N R14W	of Dept. of Conservation and witnessed in place per Manistee County Land Corner Records. 9) Cedar 6" N47°W 29.97'; 10) Cedar 12" N59°W 17.02'; 11) Black Ash 6" S48°E 10.13'; 4) Cedar Stump16" N74°W 6.3' Blaze on face - 2001 – LCRC - 01-138 – A. M. Slawinski – On June 13, 2001, a field crew under my direction found a DNR monument in good condition. The corner is 19.81' West of the SE Cor. of Sec. 34 (24-14). The corner is ±550' South of 13 Mile Road. The crew could find no other evidence to dispute this location for the corner. Condition of witnesses #1 – gone: #2 – gone, #3 – gone, #4 – fd. stump,

1960. Set 1" pipe with 4" brass cap. 5) Cedar 7" S88°W 39 L. (25.74'); 6) Cedar 8" S22°E 6 L. (3.96') - 1972 – DNR Survey Map by Carl F. Roser (#12028) – Exist DNR Monument from previous Dept. Survey Corner is 19.89' West from

SW Cor. Sec. 35 T24N R14W

- 1973 - LCRC form by Carl F. Roser (#12028) in 1973 - L. 73 p. 187, rewitnessed previous Dept. corner of record. Fd. DNR Monument. Added Cedar Guard Post. 5) Cedar 7" S88°W 25.7' Old KJO wit.; 6) Cedar 8" S22°E 3.9' Old KJO wit.; 7) Cedar 7" N33°W 36.2'; 8) Cedar 6" N77°W 68.2"

- 1974 – Survey Map by J. L. Wilcox & Associates, Inc. – NE Cor. Sec. 3, fd. DNR Monument Corner is 19.81' West of the SW Cor. of Sec. 35, T24N R14W

1988 - LCRC form by Robert F. Mitchell (#28417) in L. 88 of Surveys Fd. iron pipe and brass cap (in good condition)

#5 - good, #6 - good, #7 - good, #8 - gone, #9 - good, #10 - good, #11 - good.

The above mentioned DNR monument as the corner and as a careful and faithful perpetration of the position of the original corner, and witnessed by:

- 4) N75°W 6.60' 16" Cedar Stump; 5) S88°W 25.80' 7" Cedar (Fd. Blaze with scribing, but could not read);
- 6) S25°E 4.00' 8" Cedar (Fd. Blaze with scribing, but could not read); 7) N33°W 36.30' - 7" Cedar (Fd. two blazes on SE side of tree); 9) N48°W 30.40' 6" Cedar (Fd. 30d spike on SW side of tree); 10) N58°W 17.04' - 12 Cedar (Fd. 40d spike on N. side of tree); 11) N48°E 10.10' - 6" Black Ash (Fd. 30d spike on SW side of tree);

12) East 19.87' SE Cor. Sec. 34 (24-14)

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- 1-1 Closing corner common to Sec. 2 & 3, T23N, R14W Fd. 4" DOC Brass Cap on 1" iron pipe that is 1.56' North of intersection with standard line. Witnesses #1, 2 & 3 are gone; #4 rotten stump; #5 is dead; #6 is fallen; #7 is dead; #8 is gone; #9 is leaning, #10 is dead; #11 is gone. #12 is OK. South 21' to N. Edge of Lemon Creek. DOC monument accepted as a careful and faithful perpetuation of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 1-1 DOC (DNR) Monument 1.56' North of Standard Line intersection. Add Blue Carsonite Post 1' South. NW 0.5' to face fd. Cedar Post – East 19.85' to top 'T' iron fence post in creek # I13 – T24N, R14W (#12).

 N15°W 17 00' to fd. 30d nail in E. side 11" Cedar: N54°W 21.49' to set N & T in SW side 12" R. Maple: N54°W 21.49' to set N & T in

SW side 12" R. Maple; N35°W 36.5					λ(N Q T III
14" R. Maple	00.01	,	الحد ا	OF M/O	
Signed by: Oney	Melon	Date: 6/28/	12010 \$	THICH.	
Surveyor's Michigan License No.:	39088	, ,	1:/	CRAIG W.	· P
				PROFESSIONAL GURVEYOR	
	FORM APPROV	/ED BY MICHIGAN STATE I	BOARD OF PROM	No.	N. 28, 1971
	TORNIALINOV	ED BY MICHIGAN CTATE	67	Revise	May 14, 1975 sed Jan. 1983
			****	OFE 3510% Revis	sed Oct. 1995