SUHVEY & REMONUMENTATION

MAY 07 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Mason	Located In:			
(County)	cocated IU.	Corner Code #	H. 1944 FILED	-
1. Public Land Survey	T19N R 181 T19N R 171	- Maria		M
Property Controlling in Section Miscellaneous Property in Sec.	TRTRSTRSTRSTR		OCT - 3 1996 MARY GOLDEN KOLASKI MASON COUNTY REGISTER OF DEEDS	
4. Lot No, Reco	rded Plat		Register of Deeds Stamp & File Num	nbe
5. Private Claims			, A B C D E F G H T T V	
i, Sammy S. Barnett requirements of P.A. 74, Michiga conformance with regulations and United States Department of the I that the corner points mentioned Board of Land Surveyors or by recovered, found as expressed be	, in a field survey on <u>Sept</u> an P.A. of 1970, the corner point rules therefore as required in the interior, Bureau of Land Manager In lines 3, 4 and 5 above were in a Decree of a Court of Law; low:	. 19 96 do hereby state is mentioned in lines 1 and 2 abore current manual of survey instructionent or by a decree of a Court of Liconformance with the rules of the established, re-established, more	e that under 4 7 9 10 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
NOTE: Not more than 2 com- on this certificate.	ers, all in the same town and n	ange, may be recorded	10 30 29 28 27 26	24-
A 50			12 31 32 33 34 35	∫ 36
#1 Sugar 10" S21W 43 1ks. #2 Beech 9" N35W 19 1ks. (1887 J. Mitchell Monument not given Witnesses trees still stand 1959 K.B. Stephens B. Description of corner evider M-03 & A-03 corner common ton Sept. 11, I found 1%" recorded witnesses are: # 1 Gone # 2 Gone # 3 Beech 26" W. 54.2' # 4 Hemlock 20" N06E 13.01' # 5 cut off # 6 same as # 4 # 7 Cut off C. Description of monument force	G.L.O. Set 1½" pip (28.38') #3 Beech 20 12.54') #4 Hemlock: #5 Maple 24' 1974 K. Ross found 1½" pi #6 Hemlock 1 nce found and/or method app to sections 1 & 12 T19N. pipe. I found no eviden #8 Tw. Beech 24 #9 P.K. in end #10 Capped iron spike in NW side	e "W. 54.2' 20" N 12.0' "NNW 9.7' s Act 74 L 1. P 265 ipe .8" N12E 13.0' (#4) Diedin restoring or reestablish R18W (Hamlin) & section ice to dispute this locat "SI7W 63.50' spike in S of Asp. Dr. S37W 7.21' 10" East	ns 6 & 7 Tign. Ri7W (Victory) same corner tion. The condition of the SW side	36-
C. Description of monument for of M-03 & A-03 corner common to I replaced the 1% pipe, in	+h +	RIBW (Hamlin) & sections	5 6 8 7 TION RITW (Victory) same corner	
I replaced the 14" pipe, in this location as a careful and 4 Hemlock 20" NOSE 13.01's 8 Tw. Beech 24" S17W 63.50'd 9 P.K. in end of Asp. Dr. s 10 capped iron East 10.0'd 11 Maple 10" S75W 38.19's p 12 Power Pole N23W 12.15's Signed by	nd faithful reestablishm spike in NW side spike in SW side 637W 7.21' wike in SE side pike in NE side Bevere 16923 Peer Group Reviewed	a Standard Mason County ment of the original cor.	Monument and accepted oner. SAMMY S. BARNETT PROFESSIONAL SURVEYOR No. 16923	
Date:		FORM APPROVED BY M	MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1871 REVISED MAY 14,1975	

Mason County Surveyor

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14,1975
REVISED JAN, 1965
REVISED JAN, 1965
REVISED OCT, 1965 LIBER