SURVEY & REMONUMENTATION

APR 28 1995

Miscellaneous

Property in Sec.

CON	ARA	CC	ION
1 .L 2N	/i LV1		

LAND CORNER RECORDATION CERTIFICATE FILED Filing Requirement of Act 74, Mich. P.A. 1970 AT 1 O'CLOCK For corners in Corner Code ## MASON Located In: OCT - 7 1994 K-13 T 19 N R 15 W **Public Land Survey** __ R _ MARY GOLDEN KOLASKI __ R _ MASON COUNTY _ R _ Т REGISTER OF DEEDS __ R **Property Controlling** Ť __ R __ T __ in Section S ____ T .___ R Register of Deeds Stamp & File Number

_ , Recorded Plat ... 5. Private Claims

I, Sammy S. Barnett , in a field survey on Scptember 20 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

SouthEast corner, Section 35, on the Township Line

S

Τ_

1838, GL.O., John Brink 1914, C.E. Mitchell Monument - not given Set wood post Beech 8" N 71° W 331k(21.78') #1 1971, R.A. Griffin, P.S. #2 Maple 4" N 35° E 201k(13.20°) Did not find corner monument, set by measured distance from 1904 R.O. Towns, C.S. NW cor., Sec. 1, T18N,R15W, on Monument not given

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

SouthEast corner, Section 35, on the Township Line K-13

On September 20, 1994, I found 1" Iron Pipe North of center-line of Decker Road Found no other evidence to disbute this location for the corner.

NOTE; Did not recover R.A. Griffins concrete monument, might not have been set. witnesses is; #1 Gone #2 Gone #3 Found in good cond. #4 Found in good cond. #5 Found in good cond.

#6 Found in good cond.

of Section 1, I18N, R15W Set 5" x 36" Conc. Monument 1990, John Schulke, P.S. Found 10" dock spike, replaced with 1" x 30" iron pipe

10

11

R.A. Griffins witnesses

- #3 Maple 5" N 50° E 100.50
- Tw. Maples 10"-10" N 389 41.45
- Center of brass cap monu NE cor. Sec. 2, T18N,R15 East 14.52'
- #6 Pine Post 4" x 7' North 33.20

Condition of recorded

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SouthEast corner, Section 35, on the Township Line K-13

Replaced 1" Iron Pipe with a 5/8" Re-rod 24" in lenght with 2 1/2" aluminum cap, stamped Mason County Monument set 1 foot below Road surface, and is accepted as a careful and faithful reestablishment of the position of OF MICHIGAN the original corner.

(OBT #3) Maple 5" N 50° E 100.50' (10" dock in SE side of tree) (OBI #4) Tw. Maple 10"-10" N 38° W 41.45' (10" dock spike in SW side of tree) Center of brass cap concrete monument East 14.58' W. Pine 9" N 28° E 48.78' (60d spike in NW side of tree)

Signed by Sammy & Bang & Surveyor's Michigan License No.

Prer Group R

No. 16923 REVISED JAN., 1

SAMMY S. BARNETT PROFESSIONAL SURVEYOR

and Approve

Kenneth L. Ross Mason County Surveyor

LIRER

3PAGE 186