DEDTION	LAND CORNER RECO	RDATION CERTIFIC	ATE						
	Filing Requirement of	Act 74, Mich. P.A.	1970	· · · · · · · · · · · · · · · · · · ·	FIL	ED			7
For corners in Mason Locat	ted In: Corner	r Code #	AT 2:	59	_ 0'CL	OCK _		<u>e</u> 1	1
(County)								T "	
Public Land Survey T_20	N. R 17W. I	<u>13</u>		NO)V 2	! 1998	3		
т <u>т</u> Т	RR			<u>L</u> ИАТУ :	GOLDE	N KOI	ASKI		
2. Property Controlling S T	R				SON		Υ		
in Section S T 3. Miscellaneous S		***************************************	Registe	er of De		•	•	Numbe	} er
Property in Sec. ST						<u></u> -			
····									
Lot No, Recorded Plat _ Private Claims			<u> </u>	A B (C D	E F C	Э н :	J K	L M
			2	6	5	4	3	2	1
I, Kenneth L. Ross	, in a field survey on Oct	tober 10, 1998	4	7	8	9	10	ij	12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land			5 6	18	17	16	15	14	13
Management or by a decree of a Court of Law a above were in conformance with the rules of the	and/or that the corner points men ne Michigan Board of Land Surve	tioned in lines 3, 4 and 5 eyers or by a Decree of a	7					- 30	
Court of Law; established, re-established, expressed below:	monumented, re-monumented,	, recovered, found as	8 ; 9	19	20	21	- 22	- 23	24
NOTE: Not more than 4 corners, all in	the same town and range,	may be recorded	10	30	29	28	27	26	25
on this certificate.			11 12	31	32	-33	34	35	36
A. Description of original monument a L-13 S & Corner Section 36, T.20	and accessories and/or subs	sequent restoration:	13	:	<u>.</u>		. :		-
ORIGINAL GOVERNMENT SURVEY Mullett and Brookfield, 1837 to 1838 Set quarter sec. post (1) Elm, 8", N59°E, 36 links (23.76') (2) Elm, 7", N35°W, 29 links, (19.14') Lawrence Slater, PLS, LCRC, Liber 2, page 191, August, 1983. Michigan Dept. of Transportation States Found 10"X 14"X 20" tapered Red Stone, buried 28". Raised with a 23"X 1" Steel Rod buried 4" below the road surface. S 87° 44' 40.77"E, 5.28 feet to a %" steel rod. No other witnesses given.									
No other research on this corner wa	as found.								
B. Description of corner evidence four L-13 S % Corner Section 36, T.20		n restoring or reestablis	shing corr	ner:					
On October 10, 1998, I foun	d a 1"X 23" Iron as a r	iser to a stone that	is 30 °	belo	w the	road s	surfac	e.	
Condition of Record Witness	es are as follows: (1)	Gone, (2) Gone							
•									
C. Description of monument for corner L-13 S & Corner Section 36, T.20		ned to perpetuate locat	ing the p	osition	of the	corner	":		
I removed the 1" X 23" iron MONUMENT" on top of the stone in the and faithful re-establishment of the (3) P.P. N 80°E, 112.19', (60d spike (4) P.P. N 05°E, 54.64', (60d spike (5) Guard Rail Post N 24° W, 19.71' (6) Guard Rail Post, S 35°W, 18.20' (7) Guard Rail Post, S 75°W, 48.85'	ne exact location of the ne original corner. Re NW side) RE East Side) (60d spike on top) (60d Spike on top)	" Harrison Cast Iro 1" X 23" iron pin.	n Monume This c	nt sta	1s acc	MASON OF OF INETH I LAN SURVE	MICAY L. ROSS	caref	ul

Surveyor's Michigan License No. 17634