## SURVEY & REMONUMENTATION

## RATIFIED BY PEER GROUP PA 345 OF 1990 MONROE COUNTY, MIC 1994

ED BY PEER GROUP APR 2 8 1995

MONROE COU	
date: 10/4	1994
County Ren	1(5)

Property in Sec.

COMMISSION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED	en recorn
94 DEC 16	PH 3: 26

REGISTER OF TEEDS MOTIFICE COUNTY, MICH

Register of Deeds Stamp & File Number

ro	Comers in		
	MONROE (County)	Located In: IDA TWP. Corr	ner Code <i>=</i> ##
1.	Public Land Survey	7 8 8 7 E	E-6
	•	TR	
		T R T R	
2.	Property Controlling	S R	
_	in Section	S	
3.	Miscellaneous	SIR	1

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-6, T75, R7E, Ida Township, Monroe County — HD No. 58 1/4 Corner Common to Sections 16 and 17 ( Douglas Road being 1/2 mile south of Lulu Road — 6 inch stone over yellow sand ) 1820, G.L.O. Surveyor, Joseph Wampler, set quarter section post witnessed: B. Oak 18 (inch) S.41°W. 10 links & B. Oak 20 (inch) N.16°E. 9 links. 1903, L.A. Howard found stake partition survey of Section 17, T75, R7E. 1956, A.J. Marino notes unable to find stone. 1961, A.J. Marino notes placed spike. 1968, A.J. Marino notes iron pipe buried with witnesses. 1977, G.B. Warnke recorded L.C.R.C., Liber 2, Page 220.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-6 - 9/1994, found 1/2 inch x 8 inch iron pipe over 3/4 inch x 15 inch pinch pipe. Dug 20 inch diameter x 24 inch deep hole in yellow sand, no stone found. Set 1 inch x 36 inch iron pipe, 1.84 feet west of straight line between section corners and witnessed as shown below. 11/23/1994, set brass remonumentation cap on 1 inch x 36 inch iron pipe and set monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-6 - Set 1 inch x 36 inch iron pipe with brass remonumentation cap inside monument box to replace 1/2 inch iron pipe and pinch pipe and is accepted as the best available evidence of the position of the original corner and Witnesses:

North 80° West 140.38 feet to southwest corner of attached garage to res'd # 5298 West 33 feet to found 1/2 inch iron pipe

North 80° East 19.93 feet to double headed nail/shiner in west side of 24 inch Oak South 30° East 37.29 feet to double headed nail/shiner in west side of 18 inch Maple West 4.5 feet to centerline of pavement

Date 11/23/1994

\* GEORGE B. \*
WARNKE, JFI.
LAND SURVEYOR
NO.
19474
OF ON AND SURVEYOR
H STATE BURN OF AND SURVEYOR
H ST

APPROVED BY MICHIGAN STATE GOAL OF AND STRUCTURE. JAN. 28, 19 Revised May 14, 19 Revised Jan., 19