SURVEY & REMONUMENTATION

FEB 1 3 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A., 1970

		Filing Requirem	ent of Act /4, Mich. P.	A., 1970		CO DO
	corners in				₹	RECU 97 D
	Monroe (58) (County)	Located In:	Corner Code #		RESECTION OF THE PROPERTY OF T	OEI VE
1. F	Public Land Survey	WHITEFORD TWP. T <u>88</u> R <u>6E</u> T R T R	1-4	·		30 PM
i 3. N	Property Controlling n Section Miscellaneous Property in Sec.	TR STR STR STR		Register (ĉ	€ File Number
4. L	ot No, Recorded	Plat		1 A B	C D E F G	H I J K L
5. F	Private Claims			2 -6-	54	-3-2-1
1997 Remonumentation Program Corner					89	10
I, George B. Warnke, Jr., in a field survey on October, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and / or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:				nent of 7 points 8 19	29 - 28	-15 -14 -1321272625
NO	E: Not more than 2 corners, a on this certificate.	ll in the same town and range, m	ay be recorded	11	32 33	
 A. Description of original monument and accessories and/or subsequent restoration: 1820 GLO, Surveyor - J. Wampler, set the ½ mile post from which an Elm 11 ins. dia. bears S73W 14 lks. dis. & a W. Oak 23 ins. dia bears N18E 20 lks. dis. 1964 Michigan State Highway Department Witness Card notes Found boat spike in Mon Box & witnesses: N70W 57.14' to a C.B. & S75W 86.32' to a C.B. 1965 Michigan State Highway Department Witness Card notes Found boat spike in monument box & witnesses: S80W 87.75' chiseled X on top of catch basin curb / N76W 58.45' chiseled X on top of catch basin curb 1973 M. Freels Survey #73-109, recorded in Liber 643, Page 124, notes ships spike in mon box fd as per State Highway plans 1989 G.B. Warnke Survey #89-209 notes found boat spike in monument box & witnesses: N 2.48' of CL conc. pavement / N78W 57.1 to SE cor curb inlet / S79W 86.33' to NE cor curb inlet 1994 G.B. Warnke Survey #76-200 notes found boat spike in monument box / probed 1 ¾' to 2' below boat spike with no other evidence found – witnesses: South 2.45' centerline conc. pavement / S85E 101.68' "+" in 82+00 on S side of conc / N75W 76.45' NE conformation of N conc rail for bridge over US 23 / S70W 86.40' NE cor of steel rim at SE cor bridge over US 23 						
B.	October 7, 1997, G.B. Warnk	e found and/or method applied se crew found boat spike 10" d f CL concrete pavement & 90'	leep near southeast edge o	of existing monu	ment box in con-	crete pavement of
RA	TIFIED BY PEER GROUP, PA	345 OF 1990, MONROE CO	UNTY, MICHIGAN, DATE	10/4/1997, CO	UNTY REP.	
	12/1/1997, G.B. Warnke wire	ed on plastic remonumentation	n cap to found boat spike i	in existing monu	ment box.	
C.	Wired on plastic remonumen the position of the original co North 78° West 56.86 feet to South 79° West 86.33 feet to North 9.5 feet to north edge of South 14.5 feet to south edge South 45° West 28.26 feet to South 10° West 29.24 feet to	southeast corner of catch bas northeast corner of catch bas of concrete pavement	in existing monument box in at east end of overpass in at east end of overpass aerial target beam support for south gu	and is accepted over US 23 over US 23 ard rail		nilable evidence of
Ŭ	ned byveyor's Michigan License No.	19474 * * LICE	GEORGE B. WARNIKE, JR. RROFESSIONAL WARNIKE, JR. RROFESSIONAL NO. 19474 SPENSIONAL MINIMUMANIMUM NO. 19474 SPENSIONAL	Date <u>De</u>	cember 3 , 1997	7 ND SURVEYORS, JAN. 28, 1 REVISED MAY 14, 1 REVISED JAN., 1 REVISED OCT., 1
			APOFESSIONAL SIR MINISTRALIA	• 00		REVISED JAN., 1 REVISED OCT., 1

4 FABI 337

LIBER