SURVEY & REMONUMENTATION

APR 2 8 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

PA 345 6	
MONROE COUR	TY, MICHIGAN
date: 11 [2.]	1903
County Rep.:	Sign
or corners in	7

Property in Sec.

RATIFIED BY REER GROUP

	MONROE	Located In:	Corner Code =##
	(County)	BEDFORD TV	
1.	Public Land Survey	T 8 S R 7 E	A-8
		T R	F-100 Market
		T R	
		T R	
2.	Property Controlling	S T R	
	in Section	S	
3.	Miscellaneous	S T R	
	Property in Sec.	S T R	,

Register of Deeds Stamp & File Number

Lot No	, Recorded Plat		
Private Claims			
MONROE COUNTY REMONE	MENIATION PROGRAM		
Peer Group approved	corner on 11/08/1993 p	er Act 345 of 1990	
	остиск ст. тат род 1999 р	C. ACC 343 Of 1,550	•
G.B. WARNKE, JR.	, in a field survey on	8/24/1994	40
books a satisfication of the	, in a new survey on	D. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	, 19 ,
	requirements of P.A. 74, Michi		
	e in conformance with regula		

current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-8, T8S, R7E, 1/4 Corner Between Section 19, T8S, R7E, & Section 24, T8S, R6E (At Intersection of Consear & Adler Roads) (Also M-8, T8S, R6E) G.L.O. Surveyor set 1/4 post on east range line of Town 8 South, Range 6 Fast. / Road survey in 1924 indicates a stone. / Concrete pavement in place since approximately 1929. / J.W. White survey (1920's?) indicates a stone. / Case & Fleck survey in May of 1950 indicates a spike. / G.B. Warnke surveys No. 77-42, 81-73 & 83-271 indicates a 1/2 inch iron pipe over a bolt.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-8 - 9/8/1993, found a 1/2 inch iron pipe at road surface. Warnke references fit well. 8/24/1994, dug 18 inch x 36 inch deep hole, found 1/2 inch x 3 inch iron pipe over 1 inch x 3 inch hex bolt, and probed in all directions but no stone or post found. Found 1 inch x 24 inch iron pipe approximately 12 inches below surface and 0.6 feet east of 1/2 inch x3 inch iron pipe. Set brass remonumentation cap on 1 inch x 36 inch iron pipe inside monument box to replace 1/2 inch iron pipe over bolt. Witnessed as shown below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-8 - Brass remonumentation cap on 1 inch x 36 inch iron pipe inside monument box to replace found iron pipe over bolt and is accepted as the best available evidence of the position of the original corner and witnesses:

South 75° West 74.54 feet to found nail/shiner in north face of telephone pole North 40° West 37.48 feet to found nail/shiner in south face of electric pole North 45° Fast 48.58 feet to found nail/shiner in southeast face of telephone pole South 50° East 47.17 feet to found mail/shiner in north face of telephone pole

Signed by	5()	人
Surveyor's Michigan License No.	19474	
dave, eve investigant all and the		(

8/24/1994

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971