SURVEY & REMONUMENTATION

RATIFIED BY PEER GROUP PA 345 OF 1990

Property in Sec.

For

APR 2 8 1995

MOMINE COOMITY, Date of the	
dato: 10.04-1993	LAND COMPRESSION CERTIFICATE
date: 10 · OU - 1993 County Rep.:	Filing Requirement of Act 74, Mich. P.A. 1970

	00,,,010,117		
	MONROE (County)	Located In: BEDFORD TWP.	Corner Code ##
1.	Public Land Survey	т <u>8SR7E</u>	G-2
		T R	
		T R	
		T R	
2.	Property Controlling	S T R ·	
	in Section	S T R	
3	Miscellaneous	STB	

Register of Deeds Stamp & File Number

4.	Lot No , Recorded Plat			
5.	Private Claims			
	MONROE COUNTY REMONUMENTATION PROGRAM Peer Group			
	approved corner on 10-26-1993 per Act 345 of 1990.			

I, G.B. WARNKE, JR., in a field survey on _ NOVEMBER do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

G-2, T8S, R7E, 1/4 Corner Between Sections 3 & 4 (Jackman Road between Rauch & M-151) G.L.O. Surveyor Joseph Wampler set 1/4 section post between Sections 3 & 4. Witnesses: B. Oak 40 inch N.62°W. 24 links, B. Oak 17 inch N.65°E. 90 links. / Old book indicates stone at 1/4 corner between Section 3 & 4, (Jackman Road). The Northeast 1/4 of Section 4 was measured by John W. VanDeventer in 1900. / Surveys by M.R. Fleck in 1970's witness a 5/8 inch iron rod. / This corner was excavated following chip and seal paving in 1991 and found intact. This corner has been used extensively for this area.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-2 = 9/17/1993, found mangled 5/8 inch iron pipe (3/8 inch interior diameter) and witnessed as shown below.

11/1994, set 1 inch x 36 inch iron pipe with brass remonumentat OF MICHIG inside monument box to replace found pipe.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

G-2 - 9/17/1993, found mangled 5/8 inch iron pipe (3/8 inch interior diameter). accepted as the best available evidence of the position of the original corner. Witnesses:

South 45° East 25.41' nail/shiner in northwest side of power pole North 70° East 37.24' nail/shiner in northwest side of 24 inch Maple tree

South 50° West 44.19' nail/shiner in southeast side of 48 inch Oak tree West 59.72' nail/shiner in northeast side of Poplar tree

West 33.00' capped (No. 19474) iron pipe on East & West 1/4 line

11/1994, set 1 inch x 36 inch iron pipe with brass remonumentation inside monument box to replace found pipe.

Signed by Surveyor's Michigan License No.

NOVEMBER 28, 1994

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1

GEORGE B. WARNKE, JR. LAND SURVEYOR NO. 19474

LAND

Date ...