SURVEY & REMONUMENTATION

RATIFIED BY PEER GROUP PA 345 OF 1990

DEC 0 7 1994

RECEIVED FOR RECORD

MONROE COUNTY, MICHIGAN				
date:	12	11994		

County Rep.:

in Section

LAND CORNER REGORDATION CERTIFICATE Filing Requirement of Act 74 Mich PA 1970

94 OCT 12 PH 2: 43

For corners in		3	Toquilonione of Not 14, thini: 114, 1570		
	MONROE (County)	Located In:	Corner Code ≠1	,	
(County)		ERI	ERIE TWP.		
1.	Public Land Survey	T 8 S R 8 E	A-2		
		T R			
		T R			
		T R			
2.	Property Controlling	S T R			

REGISTER OF DEEDS

S ____ T ___ R ___ S ___ T ___ R ___ Miscellaneous Register of Deeds Stamp & File Number Property in Sec.

4. L	ot No, Recorded Plat
5. P	rivate Claims
199	94 MONROE COUNTY REMONUMENTATION PROGRAM
	er Group approved corner on 7/12/1994 per Act 345 of 1990.

10

8/30/1994 __ , in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, lound as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-2, T8S, R8E, East 1/4 Corner of Section 6 (On Minx Roads) (Also M-2, T8S, R7E - Approved in 1993)

1820, G.L.O. Surveyor Joseph Wampler set 1/4 post on east range line of Section 1, T8S, R7E. Witnesses: B. Oak 17 inch S.50°E. 38 links & B. Oak 19 inch S.71°W. 31 links. Examined Bedford & Erie Township files & found no old evidence of corner used. L.A. Howard December of 1903 did survey in northeast 1/4, Section 1, T8S, R7E, but didn't dig corners. Accepted available surveys from 1973 to date. Recorded in L.C.R.C., Liber 3, Page 282.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-2 - 1993, gravel road is approximately 18 inches below natural grade passing over a sandy knoll. Evidence of original post was probably obliterated. Found Case & Fleck 1/2 inch x 48 inch iron pipe, which fit occupation east and west. Dug 24 inch x 24 inch x 20 inch hole; found evidence that it had been dug before further west & north. Reset 1/2 Inch Iron Pipe & Set 1 Inch x 32 Inch Iron Pipe and witnessed as shown below. 11/16/1993 - Dug 4' x 3' (N. & S.) x 18 inch deep hole to east of iron pipe - No other evidence found. 8/30/1994, set brass remonumentation cap on 1 inch x-36 inch iron pipe to replace 1/2 inch iron pipe & 1 inch x 32 inch iron pipe.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-2 - Set brass remonumentation cap on 1 inch x 36 inch iron pipe to replace 1/2 Inch Iron Pipe & 1 Inch x 36 Inch Iron Pipe and is accepted as a careful and faithful perpetuation of the position of the original corner; and, this position not established by original government surveyors; this monument is accepted as the best available evidence of the position of the corner. Witnesses:

14350

East 33.00' 1/2 inch capped iron pipe (No. 6193)

South 85° East 23.00' nail & washer

South 40° East 70.51' roofing nail/shiner in west face of 12 inch Spruce

South 70° Fast 94.55' southeast corner of residence No. 10952

Signed by 19474 Surveyor's Michigan License No.

8/30/1994

warnke, ja. LAND SURVEYOR NO. 19374 SED LAND $\bar{e}Q$

GEORGE'B.

OF END SURVEY EYORS, JAN. 28, 197

3 MUE 377

Date

REVISED MAY 14, 1975 REVISED JAN., 1983