SURVEY &

ONUMENTATION ON TOALM COUNTY REMONUMENTATION PROGRAM

JAN 17 1996

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

P-13: S 1/4

STATE D	F MICHIGA	Ì
MONTCA	LK COUNTY	
RE	CORDED	

For corners 60MMISSION Located In: Montcalm Corner Code #

Ferris Township

1. Public Land Survey Sec. 33 T 11 N R 5 W

2. Property Controlling in Section

(County)

3. Miscellaneous Property in Sec.

__, Recorded Plat _

5. Private Claims

William Tingley

a field survey on

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

1831, Robert Clarke, Jr. Deputy Surveyor, GLO Notes

Set Post

Beech 7" N53°E 21 links

Beech 13" N59'W 12 links

August 22, 1911, E.D. Youdan, County Surveyor, Field Book 11-5, Page 24 Found large stone point up set by J.E.Youdan, Took new Bearing Tree Maple 5" S 17-1/2°E 31'10"

September 10 and 11, 1912, E.D. Youdan, County Surveyor Found Stone thrown out in grading road

Reestablished from my new Bearing Tree of 1911

Drove Gas Pipe

20 DEC 95 11:41 A.M.

VIRGINIA L. KNEPPER REGISTER OF DEEDS

Register of Deeds Stamp & File Number

	6	5	4	3	Ź	1
	7	. 8	9	10	. 11	12
	18	17	16	15	14	13
	19	20	-21	22	23	24
	30	29	28	27	26	25
(31	32-	-33	34	35	36

ACCEPTED BY THE MONTCALM COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD 12.5.95

> WGT. William Tingley, PS, Chairman

Description of corner evidence found and/or method applied in restoring or reestablishing corner: Did not find pipe. Set 126-2/3 feet West of NE Corner, Section 5 per Youdan record of 1912 when surveying Section 5, 10-5 agreeing with 1912 distances to Section Corners

Description of monument for corner and accessories established to perpetuate locating the position of the corner: **Set Remonumentation Monument**

Set P.K. Nail & Tag In Eastside Post

N05°E

30.92 feet

Set P.K. Nail & Tag in Westside Post

N15°W

33.65 feet

Remonumentation monument for Section Corner 4 and 5, T10N-R5W, East 126.67 feet

Centerline East-West Pavement, South 8.1 feet

Southwest Corner Section 33

West

2642.89 feet

Southeast Corner Section 33

East

2638.50 feet

This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

Surveyor's Michigan License No.

REVISED MAY 14, 1875
REVISED JAN., 1883
REVISED JAN., 1883
REVISED JAN., 1883
ADAPTED FOR WORD PROCESSING MARCH, 1893



ER 3 PAGE 265