SURVEY & REMONUMENTATION

APR 2 4 1995

MONTCALM COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in COMMISSION	ı							
Mont calm Located In: Corner Code #	ļ			TTATT.	ne sit	MITTORI		
					OF HI CALM C		•	
					RECORD			
1. Public Land Survey Sec. 33 T 11 R 7 F-13 S 1/4	-		,		(/Frantri	Ç.U		
			i	5 JUL	94 9	:39 A.	M :	, <u>, , , , , , , , , , , , , , , , , , </u>
T R						,		4-49
2. Property Controlling S T R	\				nia L.			
in Section S T R	R	eniste	r of De	REGI Seds S	STER (5 Jumbe	r
3. Miscellaneous SR								
Property in Sec. STR				`				
4 Lot Ata Canadad Dist								
4. Lot No, Recorded Plat 5. Private Claims		۱,4	. В (C D	E F G	H	J K	L M
o. Thrate diams		2	6	- 5		- 3.	2	,
		3	-		7		-	
I, William Tingley a field survey on November 15,	1002	4	7	8	9	10	11	- 12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points me		5						
in lines 1 and 2 above were in conformance with regulations and rules therefore as required	d in the	6	18	17	16	15	14	13
current manual of survey instructions of the United States Department of the Interior, Bureau of Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3,		7			<u> </u>			
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Dec	cree of a	В	. 19	20	21	22	-23	24
Court of Law; established, re-established, monumented, re-monumented, recovered, for expressed below:	und as	9						
expressed below.		10	30	29	28	27	26	25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded	d	11					<u> </u>	
on this certificate.		12	31 -	32	3 3	34	35	36
A. Description of original monument and accessories and/or subsequent restoration:		13 l					i_	لــــــا
December 9, 1836, Noah Brookfield, Deputy Surveyor, GLO Notes								
Set Post 40 Chains West of Corners 33-34								
Pine 24" N46°E 27 links Beech 10" N86°W 11 links								
1884, H.M. Caulkin, County Surveyor, Field Notes 11-7 Page 82								
Reestablished 39.88 chains from Corner 33-34 South Boundary and 26.12 chains	s from N	leande	r Con	ner on	Lakesi	hore		
Set Fire Clay Mon and Blacksmith Cinder								
New Bearing Tree: Pine Stump 28" N10°E 62 links	. ludou (Saudal						
1915, R.D. McNutt, County Surveyor, Notes (Montcalm County Road Commission Found Fire Clay mon	ı muex (-arus į						
Oak 6" N45°30'W 70-1/4 links								
Hickory 3' N39°E 63-1/4 links								
1920, R.D. McNutt, County Surveyor, Notes Oak 6" N46°W 46.5"								
Apple 8" S4°E 46'								
Centerline Pine Stump N10°E 42'								
Ash 3" N39°E 41.7'			1_ #40	4) /D-			0221	
June 8, 1934, R.D. McNutt, County Surveyor (Montcalm County Road Commission Gas Pipe 3' long	ingex c	aro ri	(6 #.1 <i>0</i>	4) (RC	ssien	says I	2001	
Oak 6" N46°W 46.5'								
Apple 8" S4°E 46'								
Centerline Pine Stump N10°E 42' Ash 3" N39°E 41.7'								
August 30, 1977, Mid-Michigan Engineering Company , Jerald Gray, #17741								
Used S1/4 Section 33 T11N R7W								4.
Recorded Survey November 13, 1978, Liber 511, Page 1124							•	
No witnesses given - no response to our request for them Continued on back							٠, , ,	
B. Description of corner evidence found and/or method applied in restoring or reestab		orner:					÷	
Found 3/4" Iron Rod as per Kevin Roosien, 1988; as per Mid-Michigan 1977; as per	r R.D. M	cNutt	1934 r	iotes.				
Accepted as corner. C. Description of monument for corner and accessories established to perpetuate local	esting the	nociti	on of t	he com	Norr	•		Ħ
Set remonumentation corner and mon box over 3/4" iron.	aung me	: positi	JII OI U	16 6011		·		LIBER -
Spike Southwest Side 40" Oak N40°W 47.12'					· .			
Spike in Northwest side 30" Catalpa (now stump) S45°W 92.14'							3	PAGE
Spike in Northwest side Power Pole N35°E 71.80' Spike in Northside Power Pole S75°E 115.60'								-0
Iron East 7.9" (Northeast Corner Section 5 T10N R7W								
This corner is accepted as a careful and faithful perpetuation of the position of the	e origina	al corn	er.					
Signed by Illiam linely Date	1/10	2/9	9					
Surveyor's Michigan License No. 30104	FORM AT	PROVED F	Y MICHIC	AN STATE	BOARD OF	LAND SUR	VEYORS, JA	IN. 28, 1971
THE THE PARTY NAME AND THE PARTY STRAFT PERSON				(,	=•		EVISED MA	
GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLICACT 365 OF 1960 AT A MEETING HELD				ADAP	TED FOR W	ORD PROC		
PULLINA INTO THE PROPERTY OF T								t

Willem Tingley, PS, Chairman

Section A (continued)

February 4, 1988, K. Roosien, #31604, Land Corner Record, Liber 2, Page 203
Found 3/4" Iron Rod per 1934 Notes from MCRC -- also fits Courthouse Records
Spike in Westside of 40" Oak N40°W 47.12'
Spike in Northwest side 30" Catalpa S45°W 92.14'
Spike in Northside of Power Pole S75°E 115.60'
Spike in Northwest side of Power Pole N35°E 71.80 '
Iron East 7.92' (NE Corner Section 5 T10N R7W)

The state of the s