MONTCALM COUNTY REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in	TAKU TEGIN
Montcalm Located in: Corner Code #	STATE OF MICHAELY MONTCALM COUNTY
Pierson Township	RECORDED
	7 NOV 2000 5:12:57 AM
, 1. Public Land Survey Sec. 36 T 11 N R 10 W K-13	LORI A. WILSON REGISTER OF DEEDS
T R	REGISTER OF DECUS
TR	
<u>TR</u>	
2. Property Controlling S T R In Section S T R	Register of Deeds Stamp & File Number
3. Miscellaneous S T R	register of Deeds Staffip & File Number
Property in Sec. S T R	
	: •
4. Lot No, Recorded Plat	. , A B C D E F G H I J K L M
5. Private Claims	
	2 6 5 4 3 2
to Feldonium at the Co. Co.	3
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentione	4 7 8 9 10 11 12
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the	he 3
current manual of survey instructions of the United States Department of the Interior, Bureau of Lan Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and	
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of	fa / Table T
Court of Law; established, re-established, monumented, re-monumented, recovered, found a expressed below:	
expressed below.	9
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	10 30 29 28 27 26 25
on this certificate.	" - - - - - - -
	12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:	13
 December 12, 1836, Noah Brookfield, Deputy Surveyor, GLO notes, West on south Set post comer of Sections 35 and 36 	side of section 36.
Maple 12" N81°W 17 links (11.22 feet)	•
Birch 10" N64°E 12 links (7.92 feet)	
2. April 20, 1896, H.M. Caukin, county Surveyor, Record of Survey Book 2-A Page 49	
T11N-R10W corner 35,36 south boundary June 1896. Found bearing tree maple I	blown down NNE from estimated point where
bearing spot was measured. S81°E 1.7 links an found bottom of stake, Thence N	64°E 12 links and found rotten birch. Took New
Bearing Tree Pine stump 22" N49½°E 34½ links (22.77 feet)	
Pine stump 22" N49½°E 34½ links (22.77 feet) 3. December 28, 1903, Henry M. Caukin, County Surveyor, Record of Survey Book 2-	A Page 49. Book 3 Page 100. Book 1-A
Page 84	
Found my new bearing tree of 1896at corners marked put down iron. Pine stump 22" N49½°E 34½ links (22.77 feet)	•
Pine stump 22" N49½°E 34½ links (22.77 feet) 4. December 1988, Glen S. Hackbardt # 25844, LCRC Liber 002 Page 239	
Found concrete monument near centerline "X" E-W road & fence to north also mea	asured 326.12 feet west of N 1/4 corner Sec. 2
Nelson Twp.	
Maple 12" N40°W 33.65 feet Maple 10" North 37.45 feet	ACCEPTED BY THE MONTCALM COUNTY SURVEY PEE GROUP AS THE OFFICIAL CORNER UNDER MICHIGAL
Ash 5" N40°E 38.85 feet	PUBLIC ACT 345 OF 1990 AT A MEETING HELD 8/09/
Conc. monument East 326.12 feet	WEX
5. May 15, Kirk Breitels, #30077, Kent County Remonumentation LCRC #11842 Montcalm Co. Monument K-13, T11N-R10W Sec. 36 west 326.18 feet	William Tingley, PS, Chairman
Montcain Co. Monument N-13, 11114-R 1044 dec. 30 West 320.10 leet	triman rugity, F5, Chainnan
B. Description of comer evidence found and/or method applied in restoring or reestablishing	
Found Concrete monument 3" below road surface with an iron bar along the north Concrete monument possibly set in 1938.	side of monument. No other evidence found.
Concrete monument possibly set in 1990.	
C. Description of monument for corner and accessories established to perpetuate locating to	he position of the order OF MICA
Set remonumentation pipe in place of concrete monument.	
Set N/T W/S poplar 17" S11°E 20.59 feet Set N/T W/S maple 7" S47°W 25.60 feet	* WILLIAM G. *
Set N/T W/S maple 18" N30°W 33.75 feet	PROFESSIONAL
Set N/T W/S maple 14" N06°E 28.41 feet	SURVEYOR ON
T10N-R10W J-01 East 326.18 feet This corner is accepted as the best available evidence of the position of the original co	mer. 30104
	POFECCIONAL
Bearings given are magnetic. Standard remonumentation pipe consists of a Berntsen s	stainless steel 2 3/8 3 20 11 his with a brass
cap stamped "MONTCALM COUNTY REMONUMENTATION, P.S. # 30104"	
en de la companya de	
	2/2/
Signed by William S. horry Date	8/09/00
Surveyor's Michigan License No. 30104	M APPROVED BY MICHGAN STATE BOARD OF LAND SURVEYORS; JAM. 28, 1971 REVISED MAY 14, 1975