SURVEY & REMONUMENTATION

APR 2 8 1995

LAND CORNER RECORDATION CERTIFICATE

MARQUELLE COUNTY
MICHIGAN RECEIVED FOR RECORD

1994 DEC 29 PM 1: 54

		a a
		- 5
 	*	10.

COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

r comer	s in	IMIOO(OIAaa.	rement of Act 74, Mich.	Patricia d. Manley &
Marqu		Located In:	Corner Code ##	REGISTED OF DEED A
Public	Land Survey	T 46N R 25W T 45N R 25W	K-13 /	RATIFIED BY PEER GROUP P.A. 345 OF 1990 Aarry Of Bussme
•		T R T R		DATE Sept 12, 1994
in Seci Miscel	ty Controlling tion laneous ty in Sec.	S T R S T R S T R S T R		Register of Deeds Stamp & File Number
Lat No	, R	ecorded Plat		A B C D E F G H I J K L 1
				A B C D E F G H I J K L I
Michae	el Mileski	in a field survey on	September 94	2 6 5 4 3 2 10 11 12 12 12 15 16 17 18 18 18 18 18 18 18 18 18 18 18 18 18
urt of La pressed b PTE: No on	w; established, re elow: ot more than 4 co this certificate.	the rules of the Michigan Board e-established, monumented, re- erners, all in the same town a	monumented, recovered, for	und as 10 30 29 28 27 26 25 d 11 12 32 33 34 35 36
	_	nonument and accessories ar	id/or subsequent restoration	on:
K-13;	Southeast Co	rner Section 35;		
	See back of f	orm.		
Descrip	otion of corner evi	idence found and/or method	applied in restoring or rees	stablishing corner:
K-13;	Southeast Co	rner Section 35;		
	corner of sec		ite distance along an corner of section 34. <u>State Plan</u>	accessories. Reestablished the southwest arc connecting the southeast corner of the Coordinates:

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-13; Southeast Corner Section 35;

See back of form.



Units

Х

ned by	learnel	inlachil	Date	75	P00	1994	
,							

Zone Number - 2111 Michigan North

- International Feet = 565300.92268

= 26148999.92024



A. Description of original monument and accessories and/or subsequent restoration:

K-13; Southeast Corner Section 35;

Originally established during U.S. Survey conducted by Wm. A. Burt, D.S. for Douglass Houghton, D.S. in 1844 and monumented with a wood post witnessed by a Spruce Pine 8 N74°E 38 lks.

and a

Spruce Pine 8 N48°W 25 lks.

And from the 1852 subdivision notes of T45N, R25W a Spruce Pine 12 S31°W 11 lks. and a Spruce Pine 14 S65°E 14 lks.

During the course of a survey conducted by the Marquette Road Commission in 1941 and described in M.C.R.C. field book 712 all U.S. corners lying between the south one-quarter corner of Section 36 and the southwest corner of section 34 were considered lost. The south one-quarter corner of section 36 and the southwest corner of section 34 were both considered by the Marquette County Road Commission as legitimate U.S. corners and all intermediate standard corners except possibly the south one-quarter corner of section 35 were monumented with a 1" iron pipe and jack pine post at the appropriate proportioned position. Refer to M.C.R.C. field book 712 page 9 for diagram.

The M.C.R.C. noted the following new bearing trees as of 15 December 1941:

9" Jack Pine S35°E 34.6'

6" Dry Jack Pine Stub S85°W 83.9'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

K-13; Southeast Corner Section 35;

Set 3/4" x 24" iron rod with 3" aluminum cap proportionally along an arc correcting the southeast corner of section 36 and the south one-quarter corner section 34.

N21°E N62°E S62°W N53°W N12°W	SW Corner of Garage Set ½" x 18" Iron Rod & Cap Set ½" x 18" Iron Rod & Cap SE'ly Corner Warehouse Bldg. SE Corner Quonset Bldg.	#3909 <u>1</u> #39091	171.89' 46.65' 129.31' 108.44' 274.71'
	como decinoce blag.		Z/4./ `

. .