MARQUETTE COUNTY MICHIGAN RECEIVED FOR RECORD

OB N	UMBE	94030			
HEET	NO.	:	1-498		

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1994 DEC 28 PN 5:57

or corners in	. 0		
MARQUETTE (County)	Located in:	Corner Code =##	Patricia A. Manley MREGISTER OF DEEDS OF
. Public Land Survey	T 47N R 27W T 46N R 27W	L-13	KECIZIEK DE DEFIIZ N. K.
Property Controlling in Section Miscellaneous Property in Sec.	T R S T R S T R S T R S T R		LIBER 1 PAGE 168 Register of Deeds Stamp & File Number
	ecorded Plat		A B C D E F G H ; J K L M
GERALD W. CARLSON: Thereby certify that under requires 1 and 2 above were in the service of a survey instruction of the service of a service were in conformance with the service of Law; established, reserved below:	in a field survey on Monday, I uirements of P.A. 74, Michigan P.A. conformance with regulations and ctions of the United States Departicular of Law and/or that the corner the rules of the Michigan Board of	of 1970, the corner points mentioned drules therefore as required in the ment of the Interior, Bureau of Land r points mentioned in lines 3, 4 and 5 f Land Surveyors or by a Decree of a conumented, recovered, found as	19 20 21 22 23 24 9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
L-13: 1/4 Corner common Section 36, T47N-R27W. 1846: Austin Burt's orig corner monument as a Cec 10" White Birch N07W 2 7" Fir N84W 2 1932: M.C.R.C. field boo	dar post referenced by: 21 l	3" Spruce S83W 16.2' 12" Pine S18W 10.2' e 1976: Land Corner Record fro indicates the corner is a 1" 6" Sugar Maple AZ.120 10.0 4" Maple S89E 6.57 13" Fir S34W 8.78	' old bearing ' old bearing est, 9.0' North of South 1/4 Corner

Description of corner evidence found and/or method applied in restoring or reestablishing corner;

2994: Corner position established equidistant and on line between the Southwest and Southeast Corners of Section 36. Distances West and East are 2637.37'. The previous position established by Brotherton was considered incorrect as the Southeast Corner of Section 36 was not considered in his survey. The re-established Southeast Corner of Section 36 WECI double proportion - 1978) was re-calculated using the re-established Southwest Corner of Section 36 and the Dosition would move very little. It was decided by the Marquette County Peer Group to leave the re-established Toutheast Corner of Section 36 in place and re-establish the South 1/4 Corner of Section 36 as, stated above. The Te-established South 1/4 Corner is S29-10'23"W, 40.77' from the Brotherton iron.

> RATIFIED BY PEER GROUP DATE Dec

> > OF MICH

escription of monument for corner and accessories established to perpetuate locating the position of the corner. 994 - Set a 2 1/2" diameter aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Dnument stamped to identify the corner referenced by nails in:

Twin Jack Pine	e SloE	35.75	ft.						
Jack Pine	\$35W	19.98	ft.						
White Pine	N47W	4.57	£t.						
White Pine	N39E	9.30	ft.						
eel sign post	East	1.0	ft.						
nument is 0.30°	above gr	ound.	Monument	is 51.	5' East	of tr	wo track	road.	
. 8, Pg. 47									

GERALD W CARLSON SURVEYOR No. 24589 FORM APPROVED BY MICHIGAN STATE BOAR

Guslet W Carlso ∍r's Michigan Liceñse No.

DE EAND CONVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 MEYISED JAN., 1983

Record No. 498

Corner was set by running transit line due East from bearing tree corner at NW Section Corner.

1/4 Corner is 2656.60' East of the Section Corner.

1978: Land Corner Recordation Certificate filed by Charles F. Clark RLS No. 25836 found a 1" drill rod in stone pile and C.C.I.C. location tag referenced by:

Spike in P. pole

S71 56" West 96.62'

Spike in P. pole

NO 34" West 181.48'

Spike in 5" Maple stump

N85E 6.78'

Liber, 1RC, pg. 233

Jan of Ser