LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Marquette	I manda d Inc.								
(County)	Located In:	Corner Code #							
1. Public Land Survey	T 46N R 29	IM V1A							
1. Public Land Survey	T <u>46N</u> R 29 T <u>46N</u> R 29		-						
	TR	<u> </u>	-						
	TR_		_			,			
2. Property Controlling	S TR		_						
in Section 3. Miscellaneous	S TR		_						
Property in Sec.	S IK	-	_						
	·			Regi	ster of De	eds Stam	p & File	Numb	er
_									
4. Lot No, Records	ed Plat	···							
5. Private Claims				1 A B		, † G	H 1	J K T T	L
	٨	ıg 06 2003		2 6-	- - 5	-∤-	3-	2- -	1-
, Stephan J. Szyszkoski	nt in a falst accessor	19 V6 2VV3		3			+-		╁
J. Stephan J. Szyszkoski in a field survey on, 20 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in						— <u></u> 9——	10	 	1/2—
conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or					- 		++-		\vdash
United States Department of the Inte that the corner points mentioned in	erior, Bureau of Land Mana lines 3, 4 and 5 above wer	gement or by a decree of	a Court of Law and /or	6 —18		-16	151	141	ا 1 _. 3—
Board of Land Surveyors or by a	Decree of a Court of Li	aw; established, re-estal	blished, monumented,	7			+		<u> </u>
recovered, found as expressed below	V:			8 -19-	20	21	222	32	 24—
NOTE: Not more than 2 comer	s, all in the same town a	nd range, may be recor	ded	9					\perp
on this certificate.		,,,		10 - 30-] 27———7	T 6- 4 -2	
				11					Ľ
				12 -31-	32		34 3	5	36
				13			ĭ	j	,
B. Description of corner evide	nce found and/or metho	od applied in restoring	or reestablishing co	rner:					
(K10) Recovered the 1979 MDNR m the 1983 witnesses. The Spruce monument in place and made one (J9) Recovered the 1979 monumen and down. The cedars are in go and surveyor's tag #17618. I r proportional position between t section corner, which should ha monument at J9 as a careful and	NO6W has been cut do new witness as descrift t in good condition al od condition with part eviewed the notes of f he noted line tree and we been properly report	on. The remaining with the second below. Indicate the second bearing to the second bearing to the second s	itnesses are in goo and distance from overgrown blazes an and determined that owever, he misstate s east. I found i	d conditio the 1979 w d were fou he restor d the dist t to be 40	n with over itnesses. nd marked ed this co ance on t	The B.Sp with a ma orner at the	lazes. Druce SE Basuring the prop CRC to t	Left th is dea nail er he	ne
C. Description of monument for	r corner and accessorie	s established to perpe	etuate locating the po	_		Alberta.			
Remeasured the 1983 witnesses: 7° Balsam M54E 8.2' to nail 5° Balsam S44E 5.6' do 16° Spruce S41W 11.2' do Bearings are magnetic. Distanc nail with tag. Set sq'd cedar	set MDNR (measure 4S NBT" 6" 8.1 3" N.1 in side Exist: 5" Cec 8" Cec es are to Fd. sc post adjace	dar N18M 4.35° q'd and scribed ceda ent. Bearings are m	1, and set "1/4S N8T" do nd tag #17618 do r post agnetic.		STEPHA SZYSZK LAN SURVE No 339	OSKI D YOR	**	Mary Control	
adjacent Signed by	syphol. Dista	nces are to mail wit	h tag. Date	9	/3/0.	3			
Surveyor's Michigan License No	3398	6							_
y	·	-	_						