MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD

JOB NUMBER: 94030

SHEET NO. : 1-510	LAND COR	NER RECORDATION CERTIF	-ICATE	1994 DEC 28 PM 5:57	
	Filing Requ	irement of Act 74, Mich. P.A	\. 1970	1001 pro 50 14 2 21	
For corners in				Ω_{i}	
MARQUETTE	Located In:	Corner Code ##		Patricia A. Manley REGISTER OF DEEDS &	
(County)				REGISTER OF DEEDS AN	
	- A7N 27W	M-2		A OCCUS	
Public Land Survey	T 47N R 27W				
	T47N R 26W	(A-Z)-			
	fR				
	T R				
. Property Controlling	S			4. 120	
in Section	S T R		1.18	BER 1 PAGE 176	
. Miscellaneous	S T R		Register of D	eeds Stamp & File Number	
Property in Sec.	S R			1 *	
LalMa	Pageded Blot				
	, Recorded Plat		A B	CDEFGHIJKL	
, I HVate Otalilo			2	<u> </u>	
			3 L L		
CERTIN W CIRT.COM	in a field Bronder	1. December 20	4}	8 9 10 11 11	
	_ , in a field survey on Tuesday	A. of 1970, the corner points mentio	5	╿┈╏┈╏┈╏┈╏┈╏┈╏┈╏┈╏┈╏ ┈┦	
		.A. 01 1970, the corner points mentio and rules therefore as required in		17-1-16-15-14-1-1	
		eartment of the Interior, Bureau of L		 	
		ner points mentioned in lines 3, 4 ar			
oove were in conformance v	with the rules of the Michigan Boar	d of Land Surveyors or by a Decree	ola		
	re-established, monumented, re-	e-monumented, recovered, found	as		
xpressed below:	_		10 - 30-	1 29 1 28 27 26 1 2 6	
	corners, all in the same town	and range, may be recorded	11 -	┞╸╏┈╏┈╏┈╏╸╏ ┈┪ ╸╏	
on this certificate	e.		12 31-	32 33 34 35 30	
			13	<u> </u>	
 Description of original 	il monument and accessories a	and/or subsequent restoration:			
M-2: Bast 1/4 Corner	of Section 1.	PK mail in utiltiy po	ole N70W 36.99'		
1844: William A. Burt	's original survey notes descr	ibe the Hydrant valve nut	N20W 64.88'		
corner monument as a	post referenced by:	SW corner building	N25E 80.49'		
9" Cedar N73E 13	1	NW corner building	N85E 27.81'		
8" Fir N80W 6	1	Liber 4 RC, pg. 247			
1983: A Land Corner Re	ecordation Certificate filed b	y 1986: Certificate of	Survey recorded I	Liber 357 pg. 568	
Charles F. Clark RLS	No. 25836 indicates a 1 1/2" i	ron filed by Larry Busson	me RLS No. 25833	indicates the East	
pin under manhole cover witnessed by:		1/4 Corner of Section	1/4 Corner of Section 1, T47N-R27W as recorded in Liber		
		4, RC pg. 247. No co	mer accessories g	given.	
. Description of corner	evidence found and/or method	d applied in restoring or reestab	dishing corner		
·		ferenced in part "A" above. A	-	14-4 4- 43-	
	=	nt was place on top of the bolt		e contract of the contract of	
		2.38' Maas). Corner is in cent			
Jackson St. in the Cit				J. Boddin Ol	
.* ,					
The second	en e				
	j				
- 	\$ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\		R	ATIFIED BY PEER GROUP	
*			P.	.A. 345 OF 1990	
	· /			Lama Jousson	
الماء فيحالين	· · · · · · · · · · · · · · · · · · ·		<u>_</u>	ATE DU 19 1994	
			D.	AIE - COLOR	
Description of monum	ent for corner and accessories	established to perpetuate loca	ting the position	of the corner:	
•	,	e County Survey Monument stamp			
referenced by nail in:					
Power Pole		ft. Clark Accessory			
	t valve nut) N25W 64.72	•			
Southwest corner Senio	· · · · · · · · · · · · · · · · · · ·	ft. Clark Accessory			
	bldg. foundation N77E 27.80	• •			
	_	rete 0.95 below road surface.	Bearing tree +20	gs were	
	accessory but no sign post was			SE OF AUGUS	
Bk. 8, Pg. 57		•		6	
				· AT TA N TI	

Guald W Conlson

Surveyor's Michigan License No. 24589

GERALD W. **CARLSON**

SURVEYOR