JOB NUMBER: 95053 SHEET NO. : 1-628

APR 6 1 1996 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For	cornore	in	

MARQUETER

Corner Code # Located in:

1.	Public Land Survey	T47	N R ²⁶	N-13	
		T47	'N R ²⁵¹	V A-13	
		T46	N R ²⁶¹	γ M-1	
		746	N R ²⁵¹	N A-1	
2.	Property Controlling	S T	R		
	in Section	S T _	R		
3.	Miscellaneous	S T _	R		
	Property in Section	S T _	R	<u>.</u> .	

1 PACE 24 LIBER

Register of Deeds Stamp & File Number

4.	Lot No.	_ , Recorded Plat			
5.	Private Claims		 , ,		

Monday, November 27 , 19⁹⁵ _, in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

M-13: Section Corner common to Section 36, T47N-R26W Section 31, T47N-R25W; Section 1, T46N-R26W; and Section 6, T46N-R25W. 1844: William A. Burt's original survey notes describe the corner monument as a wood post without references.

A_	8	C D	E F	з	H !	J	K L
2	-6	 - 5			3	-2	
3		<u> </u>				-	igspace
4	-7—	 	-	1	0	 11	12-
5		 					ļļ
6	.18	. 17-	16	+٠	5	 -14	 13-
7	+		++			-	-
8	 19	-20-	2 <u>1</u>	2	2-	-23	—24-
9	+		++	-	-	+-	\vdash
10	30-	29-	28	2	7	-26	 25-
11		ļ					
12-) 31	 32-	33	 3	14	-35	36-
131	F	1	1 1	- 1		1	

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1995: Found and rejected a 3/4" diameter rod with a 1 1/4" square top, 4" above ground. Distance North is 2643.14', and Distance South is 5303.79'. The East-West position of this found iron checks well with existing irons. The North-South position does not fit the position of the D.N.R. corners 1 mile North and 1 mile South. The measured 2 mile distance from the S.E. Corner of Section 1, T46N-R26W to the N.E. Corner of Section 36, T47N-R26W, was 1.94' less than the D.N.R. in 1951. The corner was set at the proportional distance between the found corners 1 mile North and 1 mile South on line between the found 3/4 diameter rod and the found corner 1 mile North, 22.68 North of the found 3/4 Nor diameter rod.

RATIFIED BY PEER GROUP

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1995: Set a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument, flush with ground, and stamped to identify the corner. Referenced by double headed nails set in:

		_		-		-			
7 ⁿ	J. Pine							N11W,	38.63
7"	J. Pine							N67E,	38.93
7"	J. Pine							\$30W,	41.19
7 n	J. Pine							S66E,	29.60
Gre	en Steel	Sian	Post	w/Vallow	Curren	Marker	cian	Mont	1 01

Note: Found 3/4" bar was driven below ground on 11/27/95. Bearing trees all were face and butt blazed, painted, and had Bearing Tree Tags affixed.

Bk. 9. pp. 65-66.

Serold Wlarlan Surveyor's Michigan License No. 24589

Date[2-15-95

CARLSON **SLIRWEYOR** JAN

GERALD W.

No. REVISED NA

FORM APPROVED BY MICHIGAN STATE BOAR OF