LAND CORNER RECORDATION CERTIFICATE

Approved by Monomines One:	
Lond Survey Romanuseushills	Ď
Poer Group Mader Ant 345 G	ĺ
14/70	

Commence of the control of the contr	Filing Require	ment of Act 74, Mich. P.A.	1970	March
For corners in			***************************************	ALAED PREEDS
MENOMINEE Locat	ted in:	Corner Code #	Till the second	元元 元 (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)
(Country)			8	
•			Ž	
	N R 27W	(B-1) V	į́ni	87 C B
T 33	<i>Ν</i> R λγω	B-13 33/27		
<u>T</u>	<u>R</u>		En.	出来の書館
2 Promostiv Controlling C	<u>R</u>		če	So k & S
2. Property Controlling S T I	R		స్ట	" <u>2</u> 5" –
3. Miscellaneous S T			Pegister of Door	is Stamp & File Number
Property in Sec. S T			register of peer	is stamp & the Rumber
4. Lot No, Recorded Plat _				D E F G H I J K L M
5. Private Claims			¹ • • • • • • • • • 	
			2	5 4 3 2 1
			3	
I, WILLIAM LENCA	, in a field survey	on July 21 19 93 ,	4 7	3 9 10 17 72
do hereby certify that under requirements of P.i	A. 74, Michigan P.A.	of 1970, the corner points mentioned	5	
in lines 1 and 2 above were in conformance vacurrent manual of survey instructions of the Un	with regulations and ited States Departm	rules inererore as required in the	6 18 1	7 16 15 14 13
Management or by a decree of a Court of Law a	ind/or that the corner	points mentioned in lines 3, 4 and 5	7	
above were in conformance with the rules of the	e Michigan Board of	Land Surveyors or by a Decree of a	1 1	0 21 22 23 24
Court of Law; established, re-established, expressed below:	monumented, re-m	onumented, recovered, found as		J 21 22 25 24
		•	9	
NOTE: Not more than 4 corners, all in	the same town ar	d range, may be recorded	I -:- I ***	9 28 27 26 25
on this certificate.			11	
A. Description of original monument a	and nonconving o	od/or outpossuppt restoration.		2 33 34 35 36
ORIGINAL B.T.'s: Tamarack, 18"	', N30 ⁰ E, 14 1ks	toror subsequent restoration:	33	
Cedar, 6", N4	15 ⁰ W 10 1k		•	•
Original Survey by James H. Mul	lett in 1848.			·
				· .
,				,
				:
				•
		·		,
B. Description of corner evidence four	nd and/or method	applied in restoring or reestabli	shing corner:	:
I had set a 1/2 inch diameter I	ron Rod. 18 inc	hes long in a August 1981	survey The Troi	has been
destroyed, but the corner posit	ion was re-esta	blished from 4 bearing tree	s which I had man	ked in
1981. The corner was set in li this position. The East-West p				
the Northeast Corner (C-1) and	the East 1/16 f	ence. This position checks	ed with a GLO Term	rain call to
a well defined 14 foot high rid		t. This corner is accepted	l as the best avai	lable evidence
of the position of the original	. corner.			1
		•		<u>}</u>
				l,
		•		
				f
C. Description of monument for corne	r and accessories	established to perpetuate local	ting the position of	the corner:
Set Berntsen Drivable F-130 Alu	minum Monument	stamped for corner:		COOLER OF MICH.
6" dia. Spruce	N48°E	17.17 feet	-	A TANK THE TOTAL OF THE TOTAL O
5° dia. Tamarack 6° dia. Cedar	s20 ⁰ e s50 ⁰ w	24.30 feet		A WILLIAM A
6" dia. White Birch	850°W N43 ⁰ W	25.08 feet 11.33 feet		# LENCA + B
Metal Survey Sign Post	North	0.75 feet		E LAND SE
		•		No.
	_			26461
NOTE: All bearings are magneti All distances to trees a		l distances are measured wi nails in side of tree.	th steel tape.	The sun of the
*				ENIS FAIR
Signed by Ce) Winn Long		Date Dece	mber 27, 1993	:
-		Date Dece	MUCI 21, 1993	
Surveyor's Michigan License No. 2640	61	50	RM APPROVED BY MICHIGAN STA	ITE BOARD OF LAND SURVEYORS, JAN. 28, 1871