SURVEY & REMONUMENTATION

APR 1 1 1995 LAND CORNER RECORDATION CERTIFICATE COMMISSIONINg Requirement of Act 74, Mich. P.A. 1970 For corners in MENOMINEE Located In: Corner Code ## (County) _32N R __27W Public Land Survey ____ R ____ R ___ R __ **Property Controlling** ____ T ____ R _ in Section \$ ____ T ___ R ___ Miscellaneous Register of Deeds Stamp & File Number Property in Sec. _ , Recorded Plat _ Private Claims William Lenca May 17 in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 10 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 11 on this certificate. Description of original monument and accessories and/or subsequent restoration: 1847: Original Survey by James H. Mullett - B.T.'s - Cedar, 8", N37°W, 14 lks; Cedar, 6", S14°E, 18 lks. All original evidence for this corner has been destroyed by Highway Construction. Menominee Industrial Park No. 1 by Marvin Van Eyck, RLS No. 8102, shows this corner as it relates to other monument s 1980 within the plat. The corner is described as being in the center of Highway 41. The corner monument is not described. Certified Survey No. 427 by George B. Wilson, RLS No. 17607, indicates that this corner was used to establish the C1/4 1985: corner. It also shows measurements relating this corner to other corners in the survey. L.C.R.C. No. 916 by Brian Taavola, RLS No. 21583, states "Found 5/8" iron pin in Monument Box 0.35' East of US-41 C/L @ Sta. 1175+66 & intersection 56th Ave. TIES: NW Cor. Porch - N70°E - 82.95'; P.P. #47 - S45°E - 45.95'; Tel. Box -S60°W - 41.99'; Sign Pole - N85°W - 79.90'. Description of corner evidence found and/or method applied in restoring or reestablishing corner: We found a 5/8" diameter iron rod in a Monument Box and 4 Ties as described in L.C.R.C. No. 916. The corner falls in the centerline of 56th Avenue running West from this location and 0.35' East of the North - South centerline seam of U.S. Highway 41. This corner has been used in a large number of surveys, and is accepted as the best available evidence of the position of the original corner. LENCA SURVEYOR ERED LAND C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 3-1/4" dia. Alum. cap stamped for corner on existing 5/8" dia. Iron Rod in Monument Box: N70°W 82.95 feet S270E @5" W. Ash 5/8" x 24" Iron Rod/2" Alum. cap marked WITNESS MARKER 136.82 feet 5/8" x 24" Iron Rod/2" Alum. cap marked WITNESS MARKER S590W 87.23 feet @ Survey Sign N350W 4" dia. Concrete Monument 118.73 feet Survey Sign Post 87.4 feet NOTE: All bearings are magnetic bearings. All distances are measured with steel tape.

Signed by William Jone Date

Surveyor's Michigan License No. ______26461_

Dec. 15, 1994