LAND CORNER RECORDATION CERTIFICATE Act 345 OF Filing Requirement of Act 74, Mich. P.A. 1970 199 96 For corners in MENOMINEE Corner Code # Located In: (County) 1. Public Land Survey A06 \odot BK 3 7.7 2. Property Controlling ÇΩ in Section (კ) დე 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number , Recorded Plat 4. Lot No. 5. Private Claims SAME AS CORNER M-06 T33N-R28W I. <u>William Lenca</u>, in a field survey on <u>Jun. 27</u>, 19 <u>96</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: 3 NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration; Original Survey (Twp Bdy) by James H. Mullett - B.T.'s - Hemlock, 10" - N200W - 08 lks; Fir, 8" - N630E - 17 lks. All original evidence for this corner has been destroyed by county road improvements. Certified Survey No. 595, Book 4, recorded by William Lenca, RLS No. 26461, shows this corner as it relates to other 1988: corners in Section 13, T33N-R28W. Our field notes from this survey indicate that a 60d nail was found in an old wood post 4.5 fect East of the center of a N-S County Road and in line with an old fence running East. B.T.'s - Power Pole - S870E -36.52'; Cedar, 8" - S48°W - 55.47'; W. Ash, 6" - N45°W - 63.85'. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: We found a 5/8 inch diameter iron rod 24 inches long driven into an old wood post along with the 3 witnesses noted in part "A" above. The corner fails 4.5 feet East of the centerline of a North - South County Road and in line with an old fence line running East. Measurements to corners North and South of this position fit reasonbly well with GLO record distances. We accepted the location of the old wood post as the best available evidence of the position of the original corner. L OF MICHERA WILLIAM LENCA LAND SURVEYOR TIPED LIND C. Description of monument for corner and accessories established to perpetuate locating the position of the corner Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box: 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 23.41 fcct Scr. NBT S480W 55.47 feet 8" dia. Cedar N45°W 63.85 feet Scr. NBT 6" dia. White Ash East 24.2 fcet

Metal Survey Sign Post

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

$\sim 1 \omega$,	Nov. 18, 1996
Signed by William J	mis	Date
Surveyor's Michigan License No	26461	

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 19 REVISED MAY 14,19 REVISED JAN., 19 REVISED DCT., 19