		•	•		127.00	990 04	/÷"/	153 <del></del>	
	LAND C	ORNER RI	FCORDATIO	N CERTIFICAT	[F	11.11.1	auxi	1915	_
				lich. P.A. 1970		Chah			
For corners in		.oquiioiiioi			•	;			
MENOMINEE							<u>:::</u>	• • •	
	Located In:	Corner Co	ode#			10.014	Ξ"	77	
(County)						100	22		
1. Public Land Survey	. <del>1</del> 2N ⊳28W	7	M-1				150	• •	
1. Public Latte Servey	T3140.21	( <u>)</u>	D			18			
•	T23 J R 2-7	TW T	1.735/				777		
	723 / R2 8		W-13			- パード	(4)		
2. Property Controlling	S T R		<del></del>	Ì		- 19 G		.3	
in Section	S T R						12)		
3. Miscellaneous	S TR			<b>→</b>					
Property in Sec.	S TR			ı)	Register	of Deeds Si	amn &	File Nur	aber
			/sex. 1			d, beedb			
		(		1 12	? }				
4. Lot No, Record	led Plat			(_ A 15	Авс	D E F 6	; II	ı j ĸ	ь <u>н</u>
5. Private Claims					المالي				Q
SAME AS CORNERS M-	13, T33N-R28W; A-13,	T33N-R27\	N;∕M-1, Т32N-	1279/	2 6	·\$─ <del> </del> ─∳─	3	-	<del>  </del>
•					3	-	<del> </del>	╢	
I, William Lenca	In a field survey onM	lar. 24	97 do hereby s	late that under	4	- 6		1 <sup>1</sup>	12
requirements of P.A. 74, Michigan	P.A. of 1970, the corner po	ints mentione	din lines 1 and 2	abov <del>a</del> wera in	5	_ _ _			
conformance with regulations and a				rucions of the	, [				
United States Department of the in that the corner points mentioned in					619	-1716	15	<u> </u>	-13
Board of Land Surveyors or by					7	-  -		- -	
recovered, found as expressed bek	W;			•	019	-2021	-22-	z's	-24
NOTE: Not more than 2 come	um all in the éame tour an	diana mas	ha racovilad		- اا و	_ _		}	
on this certificate.	28' 90 KI (1)0 SQUIC ROALI QU	iu iango, may	DG 10COVGCG	1	10 30 -	-2920	27-	26	25
Off this Certificate.						<u> </u>			_[_]
				3	"				
				. 1	2 3  -	-32	J4 		-36
				•	13	<del></del>	LI		لـــــــــــــــــــــــــــــــــــــ
A Description of original mon			-						
	by John Mullett - B.T.'s corner was recovered.	- Cedar, 10	* - N48 <sup>0</sup> E - 33	iks.; Ccdar, 10"	' - NG0 <sup>0</sup> W	- 30 lks. No	origin	al	
		•							
		:		•					
		1 4							
B. Description of corner evide	ence found and/or metho	d applied in i	estoring or rees	tablishing corner	:				
This corner was re-establis N1/4 Corner (B-1) of Secti	ion 6, T32N-R27W for E	last - West i	position, and be	(ween the E1/4)	Corner (M	-12) of Secti	on 36, '	T33N-	c
R28W and the W1/4 Corne	er (A-4) of Section 7, T3	12N-R27W I	for North - Sou	th position, and	is accepted	l as a careful	and fa	ithful	
reestablishment of the posi	tion of the original corn	er. The cor	ner falls in a ta	marack and spre	uce swamp	- flicre is no	occupa	itional	
evidence in this area.									
							الكنتالك	and the	₹.\
		·.		c	(1b		Mark.		6, 6
C. Description of monument for					on or the co	inici. //*	W	MALLI	I
Set 2" dia. Aluminum Pipe	√3-1/4* dia. Alum cap s	lamped for o	corner location:		•	<b>*</b>	•	KNICA LAMO	
6" dia. Ccdar		N560E	22.99 fcct	Scr. NBT		IJ.		No. Kararosi	1.1
7" dia. Tamarack		S200E	8.58 fcct	Scr. NBT		4/3	•	\$6001	: X/
10" dia. Tamarack		Mo80M	27.74 feet	Scr. NBT		J.	\$7.	••••••	Chi. Top
7" dia. Tamarack	•	NO2 <sup>o</sup> €	24.11 fect	Scr. NBT		`	**************************************	I LAND	i i i i i i i i i i i i i i i i i i i
Metal Survey Sign Post	Ĺ	North	1.0 feet				~4	MUM	
NOTE: All bearings are a	ragnetic bearings. All d	istances are	measured with	steel tape. Dist	lances to tr	ces are to na	il in sid	le of tree	
10 1 12	70.00			_ Anr	08, 1997				
Signed by	17 04016	·- ·-		Date				<del></del>	
Surveyor's Michigan License N	0								
								)	
									404-