SURVEY & REMONUMENTATION

JAN 0 9 2001

S	F	C	П	\bigcirc	٨
100		\smile	1 1		

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County Land Survey Remonumentation Peer Group Under Act 345 of PA. Of 1990 On 42 22 20							
MEC ANNI DES Chairman							
Bk 6 Pg. 240							
RECEIVED FOR RECORD 28 DEC 2000 2:31:31 PM BARBARA MORRISON REGISTER OF DEEDS MENOMINEE. MI 49858							
Register of Deeds Stamp & File Number							
B C D E F G H I J K L -6 -5 -4 -3 -2 -1 -7 -8 -9 -10 -11 -12 -18 -17 -16 -15 -14 -13 -19 -20 -21 -22 -23 -24 -30 -29 -28 -27 -26 -25 -31 -32 -33 -34 -35 -36 k, 7" - N25°W -9 lks.; Tamarack							
has been destroyed by County Road aluminum cap from blazed tam. stub has definite hack marks and is							
; 6" - NW - 18.0') in place per sh and dead cedar trees in lake bog nent as a careful and faithful							
f the corner: WILLIAM LENCA LAMD SURVEYOR NO. 26461							
es to trees are to nail in side of tree.							

rot corners in		
MENOMINEE	Located in:	Corner Code #
(County)		Some Sugar
1. Public Land Survey	T <u>35</u> NR TR TR TR	
Property Controlling in Section Miscellaneous Property in Sec.	S TR S TR S TR S TR	

4. Lot No. _, Recorded Plat 5. Private Claims 1 SAME AS CORNER I-1, T34N-R26W 2

William Lenca in a field survey on <u>Dec.</u> , $19\underline{00}$ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
 - 1848: Original Survey by James H. Mullett - B.T.'s - Tamarack, 5" - N550E - 7 lks.; Tamarack 8", S75°W, 7 lks.; Tamarack 8", S57°E, 18 lks. All original evidence for this corner h improvements.
 - 1975: L.C.R.C. No. 119, Book 1, by David B. Babbitt, RLS No., 21558 states "Set 1" pipe, 4" a for S.E. g.l.o. wit. line Tree south at 11.77 chs. g.l.o. notes say L.T. was at 13.90 but th the right size etc." TIES: Cedar 6", NW, 18.0'; Cedar 7", West 25.4'.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a 1 inch diameter iron pipe with 4 inch diameter aluminum cap and 1 B.T. (Cedar L.C.R.C. No. 119, Book 1 (see part A). The other B.T. is down. This entire area consists of brus and marsh. Since this corner was re-set from original evidence, we accepted the existing monum perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of

Accepted Existing 1" dia. Iron Pipe/4" Alum. Cap stamped for corner location.

6" dia. Cedar (dead) - Ex. B.T. - Set new nail 6" dia. Cedar (dead)

N23°W 18.00 feet S87°W 43.42 feet

Scr NBT Scr. NBT

3

5

6

7

8

9

10

13L

Metal Survey Sign Post

101/12:

East 1.0 feet

Nothing else nearby, all dead cedar swamp & bog

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distance

240

Signed by 12 Malan tayan	Date
Surveyor's Michigan License No	