						Land Survey Remonumentation Pair Group Under Act 345 Of						
		I AND COE	RNER RECO	ים ואחודאתם	EDTIEICATE	P.A. O	f 1990 Oc	121	20		, 199 🕏	15
			uirement of			_//	Re s	me	11	20	S	•
Fo	or corners in	rining neq	unement of	MCC 74, MIC	II. P.M. 1370		, in the second	- ¿Ch	ai rlosaj o			
	MENOMINEE	Located In:	Corn	er Code <i>::</i> ∔#	-	· · · · · · · · · · · · · · · · · · ·	三 <u>二</u>	ルm ルギ とっ・) <u>30</u>	RECEIVE		_
		34N 27		K-12			13.37	778	27	ר דייי		
١.	Public Land Survey	TR							·O	S		
	*	TR			.		100 100 100		. ω			
2.	Property Controlling	T R S T R					က်ပာ	150 17 17 17	: 30			
	in Section	S T R			.							
3.	Miscellaneous Property in Sec.	S T R S T R			Regist	er of De	eds St	amp	& File	Nur	nber	
4.	Lot No	Recorded Plat				а в (S.D. E	F	с н	1 .	ı K	ı.
5.	Private Claims			· — 				$\overline{}$	ĬŢ	Ť	ŢΤ	Ť
							- 5		3-			
	William Lenca	., in a lield survey on	Jun. 19		95		-8	-9-	-10-		1	-12
do	hereby certify that under re	equirements of P.A. 74, Michigan P in conformance with regulations	.A. of 1970, the	corner points m	entioned a		_17	-16	15		4	-13
ÇU	rrent manual of survey inst-	ructions of the United States Dep	partment of the	Interior, Burea	u of Land 7	-				╂╾┨		+
		f a Court of Law and/or that the cou ith the rules of the Michigan Boar				19	-20	_2'1 	2'2 	1-2	3	-24
	urt of Law, established, pressed below:	re-established, monumented, re-	e-monumented	, recovered, f	ound as		-29	-28	-27		5	-25

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

on this certificate.

- Original Survey by James H. Mullett B.T.'s Cedar, 10" S13°W 17 lks; Hemlock, 14" N40°E 14 lks. All original 1848: evidence for this corner has been destroyed by county road improvements.
- 1981: Certified Survey No. 215 recorded by William Lenea, RLS No. 26461, shows this corner in relation to other corners in Sections 35 and 36. The corner is shown as being at a single proportionate position. No corner monument or ties see were established.
- 1982: Certified Survey No. 303 recorded by George B. Wilson, RLS No. 17607, shows this corner in relation to other corners in Section 35. The corner is shown as being at a single proportionate position. The corner monument is not described and no ties are given.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

In a 1995 survey in Section 36, T34N-R27W, we recovered the NW and SW Corners of said section and measured the distance between them. We found that this distance matched with the recorded distance shown in Certified Surveys 215 and 303. We established the single proportioned position and searched this area. We found no corner monument or occupation which would indicate a corner position. We therefore established the corner at the single proportionate position as shown in Certified Surveys 215 and 303, and accepted this location as a careful and faithful reestablishment of the position of the original corner,

C. Description of monument for corner and accessories established to perpetuate locating the position of the c Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum, cap stamped for corner location:

		S360E	64.58 fcct	Scr. NBT
¥.,		S23°E	56.83 feet	
	3.	S68°W	27.48 feet	Scr. NBT
		N21°W	54,67 fcct	Scr. NBT
		S71°E	34,0 feet	
			S23 ^o E S68 ^o W N21 ^o W	S23°E 56.83 feet S68°W 27.48 feet N21°W 54.67 feet

NOTE: All bearings are magnetic bearings. All distances are measured with a steel tape. Distances to trees are to nail in side of tree.

(2) (2)	Nov. 04, 1995
Signed by William Bridge	Date
Surveyor's Michigan License No. 26461	
Sulveyors wichigan License No.	FORM APPROVED BY MICHIGAN STATE BUARD OF LAND SURVEYORS, JAN. 28.