LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

	FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
	1. PUBLIC LAND SURVEY	T. 35 S., R. 25 W.	I-10, I-11	
	2. PROPERTY CONTROLL- ING IN SECTION———	N. E. W. W.		
	3. MISCELLANEOUS PROPERTY IN SECTION			
	4. LOT NO , RECO	ORDED PLAT		
	5. PRIVATE CLAIMS	· · · · · · · · · · · · · · · · · · ·		REGISTER OF DEEDS STAMP AND FILING NUMBER
	the corner points mentioned in field survey on October 8 restored as expressed below a of survey instructions of the U court of law. Furthermore,	1 lines 1 and 2 above (identified in conformance with regularited States Department of that the corner points may found, recovered, restored, rest	ntified with circles on index d, re-established, monumente ulations and rules therefore a the Interior, Bureau of Land centioned in lines 3, 4 and 5 established or re-established	P.A.74, Michigan P.A. of 1970, code diagram — over) were, in a ed, re-monumented, recovered or s required in the current manual Management or by a decree of a above were, in a field survey on as expressed below and in contra or, by a Decree of a Court of
	A. Description of original mon		-	•
I - 10	East & corner, Section 27; Wood Post, Cedar 14 - N8°W - 21 lks.; Fir 10 - S39°W - 18 lks			
I - 11	S.E. section corner - 5" Cedar - N17°E - 30. Old Wells State Park m monument; 6" Cedar - N 38.0'.	06'; 5" Cedar - 836 ⁰ ap (1935) R.R. spike	W - 17.75'; T. Pole - in centerline of road	S13°E - 9.05'. I replaced by standard
I -1 0	B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Set M.P.O.L. between the N.E. and S.E. section corners of Sec. 27. No sign of O.B.T.'s Old park boundary posts are in an old telephone line about 45 ft. west but no record of them having been set by survey and no other support for other than a straight line.			
	Found 1" pipe beside broken concrete monument buried in the centerline of an old E-W road grade. Blased 6" Cedar with a nail and roofing cap is \$36°W - 17.75° and a down cedar blased and with a nail and roofing cap - N17°E - 30.06° for two M.D.S.H. witnesses. Also found remains of the double cedar Wells Park witness - N45°W - 38°. Set a new DNR monument in a concrete cylindar 3" in diameter and buried the old monument & pipe beside C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 1" pipe, 4" aluminum cap; 5" Cedar - N38°W - 16.9°; 10" Cedar - \$87°E - 10.9°; 9" Cedar - \$11°W - 7.8°; 18" Y. Birch - \$53°W - 5.9°.			
I-11	1" pine, 4" aluminum c S35°W - 17.5'; 9" Bl.	ap in concrete 3" di Ash - N12°E - 32.2';	ameter; 13" W. Pine - 8" Cedar - N23°E - 30	S67°E - 75.5°; 6" Cedar -
	SIGNED BY		DATE .	e demonstrative makes () is the large of th
	SURVEYOR'S MICHIGAN REC	SISTRATION NO		(SEAL)
	FOR STATE AND UNITED ST	ATES AGENCIES:		
	SIGNED BY		DATE	
	APPROVED AND SIGNED BY.	Chief of SURVEY PARTY A. A.	elist nor	1-26-81
	ALEROVED AND SIGNED DI.	MICHIGAN REGISTERED L	AND SURVEYOR	(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558 FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971 DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS Form No. ML M736 DDUBLEPAY BROS. & CO., KALAMAZOO, MICH.