Land Survey Remonumentation	
Poer Group Under, Act 345 01	
12/21	

SECTION

Filing Requirement of Act 74, Mich. P.A. 19	70
MENOMINEE Located in: Corner Code #	Hada 9
(County) -35N - 25W L-07	TOUVED
Public Land Survey T SN R 25W L-07	
T_R	
Property Controlling ST_R	(nai2) *
in Section S TR	858 808 10 Str. 0 14 O Str. 0 14 O Str. 0
Miscellaneous ST_R	4 On
Property in Sec. S TR	Register of Deeds Stamp & File Number
Lot No, Recorded Plat	ABCDEFGHIJKL
	2 - 6 5 4 3 2 1 -
71.11	3
William Lenca in a field survey on July 14 19 do hereby state that under	4 - 7 - 6 - 9 - 10 - 11 - 12 -
julierments of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in nformance with regulations and rules therefore as required in the current manual of survey instructions of the	5
ited States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for	6 -18 -17 -16 -15 -14 -13
it the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan and of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,	7
overed, found as expressed below:	8 19 20 21 22 23 24
OTE: Not more than 2 corners, all in the same town and range, may be recorded	9
OTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	10 30 29 28 27 26 25
	11
	12 31 32 33 34 35 36
1986年 · 基督 · 医脑囊 · 医脑囊 · 、精致 · 1980年 · 日本 · 1980年 · 1	13
Description of original monument and accessories and/or subsequent restoration:	
1848: Original Survey by James H. Mullett - B.T.'s - Birch, 6" - N63°W - 29 lks; Cedar evidence for this corner has been destroyed by logging activities and county road	improvements.
1958: Plat of Survey by Robert Olsen shows this corner as it relates to other corners in corner monument is described as "Steel Rod". No witnesses are given.	30V. Lat 4, Sec. 15, 15511-165 W. The
1970: Plat of Survey by George B. Wilson, RLS No. 17607, shows this corner as it related	es to other corners in Section 13, T35N-
D25W and describes it as "found nin" No B T's are given.	
1991: L.C.R.C. No. 928 recorded by William Lenca, RLS No. 26461, states "Found 5/8 several old survey maps. B.T.'s: 16" Cedar - N66°E - 10.17; 5" Cedar - S14°W Cedar - N16°E - 11.80'.	" dia. Iron Rod in location indicated on -7.44'; 10" Cedar - N76°W - 7.57'; 20"
Description of corner evidence found and/or method applied in restoring or reestablishing cor	ner:
We recovered a 5/8 inch diameter iron rod as described in L.C.R.C. No. 928 (see part A) a county road centerlines East and South. This position fits with measurements to corners s	hown in Robert Olsen's 1958 survey and
with those shown in George Wilson's 1970 survey. This corner position has been used by	local surveyors for at least 39 years, and is
accepted as the best available evidence of the position of the original corner.	
	01 110
	STATE OF THE STATE
Description of monument for corner and accessories established to perpetuate locating the po	sition of the corner LENCA
Set 2" dia. Aluminum Pipe 30" long/3-1/4" dia. Alum cap stamped for corner location:	# BURVEYOR #
16" dia. Cedar N66°E 10.17 feet Scr. NBT	
5" dia, Cedar S14°W 7.44 feet Scr. NBT	SOUTH AND THE STATE OF THE STAT
10" dia. Cedar N76°W 7.57 feet Scr. NB1 20" dia Cedar N16°E 11.80 feet Scr. NB7	
20" dia. Cedar N16°E 11.80 feet Scr. N13' Metal Survey Sign Post West 1.15 feet	•
NOTE: All bearings are magnetic bearings. All distances are measured with steel tape.	Distances to trees are to nail in side of tree.
19/201 -	uly 18, 1997
gned by Ll Many Faces Date	
and the second s	