## LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Maria de la Companya de la Companya

10

FUK C	CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	MENOMINEE
1. PU	BLIC LAND SURVEY	36 T. 35 N. R. 26 E		, co.
2. PR	OPERTY CONTROLL-	36 ,T. 35 N. R. 26 E	1, 3	
		,T N. E E., R W		
	T NO, R			
5. PR	IVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
field resto of su cours	corner points mentione survey on Februar ored as expressed belowerey instructions of the corner of t	ed in lines 1 and 2 above (id y 26 1976, establish w and in conformance with rethe United States Department of the corner points	entified with circles on index ed, re-established, monument gulations and rules therefore a fine interior, Bureau of Land mentioned in lines 3,4 and 5 established or re-established	P.A.74, Michigan P.A. of 1970, code diagram—over) were, in a ed, re-monumented, recovered or as required in the current manual Management or by a decree of a above were, in a field survey on as expressed below and in conters or, by a Decree of a Court of
law:				
A. I L-11	Description of original North % corner; V	monument and accessories an lood post - Tam. 6 - N	d/or subsequent restoration: 14°E - 18 lks.; spruce	4 - S34°W - 17 1ks.
		orth Section line.		
3 1	N 1/16 cor. on we	est Section line.		
L-11 8	Set M.P.O.L. betw Set M.P.O.L. betw	veen section corners 첫 veen the N눅 corner and	applied in restoring or re-esta mile east and is mile the N.W. section corner and the N.W. section (	er
L-11	Description of monumed in pipe with 4" of 5" spruce - N750	aluminum cap; 7" spruc	s established to perpetuate lo e - N40°W - 15.3°; 6°°	cating the position of the corner: spruce - S45°W - 12.6°;
1	1" pipe with 4" a	aluminum cap; 8" yello 25.1 feet	w birch - S26°E - 40.8	feet; 10" white
3	1" pipe with 4".	aluminum cap; 4" cedar	- N24°E - 12.9'; 6" c	edar - S54°E - 20.65'.
		•	•	
			DATE	
			DATE	(SEAL)
			,	
	,	D STATES AGENCIES:		
		CHIEF OF BURYEY FARTY	1/ V	