## LAND CORNER RECORDATION CERTIFICATE

1.4...

. .

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

	LOCATED IN-:	CORNER CODE NUMBER	MAKAM AN WINE
1. PUBLIC LAND SURVEY 34	T. 35 N. R. 26 W.	I_11, G_11, I_13	MEND MANUEL
2. PROPERTY CONTROLL- ING IN SECTION	N. R. E. W		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
3. MISCELLANEOUS PROPERTY IN SECTION			
4. LOT NO, RECO	RDED PLAT		
5. PRIVATE CLAIMS			
, David Babbitt	•		REGISTER OF DEEDS STAMP AND FILING NUMBER
restored as expressed below and of survey instructions of the Un court of law. Furthermore.	d in conformance with regulited States Department of that the corner points me	, re-established, monumer lations and rules therefore the Interior, Bureau of Lan	of P.A. 74, Michigan P.A. of 1970 ex code diagram – over) were, in a need, re-monumented, recovered of as required in the current manual distance of a babove were, in a field survey of
			) above were, in a field survey or d as expressed below and in con- yors or, by a Decree of a Court o
law:	Sound of Me	gistration for Land Survey	ors or, by a Decree of a Court o
A. Description of original monun	ment and accessories and/	or subsequent recornia.	
TTT N.E. Sec. Cor	G-11 N.W. Sec. C		
Wood Post Pam 6-S63°W - 14 1ks. Pam 6-N63°E - 22 1ks.	Wood Post		I-13 S.E. Cor.
Cam 6-N63°E - 22 1ks.	Hem. 12 N42 E - 1:	2 lks. 18 lks.	Wood Post Tam 5-N55°E 07 lks.
,	cedar 10 S13 E - :	18 1ks.	Tam $7-N25^{\circ}W$ 09 lks.
	•		Tam 8-S75 W 07 lks.
B. Description of garage and an	e found and/or method appl	ied in restoring or re-esta	Tam 8-S75 W 07 lks. Tam 8-S57 E 18 lks.
B. Description of corner evidence- ll Set from 8" tam. stub ith definite blaze (No cribe marks visible) for .F. o.b.t stump remains n place for S.W. obb + bu	fences south a in line with c roads north an	ied in restoring or re-estatione with I-1 and east and for enterline Tred west not but	Tam 8-S75 W 07 lks. Tam 8-S57 E 18 lks.  blishing corner:  3 Set from blazed tam st S.E. g.l.o. wit. line. e south at 11.77 chs. g.l es say l.t. was at 13.90 this has definite hack ks and is the right size
B. Description of corner evidence11 Set from 8" tam. stub ith definite blaze (No cribe marks visible) for .F. o.b.t stump remains n place for S.W. o.b.t. but lmost completely rotted away	fences south a in line with c roads north an	ied in restoring or re-estatine with I-1 and east and for enterline Tred west not but markets	Tam 8-S75 W 07 lks. Tam 8-S57 E 18 lks.  blishing corner:  3 Set from blazed tam st S.E. g.l.o. wit. line. e south at 11.77 chs. g.l es say l.t. was at 13.90 this has definite hack ks and is the right size
B. Description of corner evidence11 Set from 8" tam. stub ith definite blaze (No cribe marks visible) for .E. o.b.t stump remains n place for S.W. o.b.t. but lmost completely rotted away  C. Description of monument for cell 1" pipe, 4" aluminum of	fences south a in line with c roads north an t ay	ied in restoring or re-estatine with I-1 ind east and for enterline Tre d west not but mark etc	Tam 8-S75 W 07 lks. Tam 8-S57 E 18 lks.  blishing corner:  3 Set from blazed tam st S.E. g.l.o. wit. line. e south at 11.77 chs. g.l es say l.t. was at 13.90 this has definite hack ks and is the right size  ating the position of the corner:
B. Description of corner evidence11 Set from 8" tam. stub ith definite blaze (No cribe marks visible) for .E. o.b.t stump remains n place for S.W. o.b.t. but lmost completely rotted away  C. Description of monument for cell 1" pipe, 4" aluminum of	fences south a in line with c roads north an t ay	ied in restoring or re-estatine with I-1 ind east and for enterline Tre d west not but mark etc	Tam 8-S75 W 07 lks.  Tam 8-S57 E 18 lks.  blishing corner:  3 Set from blazed tam st S.E. g.l.o. wit. line. e south at 11.77 chs. g.l es say l.t. was at 13.90  this has definite hack ks and is the right size  ating the position of the corner:  I-13 1" pipe, 4"  aluminum cap
B. Description of corner evidence11 Set from 8" tam. stub ith definite blaze (No cribe marks visible) for .E. o.b.t stump remains n place for S.W. o.b.t. but lmost completely rotted away  C. Description of monument for cell 1" pipe, 4" aluminum of	fences south a in line with c roads north an t ay  corner and accessories est cap G-11 1" pipe 10" cedar N15 5" cedar N72	ied in restoring or re-estatine with I-1 ind east and for enterline Tred west not but mark etc  ablished to perpetuate loce 4" aluminum cap  5 W 41.0'	Tam 8-S75 W 07 lks.  Tam 8-S57 E 18 lks.  blishing corner:  3 Set from blazed tam st S.E. g.l.o. wit. line. e south at 11.77 chs. g.l es say l.t. was at 13.90  this has definite hack ks and is the right size  ating the position of the corner:  I-13 1" pipe, 4"  aluminum cap 6" cedar NW 18.0"
B. Description of corner evidence— 11 Set from 8" tam. stub ith definite blaze (No cribe marks visible) for .F. o.b.t stump remains a place for S.W. o.b.t. but lmost completely rotted away  C. Description of monument for ce -11 1" pipe, 4" aluminum of	fences south a in line with c roads north an t ay  corner and accessories est cap G-11 1" pipe 10" cedar N15 5" cedar N72	ied in restoring or re-estatine with I-1 ind east and for enterline Tre d west not but mark etc	Tam 8-S75 W 07 lks.  Tam 8-S57 E 18 lks.  blishing corner:  3 Set from blazed tam st S.E. g.l.o. wit. line. e south at 11.77 chs. g.l es say l.t. was at 13.90  this has definite hack ks and is the right size  ating the position of the corner:  I-13 1" pipe, 4" aluminum cap
B. Description of corner evidence— 11 Set from 8" tam. stub ith definite blaze (No cribe marks visible) for .F. o.b.t stump remains n place for S.W. o.b.t. but lmost completely rotted away  C. Description of monument for ce -11 1" pipe, 4" aluminum of	fences south a in line with c roads north an t ay  corner and accessories est cap G-11 1" pipe 10" cedar N15 5" cedar N72	ied in restoring or re-estatine with I-1 ind east and for enterline Tred west not but mark etc  ablished to perpetuate loce 4" aluminum cap  5 W 41.0'	Tam 8-S75 W 07 lks. Tam 8-S76 E 18 lks.  blishing corner:  3 Set from blazed tam st S.E. g.l.o. wit. line. e south at 11.77 chs. g.l es say l.t. was at 13.90  this has definite hack ks and is the right size  ating the position of the corner: I-13 1" pipe, 4" aluminum cap 6" cedar NW 18.0"
B. Description of corner evidence— 11 Set from 8" tam. stub ith definite blaze (No cribe marks visible) for .F. o.b.t stump remains a place for S.W. o.b.t. but lmost completely rotted away  C. Description of monument for ce -11 1" pipe, 4" aluminum of	fences south a in line with c roads north an t ay  corner and accessories est cap G-11 1" pipe 10" cedar N15 5" cedar N72	ied in restoring or re-estatine with I-1 ind east and for enterline Tred west not but mark etc  ablished to perpetuate loce 4" aluminum cap  5 W 41.0'	Tam 8-S75 W 07 lks. Tam 8-S76 E 18 lks.  blishing corner:  3 Set from blazed tam st S.E. g.l.o. wit. line. e south at 11.77 chs. g.l es say l.t. was at 13.90  this has definite hack ks and is the right size  ating the position of the corner: I-13 1" pipe, 4" aluminum cap 6" cedar NW 18.0"
B. Description of corner evidence— 11 Set from 8" tam. stub ith definite blaze (No cribe marks visible) for .F. o.b.t stump remains n place for S.W. o.b.t. but lmost completely rotted away  C. Description of monument for ce -11 1" pipe, 4" aluminum of	fences south a in line with c roads north an t ay  corner and accessories est cap G-11 1" pipe 10" cedar N15 5" cedar N72	ied in restoring or re-estatine with I-1 ind east and for enterline Tred west not but mark etc  ablished to perpetuate loce 4" aluminum cap  5 W 41.0'	Tam 8-S75 W 07 lks. Tam 8-S76 E 18 lks.  blishing corner:  3 Set from blazed tam st S.E. g.l.o. wit. line. e south at 11.77 chs. g.l es say l.t. was at 13.90 this has definite hack ks and is the right size  ating the position of the corner: I-13 1" pipe, 4" aluminum cap 6" cedar NW 18.0"
B. Description of corner evidence—11 Set from 8" tam. stub ith definite blaze (No cribe marks visible) for .F. o.b.t stump remains n place for S.W. o.b.t. but limost completely rotted away  C. Description of monument for cell 1" pipe, 4" aluminum of cedar N80°W 20.1' cedar N55°E 18.5' rtly dead	fences south a in line with c roads north an t ay  corner and accessories estern G-11 1" pipe 10" cedar N49 5" cedar N72 corner fence	ied in restoring or re-estatine with I-1 and east and for enterline Tre d west not but mark etc  ablished to perpetuate loce by 41.0' 50 41.0' 50 54.8' post south - 35.5'	Tam 8-S75 W 07 lks. Tam 8-S57 E 18 lks.  blishing corner:  3 Set from blazed tam st S.E. g.l.o. wit. line. e south at 11.77 chs. g.l es say l.t. was at 13.90 this has definite hack ks and is the right size  ating the position of the corner: I-13 1" pipe, 4" aluminum cap 6" cedar NW 18.0' 7" cedar West 25.4'
B. Description of corner evidence—11 Set from 8" tam. stub ith definite blaze (No cribe marks visible) for .F. o.b.t. — stump remains of place for S.W. o.b.t. but how the completely rotted away.  C. Description of monument for call 1" pipe, 4" aluminum call 20.1" call 20.5" call 20.1" call	fences south a in line with c roads north an t ay  corner and accessories est cap G-11 1" pipe 10" cedar N45 5" cedar N72 corner fence	ied in restoring or re-estatine with I-1 ind east and for enterline Tre d west not but mark etc  ablished to perpetuate loce by aluminum cap by 41.0' corrected to be abled to be aluminum cap by 41.0' corrected to be abled to be aluminum cap by 41.0' corrected to be abled to be aluminum cap by 41.0' corrected to be abled to be aluminum cap by 41.0' corrected to be abled to be aluminum cap by 41.0' corrected to	Tam 8-S75 W 07 lks. Tam 8-S57 E 18 lks.  blishing corner:  3 Set from blazed tam st S.E. g.l.o. wit. line. e south at 11.77 chs. g.l es say l.t. was at 13.90 this has definite hack ks and is the right size  ating the position of the corner: I-13 1" pipe, 4" aluminum cap 6" cedar NW 18.0' 7" cedar West 25.4'
B. Description of corner evidence—11 Set from 8" tam. stub ith definite blaze (No cribe marks visible) for .E. o.b.t stump remains n place for S.W. o.b.t. but lmost completely rotted away  C. Description of monument for cell 1" pipe, 4" aluminum of cedar N80°W 20.1' cedar N55°E 18.5' artly dead	fences south a in line with c roads north and t and accessories estern G-11 1" pipe 10" cedar N72 corner fence	ied in restoring or re-estatine with I-1 ind east and for enterline Tre d west not but mark etc  ablished to perpetuate loce by aluminum cap by 41.0' corrected to be abled to be aluminum cap by 41.0' corrected to be abled to be aluminum cap by 41.0' corrected to be abled to be aluminum cap by 41.0' corrected to be abled to be aluminum cap by 41.0' corrected to be abled to be aluminum cap by 41.0' corrected to	Tam 8-S75 W 07 lks.  Tam 8-S57 E 18 lks.  blishing corner:  3 Set from blazed tam st S.E. g.l.o. wit. line. e south at 11.77 chs. g.l es say l.t. was at 13.90 this has definite hack ks and is the right size  ating the position of the corner:  I-13 1" pipe, 4" aluminum cap 6" cedar NW 18.0' 7" cedar West 25.4'
B. Description of corner evidence.  -11 Set from 8" tam. stublish definite blaze (No cribe marks visible) for .F. o.b.t. ~ stump remains no place for S.W. o.b.t. but lmost completely rotted away.  C. Description of monument for class of the state of th	fences south a in line with c roads north an t apy  corner and accessories est cap G-11 1" pipe 10" cedar N72 5" cedar N72 corner fence	ied in restoring or re-esta- ine with I-1 and east and for enterline Tre d west not but mark etc  ablished to perpetuate loce 4" aluminum cap 5W 41.0' 2°E 54.8' post south - 35.5'	Tam 8-S75 W 07 lks. Tam 8-S57 E 18 lks.  blishing corner:  3 Set from blazed tam st S.E. g.l.o. wit. line. e south at 11.77 chs. g.l es say l.t. was at 13.90 this has definite hack ks and is the right size  ating the position of the corner: I-13 1" pipe, 4" aluminum cap 6" cedar NW 18.0' 7" cedar West 25.4'