	LAND CORNER RECO	RDATION CERTIFICA	TE //tc/statis /c
For comers in	Filing Requirement of	FAct 74, Mich. P.A. 197	'
	ited In: Corner Code #	#	3 S S S S S
(Conuty) Focs	ited In: Corner Code 7	*	RECEIVED FOR RECORD TO REC
(County)	•		555 5 E
1. Public Land Survey		B-07_	(元元) (3 円)
	<u> </u>		
	† R		
2. Property Controlling S	_ T_R		3.35 T. & 3
in Section S	<u>TR</u>		dia jum
3. Miscellaneous S			Register of Deeds Stamp & File
Property in Sec. S	_ ''\	<u></u>	Register of Deeds Stamp & File
4. Lot No, Recorded Plant	at	·	ABCDEFGHIJ
5. Private Claims			
			2 6 5 7 4 7 3 7 2
	34. 60 01	7	3
I, William Lenca in a	field survey on May 20, 19 97	do hereby state that under lines 1 and 2 above were in	4 - 7 - 8 - 9 - 10 - 1
requirements of P.A. 74, Michigan P.A. 0	r 1970, the comer points mentioned in prefere as required in the current manua	of survey instructions of the	5
I I I I O I I Described and of the Interior I	tures of Land Management of DV a dec	156 Ol 9 CORLLOI Fast discover	6 19 17 16 15 1
United States Department of the Interior, to that the corner points mentioned in lines: Board of Land Surveyors or by a Decr	3. A and 5 above were in conformance y	AND the tries of the Michigan	7 + 1 - 1 - 1 - 1 - 1
recovered, found as expressed below:	and an an annual an annual animalian and a		8 -19 - 20 - 21 - 22 - 2
NOTE: Not more than 2 comers, all	in the same town and range may be	recorded	9
NOTE: Not more than 2 comers, as on this certificate.	it are same man ena randel mak pe	· · - ***	10 30 29 28 27 2
Off Bits Certification			11
			12 31 32 34 34 3
			13
A. Description of original monumen	t and accessories and/or subseque	ent restoration:	
			marack, 6" - S35°E - 12 lks. Stump
	DICNI - 04500 /	elotor: Ed A" Sa C'edat Pi	ost, broken - point in good condition;
Birch - S60°E - 28.57	am \$35°B - 12L - Fences 5. & '; 10" Cedar - \$12°W - 18.47'; 9"	Cedar - 550°W - 12.70,	4 Count - How W - House
We recovered a 5/8" x 24" Iron	ound and/or method applied in res Rod with RLS cap at an ancient	fence corner - fences run	South and West. We also recovered 120W - 18 47': 9" Cedar - \$500W - 1
We also found the remains of a		establish the corner posit	ion. Since this corner was re-set fro
			THE WE WILL
			witten of the corner
C. Description of monument for co	ner and accessories established to	betbernare locaring rise bo	LENCA LAND
Set 3/4" x 4' long aluminum n	nd/3-1/4" dia. Alum, cap stamped	for corner:	B * STEAMO
12" dia, Tamarack	N24ºE	55,88 iccl Scr. ND	C 7% . TAAL
12" dia. Cedar	S63 ⁰ E	33.19 feet Scr. NB 18.47 feet Scr. NB	A /- ·
10" dia. Cedar (Existing B	T.) \$12 ⁰ W T.) \$50 ⁰ W	18.47 feet Scr. NB 12.70 feet Scr. NB	7 A L G L A L C C C C C C C C C C C C C C C C C
10" dia. Cedar (Existing B	.T.) 250°W 1.North	12.70 feet 501. 14B	
Metal Survey Sign Post	<u>.</u> '		Distance to troop are to unit in side
NOTE: All bearings are magn	netic bearings. All distances are		Distances to trees are to nail in side
. 11001	4		June 06, 1997
Signed by William	26461	Date	
Surveyor's Michigan License No	20101		
ONUMENTATIO		FORM APPROVED BY MICH	IGAN STATE BOARD OF PROFESSIONAL SURVEYOR REVISI
TAN BACKLASSES			RE RE
DMOMETER		110 a	REV

DEC 2 2 1997

COMMISSION

489