	LAND CORN				
	Filing Requir	rement of Act 74, Mich. P.A	. 1970		
corners in				REDEIVED FOR RECORD 15 NOV -8 /M II: (NOE # 23 Y /32 Y /3 ARBARA III: (PRINCE PRINCE) REGISTY / PRINCE PRINC	
MENOMINEE	Located In:	Corner Code =##			
(Courty)				2 8 5	
Public Land Survey	T35N _R 27V	V I-3			
	T R			38.75. 38.75. 38.75. 31.11. 31.11.	
	T R				
	T R			$\frac{1}{2}$	
Property Controlling	S T R				
in Section	S T R				
Miscellaneous	S R		Register of D	eeds Stamp & File Num	ber
Property in Sec.	S T R				
ol No.	Recorded Plat		,		
Private Claims	100010001100			CDEFGHIJ	KLM
			2 6	5 4 4 3 2	
	•		3	 	++
William I amon		July 18 95	4	-	12
William Lenca	. in a field survey on		-: 5	 	
reby certify that under red	quirements of P.A. 74, Michigan P.A. a conformance with regulations an	of 1970, the corner points mention of tules therefore as required in t	ed 6 18	17 161514	— ¦э—
es i and 2 above were in nt manual of survey instri	uctions of the United States Depar	tment of the Interior, Bureau of La	nd 7		
gement or by a decree of	a Court of Law and/or that the corne	er points mentioned in lines 3, 4 an	d5 8 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	20 21 22 23	24
e were in conformance wi	th the rules of the Michigan Board or re-established, monumented, re-r	of Land Surveyors or by a Decree of monumented recovered found	as 9	 	+
ssed below:	о-соваризнов, топошениев, теч		10 -30	29 28 27 26	
	orners, all in the same town a	nd range, may be recorded	11		
on this certificate.		• • •	1231	32 33 34 34 35	36
			13		
escription of original	monument and accessories and	d/or subsequent restoration:			
1848: Original Surv	ey by James H. Mullett - B.T.'s	- Hemlock 10" - N260F- 20 II	cs: Cedar 14" - S	450W - 31 lks All orig	inal
			, Count, 14 - D	115 17 - 51 mg. 1m 016	INICA
evidence for t	DIS COPPET HAS DECH DESITAVED DI	v county road improvements			
evidence for t	nis corner has been destroyed by	y county road improvements.			
•	•		dicates in the lege	and that a 1/2" diameter	ron
1979: Certified Surv	vey No. 170 recorded by George	B. Wilson, RLS No. 17607, in			
1979: Certified Surv	•	B. Wilson, RLS No. 17607, in			
1979: Certified Surpin was set.	vey No. 170 recorded by George	B. Wilson, RLS No. 17607, in			
1979: Certified Surpin was set.	vey No. 170 recorded by George	B. Wilson, RLS No. 17607, in			
1979: Certified Surr pin was set. A South.	vey No. 170 recorded by George A bearing and distance of N01 ⁰ 2	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown	a between this com		
1979: Certified Surr pin was set. A South.	vey No. 170 recorded by George	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown	a between this com		
1979: Certified Sumpin was set. A South. Description of corner e	vey No. 170 recorded by George A bearing and distance of N01 ⁰ 2 vidence found and/or method a	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown	n between this con	ner and the 1/4 corner to	the
1979: Certified Surpin was set. A South. Description of corner e	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method a of Section 3, T35N-R27W, we	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown applied in restoring or reestab recovered a 1/2" diameter iron	n between this con lishing corner: pin in the centerli	ner and the 1/4 corner to	the
1979: Certified Surpin was set. A South. Description of corner e In a April 1995 survey West and South, and in	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we a line with an old fence running	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown applied in restoring or reestab recovered a 1/2" diameter iron north. We found that the distance of the control of the distance of the control of the distance of	the between this consistency that is the centerly in the centerly ince between this	ner and the 1/4 corner to the of county roads East corner and the 1/4 corner	the
1979: Certified Surpin was set. A South. Description of corner e In a April 1995 survey West and South, and in the south measured 26	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we in line with an old fence running 89.22 feet, which matches close	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown applied in restoring or reestab recovered a 1/2" diameter iron north. We found that the distably with Wilson's distance of 26	tishing corner: pin in the centerlines between this 89.28 feet as recor	ner and the 1/4 corner to ine of county roads East corner and the 1/4 corner ded in Certified Survey	the
1979: Certified Survey pin was set. A South. Description of corner e In a April 1995 survey West and South, and in the south measured 26 170. This corner posi	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we a line with an old fence running	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown applied in restoring or reestab recovered a 1/2" diameter iron north. We found that the distably with Wilson's distance of 26	tishing corner: pin in the centerlines between this 89.28 feet as recor	ner and the 1/4 corner to ine of county roads East corner and the 1/4 corner ded in Certified Survey	the
1979: Certified Surpin was set. A South. Description of corner et In a April 1995 survey West and South, and in the south measured 26 170. This corner positions in the south measured 26 170.	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we in line with an old fence running 89.22 feet, which matches close tion has been used consistently in	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown applied in restoring or reestab recovered a 1/2" diameter iron north. We found that the distably with Wilson's distance of 26	tishing corner: pin in the centerlines between this 89.28 feet as recor	ner and the 1/4 corner to ine of county roads East corner and the 1/4 corner ded in Certified Survey	the
1979: Certified Surpin was set. A South. Description of corner et In a April 1995 survey West and South, and in the south measured 26 170. This corner positions in the south measured 26 170.	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we in line with an old fence running 89.22 feet, which matches close tion has been used consistently in	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown applied in restoring or reestab recovered a 1/2" diameter iron north. We found that the distably with Wilson's distance of 26	tishing corner: pin in the centerlines between this 89.28 feet as recor	ner and the 1/4 corner to ine of county roads East corner and the 1/4 corner ded in Certified Survey	the
1979: Certified Survey pin was set. A South. Description of corner e In a April 1995 survey West and South, and in the south measured 26 170. This corner posi	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we in line with an old fence running 89.22 feet, which matches close tion has been used consistently in	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown applied in restoring or reestab recovered a 1/2" diameter iron north. We found that the distably with Wilson's distance of 26	tishing corner: pin in the centerlines between this 89.28 feet as recor	ner and the 1/4 corner to ine of county roads East corner and the 1/4 corner ded in Certified Survey	the
1979: Certified Surpin was set. A South. Description of corner et In a April 1995 survey West and South, and in the south measured 26 170. This corner positions in the south measured 26 170.	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we in line with an old fence running 89.22 feet, which matches close tion has been used consistently in	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown applied in restoring or reestab recovered a 1/2" diameter iron north. We found that the distably with Wilson's distance of 26	tishing corner: pin in the centerlines between this 89.28 feet as recor	ine of county roads East corner and the 1/4 corner and the 1/4 corner and the 1/4 corner and the best available	r to
1979: Certified Surpin was set. A South. Description of corner et In a April 1995 survey West and South, and in the south measured 26 170. This corner positions in the south measured 26 170.	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we in line with an old fence running 89.22 feet, which matches close tion has been used consistently in	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown applied in restoring or reestab recovered a 1/2" diameter iron north. We found that the distably with Wilson's distance of 26	tishing corner: pin in the centerlines between this 89.28 feet as recor	ine of county roads East corner and the 1/4 corner and the 1/4 corner and the 1/4 corner and the best available control of the best available with the best available	the to No.
1979: Certified Surpin was set. A South. escription of corner e In a April 1995 survey West and South, and in the south measured 26 170. This corner posi	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we in line with an old fence running 89.22 feet, which matches close tion has been used consistently in	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown applied in restoring or reestab recovered a 1/2" diameter iron north. We found that the distably with Wilson's distance of 26	tishing corner: pin in the centerlines between this 89.28 feet as recor	ine of county roads East corner and the 1/4 corner ded in Certified Survey ed as the best available WILLIAM LENCE AND LENCE A	the arto No.
1979: Certified Surpin was set. A South. escription of corner e In a April 1995 survey West and South, and in the south measured 26 170. This corner posi	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we in line with an old fence running 89.22 feet, which matches close tion has been used consistently in	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown applied in restoring or reestab recovered a 1/2" diameter iron north. We found that the distably with Wilson's distance of 26	tishing corner: pin in the centerlines between this 89.28 feet as recor	ine of county roads East corner and the 1/4 corner and the 1/4 corner and the 1/4 corner and the best available conditions as the best available with the best available length.	the arto No.
1979: Certified Surpin was set. A South. rescription of corner e In a April 1995 survey West and South, and in the south measured 26 170. This corner position	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we in line with an old fence running 89.22 feet, which matches close tion has been used consistently in	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown epplied in restoring or reestab recovered a 1/2" diameter iron north. We found that the distriby with Wilson's distance of 26 for several years by local survey	the between this condition in the centerliance between this \$9.28 feet as recorders, and is accept	ine of county roads East corner and the 1/4 corner and the 1/4 corner and the 1/4 corner and the 1/4 corner and the best available with the best available Language.	the arto No.
1979: Certified Survey pin was set. A South. escription of corner e In a April 1995 survey West and South, and in the south measured 26 170. This corner position of the position excited and the position of monume.	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we in line with an old fence running 89.22 feet, which matches close tion has been used consistently in of the original corner.	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown expelled in restoring or reestable recovered a 1/2" diameter irong north. We found that the distably with Wilson's distance of 26 for several years by local survey the second secon	the between this condition in the centerliance between this \$9.28 feet as recorders, and is accept	ine of county roads East corner and the 1/4 corner and the 1/4 corner and the 1/4 corner and the 1/4 corner and the best available with the best available Language.	the arto No.
1979: Certified Survey pin was set. A South. The scription of corner eterm and South, and in the south measured 26 170. This corner position of the position excited and south and in the south measured 26 170. This corner position of the position excited and south and in the south measured 26 170. This corner position of the position excited and south an	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we a line with an old fence running 89.22 feet, which matches close tion has been used consistently in of the original corner.	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown expelled in restoring or reestable recovered a 1/2" diameter irong north. We found that the distably with Wilson's distance of 26 for several years by local survey the second secon	the between this condition in the centerliance between this \$9.28 feet as recorders, and is accept	ine of county roads East corner and the 1/4 corner and the 1/4 corner and the 1/4 corner and the 1/4 corner and the best available with the best available Language.	the arto No.
1979: Certified Surpin was set. A South. Description of corner et In a April 1995 survey West and South, and in the south measured 26 170. This corner position of the position exception of monume.	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we in line with an old fence running 89.22 feet, which matches close tion has been used consistently in of the original corner.	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown expelled in restoring or reestable recovered a 1/2" diameter iron morth. We found that the distable with Wilson's distance of 26 for several years by local survey the sestablished to perpetuate located for corner location;	the between this condition in the centerliance between this \$9.28 feet as recorders, and is accept	ine of county roads East corner and the 1/4 corner and the 1/4 corner and the 1/4 corner and the 1/4 corner and the best available with the best available Language.	the arto No.
1979: Certified Surpin was set. A South. escription of corner e In a April 1995 survey West and South, and in the south measured 26 170. This corner position of the position excidence of the position escription of monume Set 2" dia. Aluminum	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we in line with an old fence running 89.22 feet, which matches close tion has been used consistently in of the original corner.	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown expelled in restoring or reestable recovered a 1/2" diameter irong north. We found that the distably with Wilson's distance of 26 for several years by local survey the second secon	ting the position of	ine of county roads East corner and the 1/4 corner and the 1/4 corner and the 1/4 corner and the best available of the best available with the best available to be the best available the best available to be the best available the best available to be th	the arto No.
1979: Certified Surpin was set. A South. escription of corner e In a April 1995 survey West and South, and in the south measured 26 170. This corner posicevidence of the position escription of monume Set 2" dia. Aluminum 6" dia. Balsam 9" dia. Cedar 6" dia. Cedar	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we a line with an old fence running 89.22 feet, which matches close tion has been used consistently in of the original corner.	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown applied in restoring or reestab recovered a 1/2" diameter iron north. We found that the distably with Wilson's distance of 26 for several years by local survey the sestablished to perpetuate local ped for corner location: N48°E S50°W N48°W	ting the position of 42.13 feet	ine of county roads East corner and the 1/4 corner and the 1/4 corner and the 1/4 corner and the best available of the best available. Scr NBT	the arto No.
1979: Certified Surpin was set. A South. rescription of corner e In a April 1995 survey West and South, and in the south measured 26 170. This corner posicevidence of the position escription of monume Set 2" dia. Aluminum 6" dia. Balsam 9" dia. Cedar 6" dia. Cedar	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we in line with an old fence running 89.22 feet, which matches close tion has been used consistently in of the original corner.	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown applied in restoring or reestab recovered a 1/2" diameter iron north. We found that the distably with Wilson's distance of 26 for several years by local survey the sestablished to perpetuate local ped for corner location: N48°E S50°W N48°W	lishing corner: pin in the centerlines between this 89.28 feet as recorders, and is accept thing the position 42.13 feet 39.48 feet	ine of county roads East corner and the 1/4 corner and the 1/4 corner and the 1/4 corner and the 1/4 corner and the best available of the best available. Ser NBT Ser NBT	the arto No.
1979: Certified Surpin was set. A South. Description of corner e In a April 1995 survey West and South, and in the south measured 26 170. This corner position of the positi	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we a line with an old fence running 89.22 feet, which matches close tion has been used consistently in of the original corner.	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown applied in restoring or reestab recovered a 1/2" diameter iron north. We found that the distably with Wilson's distance of 26 for several years by local survey the sestablished to perpetuate local ped for corner location: N48°E S50°W N48°W	lishing corner: pin in the centerlines between this 89.28 feet as recorders, and is accept thing the position of 42.13 feet 39.48 feet 38.21 feet	ine of county roads East corner and the 1/4 corner and the 1/4 corner and the 1/4 corner and the 1/4 corner and the best available of the best available. Ser NBT Ser NBT	the arto No.
1979: Certified Surpin was set. A South. Description of corner e In a April 1995 survey West and South, and in the south measured 26 170. This corner position of the position of dia. Aluminum 16" dia. Balsam 9" dia. Cedar 6" dia. Cedar 5/8" x 24" Iron Roc MARKER"	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we aline with an old fence running 89.22 feet, which matches close tion has been used consistently in of the original corner. In the corner and accessories of Pipe/3-1/4" dia. Alum cap stamp	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown applied in restoring or reestable recovered a 1/2" diameter iron north. We found that the distribution with Wilson's distance of 26 for several years by local survey a stablished to perpetuate local ped for corner location: N48°E S50°W N48°W TNESS S41°E	lishing corner: pin in the centerliance between this 89.28 feet as recorvers, and is accept thing the position of 42.13 feet 39.48 feet 38.21 feet 46.03 feet	ine of county roads East corner and the 1/4 corner to t	the of to No.
1979: Certified Survey pin was set. A South. Description of corner et In a April 1995 survey West and South, and in the south measured 26 170. This corner position of the position exidence of the position	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we a line with an old fence running 89.22 feet, which matches close tion has been used consistently in of the original corner.	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown applied in restoring or reestable recovered a 1/2" diameter iron north. We found that the distribution with Wilson's distance of 26 for several years by local survey a stablished to perpetuate local ped for corner location: N48°E S50°W N48°W TNESS S41°E	lishing corner: pin in the centerliance between this 89.28 feet as recorvers, and is accept thing the position of 42.13 feet 39.48 feet 38.21 feet 46.03 feet	ine of county roads East corner and the 1/4 corner to t	the the rate of th
1979: Certified Survey pin was set. A South. Description of corner et and April 1995 survey West and South, and in the south measured 26 170. This corner position of the pos	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we aline with an old fence running 89.22 feet, which matches close tion has been used consistently in of the original corner. In the corner and accessories of Pipe/3-1/4" dia. Alum cap stamp	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown applied in restoring or reestable recovered a 1/2" diameter iron north. We found that the distribution with Wilson's distance of 26 for several years by local survey a stablished to perpetuate local ped for corner location: N48°E S50°W N48°W TNESS S41°E	lishing corner: pin in the centerliance between this 89.28 feet as recorvers, and is accept thing the position of 42.13 feet 39.48 feet 38.21 feet 46.03 feet	ine of county roads East corner and the 1/4 corner to t	the of to No.
escription of corner e In a April 1995 survey West and South, and in the south measured 26 170. This corner posic evidence of the position escription of monume Set 2" dia. Aluminum 6" dia. Balsam 9" dia. Cedar 6" dia. Cedar 5/8" x 24" Iron Roo MARKER" NOTE: All bearings a	vidence found and/or method a of Section 3, T35N-R27W, we in line with an old fence running 89.22 feet, which matches close tion has been used consistently in of the original corner. In for corner and accessories of Pipe/3-1/4" dia. Alum cap stamp	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown applied in restoring or reestab recovered a 1/2" diameter iron morth. We found that the distably with Wilson's distance of 26 for several years by local survey a stablished to perpetuate local ped for corner location: N48°E S50°W N48°W TINESS S41°E	lishing corner: pin in the centerliance between this 89.28 feet as recorvers, and is accept thing the position of 42.13 feet 39.48 feet 38.21 feet 46.03 feet the details and the details and the details and the details are the details and the details are the details and the details are	ine of county roads East corner and the 1/4 corner to t	the of to No.
1979: Certified Survey pin was set. A South. Description of corner et In a April 1995 survey West and South, and in the south measured 26 170. This corner posicion of the position of dia. Balsam 9" dia. Cedar 6" dia. Cedar 6" dia. Cedar 5/8" x 24" Iron Room MARKER" NOTE: All bearings a tree.	vey No. 170 recorded by George A bearing and distance of No102 vidence found and/or method at of Section 3, T35N-R27W, we aline with an old fence running 89.22 feet, which matches close tion has been used consistently in of the original corner. In the corner and accessories of Pipe/3-1/4" dia. Alum cap stamp	B. Wilson, RLS No. 17607, in 21'33"W, 2689.28 feet is shown applied in restoring or reestab recovered a 1/2" diameter iron morth. We found that the distably with Wilson's distance of 26 for several years by local survey a stablished to perpetuate local ped for corner location: N48°E S50°W N48°W TINESS S41°E	lishing corner: pin in the centerliance between this 89.28 feet as recorvers, and is accept thing the position of 42.13 feet 39.48 feet 38.21 feet 46.03 feet the details and the details and the details and the details are the details and the details are the details and the details are	ine of county roads East corner and the 1/4 corner to t	the of to No.