a DD	a	R	1000

Surveyor's Michigan License No._

Approved Land Survey Peer Group	Remonun		<u> </u>
PA 01-1990 On 13		199	8
Serve of	nairman	inic	<u>85</u> ,

APR 0 6 1999		Chairman					
inglija 1		NER RECORDATION O	ERTIFICATE		Vuanman		
SECTIC	Filing Requ	irement of Act 74, Mic			ದಾ .೧		
For corners in			1	至	34 34 35 36 36 36 36 36 36 36 36 36 36 36 36 36	200	
MENOMINEE	Located in: Co	orner Code #		50		¥.	**
(County)				A.	RAC -	03	; - e
1. Public Land Survey	75N R 27W	J-11			~ ≨8	RECUIVED FOR RECORD	
1. Fublic Land Odivey	TR			#2F	三の写	<u> </u>	•
	<u>TR</u>			က်လ ၁ထ	£86 € €	28	
2. Property Controlling	IK			8,0	20 20 20 20 20 20 20 20 20 20 20 20 20 2	=	
in Section	\$ T R				-		
3. Miscellaneous	s TR						
Property in Sec.	S TR			Register of	Deeds Stam	& File N	lumber
			•		1		
4. Lot No, Recor	ded Plat		,	A B C D	E F G	ніЈ	K L
5. Private Claims			· 1				
•	•		3	8 5 -		<u> </u>	
William Lenca	- Sald superson Mar.	26 10 98 de harabu atatr					12
requirements of P.A. 74. Michiga	in P.A. of 1970, the comer points	menuoned in lines ≀ and ∠ ab	Ove wetern -				
conformance with regulations and United States Department of the I	rules therefore as required in the o	urrent manual of survey instruc	ctions of the	1917_	16		1.3
that the corner points mentioned	in lines 3, 4 and 5 above were in c	onformance with the rules of th	ne Michigan 💹 📗				
Board of Land Surveyors or by recovered, found as expressed be	a Decree of a Court of Ław; e	stablished, re-established, me	onumentea, 8		21	2223	24
			9			<u> </u>	
NOTE: Not more than 2 com on this certificate.	ners, all in the same town and ra	nge, may be recorded	10				 25
Off this Certificate.	. ,		11			 	11
			12	3132-	33	 3435-	36
			13 ¹			<u> </u>	
A. Description of original mo	nument and accessories and/	or subsequent restoration:					
	t . Y II Mullett _ R T 's	: - Beech, 4" - N71 ⁰ W - 2	3 lks.; Beech, 4	" - S71 ⁰ E -	32 lks. All	original	
1848: Original Survey	s corner has been destroyed l	by county road improvem	ents.	in '	Section 35	r35N-R2	7W.
1989: Certified Survey	s corner has been destroyed I y Number 669 by William Le	enca shows this corner in	relation to othe	COINCIS III	20000H 22,	13511 1	
	*						
•							
,							
B. Description of corner evid	dence found and/or method a	oplied in restoring or reesta	blishing corner:				
•			in the center	line of an Ea	ist - West C	ounty 10a - 77 75'	a ana
My Field Notes from a s	1988 Survey show that we for ning North. We took the following	owing ties: Cedar, 8" - N	155°W - 58.23';	w. Birch, i	accented the	location	of the
In our 1998 remonumer	ning North. We took the folloation survey, we recovered	the 1" diameter from pape	and 2 D. I. s III.	piaco. Tros	الكامر	CONTRACTOR (CO	>
existing corner monume	ntation survey, we recovered ent as the best available evid	ence of the position of the	, 001g		TITLE OF E	OF BICE	Carles.
					\$ 5. V	MLLIAM	* #
					# :	LENCA	*
	·	·			*	CHALL ROYEVEUS	*
						Мо. <u>244</u> 61	. S
O Description of manufactor	for corner and accessories es	tablished to perpetuate loc	ating the position	of the corne		•••••	W. Cold
					COLUMN TO THE PARTY OF THE PART	EB LAND	A CERTIFICATION OF THE PERSON
Set 5/8" x 24" Iron Roo	d/3-1/4" dia. Alum. cap stam	ped for conten location in				G- do-	
E/OH w 2AH Iron Doc	1/2" dia. Alum. cap marked '	WITNESS MARKER"		7.09 feet	1' S. of 5"	COUNT	
5/8" x 24" Iron Roc	1/2" dia. Alum. cap marked '	'WITNESS MARKER"		4.43 feet 8.23 feet	Ex. B.T.		
10 ⁿ dia. Cedar				6.12 feet	Scr. NBT		
10" dia. Tamarack				4.5 feet			
Metal Survey Sign	rust		an markamin 🏲	ietamone to t	rees are to n	ail in side	of tree
NOTE: All bearings	are magnetic bearings. All d	istances are measured wi	in steel tape. D	PINITES IO U	WO SIV WIL		
			Ox	L 13, 1998			
Signed by <u>(1) (Man</u>	1 BUCB		Date				

26461